





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/12/2020

User ID : CatherineLee

Section A - Accident Details			
Registration Number	SMB1411B		
Case Reference Number	BUS/11/20/7025		
Registration Date	6/1/2014		
Company Type	SMRT Buses Ltd		
Make	MAN		
Model	A22		
Name of Driver	Zhao Yingshan		
Type of Accident	Head to Rear		
Accident Date and Time	23/11/2020 3:05 PM		
Accident Reported Date and Time	23/11/2020 4:15 PM		
Is Surveyor Required?	Yes		
Survey by			
Vehicle is Towed Back?	No		
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number	24108999		
Special Instruction to ARC,if any	right rear portion		
Prepared Date and Time	29/11/2020 11:22 AM		
Chassis Number	WMAA22ZZ1D7001993		
Mileage			
Work Shop			
Repair Completion Date and Time			

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$1,590.00
Total Spray Cost	\$1,048.00	\$878.00
Total Spare Part Cost	\$5,095.22	\$701.78
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$8,263.22	\$3,169.78
Lump Sum Total	\$8,250.00	\$3,150.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	29/11/2020 11:32 AM	01/12/2020 5:18 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/12/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$2,120.00				\$1,590.00			
Total Labour		\$2,120.00				\$1,590.00			
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$1,048.00				\$878.00			
Total Spray Painting & Panel Beating		\$1,048.00				\$878.00			
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010062	Body	F01001-CW273	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace /CRV
6010464	VM	S01001-CW002	BRACKET,ATTACHMEN T:FOR MAN A22 BUS	1.00	\$569.30	100.00	\$0.00	Replace	Repair X R
6009991	BODY RH	4000F06-ACCE4526	PANEL,SIDE:R10,FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Replace	Repair X R
6009992	BODY RH	A01001-CW564	PANEL,SIDE:R11,FOR MAN A22 BUS	1.00	\$1,782.50	100.00	\$0.00	Replace	Repair X R
6010299	VE	88-25320-6008	LAMP,INDICATOR:LED (MAN BUS)	0.00	\$1,274.10	0.00	\$0.00	Replace	Check XSVC
6010298	VE	88-25225-6039	LAMP,STOP:LED (MAN BUS)	0.00	\$1,141.70	0.00	\$0.00	Replace	Check XSVC
Total					\$5,935.00		\$877.23		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

877.23
-20%
701.78
2,468
3,169.78
4/5
\$3,150
4 days