



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 07/12/20
LKK - STEVE

VEHICLE NO : SBB3716P

MODEL : MIT/ECLIPSE CROSS 1.5 T/C

WIP : 60386

Material	:	\$	<u>2,842.84</u>
Labour	:	\$	<u>2,550.00</u>
Sub-Total	:	\$	<u>5,392.84</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>400.00</u>
Total	:	\$	<u>4,992.84</u>
GST 7%	:	\$	<u>349.50</u>
Grand Total	:	\$	<u>5,342.34</u>
Finalise By/Date : <u>Larry on 28/12/20</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 06 WORKING DAYS + 2 days (wk. end)

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 14/12/2020	Cust No/Name /NG KAI KHUAY Reg No/Reg Date SBB3716P / 13/09/2018 Date In/Mileage 21/12/2020/ 30054 Chassis/Package JMAXTGK1WJZ002613 /CS3P Engine No 4B40DN9040 Make/Model MIT/ECLIPSE CROSS 1.5 T/C 2WD ELEGANCE (Colour/Trim C02 BRONZE METALLIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/12/2020/ 16:01	BLE	884 / Lauro Songcuan	60386

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW LH FRONT DOOR & LH REAR DOOR, REPAIR LH FRONT FENDER				900.00 ✓
E PNT98000 SPRAY PAINT LH FRONT FENDER, LH FRONT DOOR & LH REAR DOOR				1050.00 ✓
E PNT88000 REMOVE & REFIT LH FRONT DOOR COMPONENTS				120.00 ✓
E PNT88000 REMOVE & REFIT LH REAR DOOR COMPONENTS				120.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY APPLY ANTI CORROSION ON AFFECTED PORTIONS				40.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment → <i>Supp</i>				120.00 X
SPECIALISTJOB LABOUR TO TRANSFER LH REAR RIM FROM TYRE				30.00 ✓
X EXC EXCESS				-400.00
X MOULDING,FR WHEEL ARCH,LH	1.00	151.00	23.00	116.27 ✓
X PANEL ASSY,FR DOOR,LH	1.00	949.00	23.00	730.73 ✓
X MOULDING,F/DR SASH,UPR LH	1.00	119.00	23.00	91.63 ?
X GARNISH,FR DOOR,LH	1.00	174.00	23.00	133.98 ✓
X GARNISH,FR DOOR SASH,LH	1.00	66.00	23.00	50.82 ✓
X PANEL ASSY,RR DOOR,LH	1.00	937.00	23.00	721.49 ✓
X MOULDING,R/DR SASH,UPR LH	1.00	114.00	23.00	87.78 ✓
X GARNISH,RR DOOR,LH	1.00	102.00	23.00	78.54 ✓
X MOULDING,R/DOOR PROTECT,LH	1.00	105.00	23.00	80.85 ✓
X MOULDING,RR WHEEL ARCH,LH	1.00	153.00	23.00	117.81 ✓

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 14/12/2020	<table> <tr> <td>Cust No/Name</td><td>/NG KAI KHUAY</td></tr> <tr> <td>Reg No/Reg Date</td><td>SBB3716P / 13/09/2018</td></tr> <tr> <td>Date In/Mileage</td><td>21/12/2020/ 30054</td></tr> <tr> <td>Chassis/Package</td><td>JMAXTGK1WJZ002613 /CS3P</td></tr> <tr> <td>Engine No</td><td>4B40DN9040</td></tr> <tr> <td>Make/Model</td><td>MIT/ECLIPSE CROSS 1.5 T/C 2WD ELEGANCE (</td></tr> <tr> <td>Colour/Trim</td><td>CO2 BRONZE METALLIC/ BK BLACK</td></tr> </table>	Cust No/Name	/NG KAI KHUAY	Reg No/Reg Date	SBB3716P / 13/09/2018	Date In/Mileage	21/12/2020/ 30054	Chassis/Package	JMAXTGK1WJZ002613 /CS3P	Engine No	4B40DN9040	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C 2WD ELEGANCE (	Colour/Trim	CO2 BRONZE METALLIC/ BK BLACK
Cust No/Name	/NG KAI KHUAY														
Reg No/Reg Date	SBB3716P / 13/09/2018														
Date In/Mileage	21/12/2020/ 30054														
Chassis/Package	JMAXTGK1WJZ002613 /CS3P														
Engine No	4B40DN9040														
Make/Model	MIT/ECLIPSE CROSS 1.5 T/C 2WD ELEGANCE (														
Colour/Trim	CO2 BRONZE METALLIC/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/12/2020/ 16:01	BLE	884 / Lauro Songcuan	60386

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X WHEEL,DISC → quoted as labour	1.00	783.00	23.00	602.91
X VALVE,TIRE → supp	1.00	39.00	23.00	30.03

Z TEXT

OD CLAIM - AIG
 SURVEY: STEVE (LKK) 07.12.2020
 DOA: 01.12.2020
 06 DAYS

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	2,842.84		Nett	4,992.84
Labour	2,460.00	7% GST on	4992.84	349.50
Standard Menu	0.00			
Specialist Job	30.00			
Diagnostics Job	0.00		Total Payable	5,342.34
Sundry/Others	-340.00			
Total(w/o GST)	4,992.84			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SBB 3716 P

<u>Materials</u>		Cost \$
1	Valve, Tire	39.00
	23% Discount	8.97
		<u>30.03</u>
<u>Labour</u>		
1	To Conduct Computerize Full Wheel Alignment	120.00
		<u>150.03</u>
	7% GST	10.50
	Total	<u>160.53</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SBB3716PWIP: 60386

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	WAF CHROME MOUNT	? / SUPP	<i>for</i>	<i>see 24/12</i>	
2		? / SUPP		<i>13/12/20</i>	
3	Sport Rim - WAF	? / SUPP	<i>for</i>		4005 D 787.
4	WHEEL ALIGNMENT \$ 120	? / SUPP	<i>for</i>	<i>Steve 21/12/20</i>	
5	Valve Tire	? / SUPP			4050 C 386.
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	<i>12/12</i>	<i>Tougher</i>
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: ECLIPSESURVEYOR: STEVE

Work Order: R001280
 License: SBB3716P
 Technician: ALVIN (108)
 Mileage: 30054
 Date: 21.12.20 13:42

MITSUBISHI ECLIPSE CROSS 16" & 18" 2018-

Front : Left

Actual	Before	Specified Range
0°11'	0°10'	0°00' 0°30'
2°03'	2°03'	2°00' 3°00'
0°04'	0°00'	0°00' 0°06'
12°51'	12°52'	11°30' 14°30'
13°02'	13°02'	11°30' 15°00'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°05'	0°10'	0°00' 0°30'
2°44'	2°44'	2°00' 3°00'
0°04'	0°03'	0°00' 0°06'
15°02'	14°56'	11°30' 14°30'
15°07'	15°07'	11°30' 15°00'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°06'	0°00'	-0°45' 0°45'
-0°40'	-0°40'	-0°45' 0°45'
-2°11'	-2°05'	-0°45' 0°45'
0°08'	0°04'	0°01' 0°11'

Rear : Left

Actual	Before	Specified Range
-0°26'	-0°26'	-0°55' -0°25'
0°09'	0°09'	0°06' 0°11'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°34'	-0°30'	-0°55' -0°25'
0°07'	0°07'	0°06' 0°11'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°08'	0°05'	-0°45' 0°45'
0°16'	0°16'	0°11' 0°21'
0°01'	0°01'	

Work Order: R001280
 License: SBB3716P
 Technician: ALVIN (108)
 Mileage: 30054
 Date: 21.12.20 13:42

MITSUBISH ECLIPSE CROSS 16" & 18" 2018-

Front : Left

Actual	Before	Specified Range
0°11'	0°10'	0°00' 0°30'
2°03'	2°03'	2°00' 3°00'
0°04'	0°00'*	0°00' 0°06'
12°51'	12°52'	11°30' 14°30'
13°02'	13°02'	11°30' 15°00'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°05'	0°10'	0°00' 0°30'
2°44'	2°44'	2°00' 3°00'
0°04'	0°03'	0°00' 0°06'
15°02'*	14°56'*	11°30' 14°30'
15°07'*	15°07'*	11°30' 15°00'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°06'	0°00'	-0°45' 0°45'
-0°40'	-0°40'	-0°45' 0°45'
-2°11'*	-2°05'*	-0°45' 0°45'
0°08'	0°04'	0°01' 0°11'

Rear : Left

Actual	Before	Specified Range
-0°26'	-0°26'	-0°55' -0°25'
0°09'	0°09'	0°06' 0°11'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°34'	-0°30'	-0°55' -0°25'
0°07'	0°07'	0°06' 0°11'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°08'	0°05'	-0°45' 0°45'
0°16'	0°16'	0°11' 0°21'
0°01'	0°01'	

SRB3716P

All DTCS

Diagnostic Check all DTCS

2020.12.21

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	GK1W 2018MY

All DTCS

2020.12.21

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MP/IGDI/DIESEL	GAS_0C640000		No DTCS	
AT/CVT/A-MT/TTC-SST	CVT_14080300		No DTCS	
4WS/Electric Power Steering	EPS_45840000		No DTCS	
ABS/ASC/ASTC/WSS	ASC_42080014		No DTCS	
SRS-AIR BAG	SRS_81047305		No DTCS	
Air Conditioner	AC_80080017		No DTCS	
ETACS	ETACS_83040800		No DTCS	
TPMS (with KOS)	ETACS_83040800		No DTCS	
Meter	METER_84088001	U0184	AUDIO CAN timeout	Active
Steering Angle Sensor	GS_SAS_47000100_Fo rMUT3		No DTCS	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040800		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	ETACS_83040800		No DTCS	
FCM/LDW/AHB	ADAS_4B080003		No DTCS	

All DTCs

2020.12.21

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	