

ASS. REC. BY:

REF: CS/AGI20013495/Bvf3

Special Instruction:

Surveyor: LIM

ASSIGNMENT (Office)

From (Person): Ivy Ratilla of AGI Date/Time: 8/12/2020 9:19 AM

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GX 6479D Insured: SMH 5897A

at Workshop m/s Team Auto Pro Pte Ltd Tel: 62581955

of 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

Policy No: Claim No: C10008254/JM

Sum Insured: Excess:

Make of Veh: D.O.A. 07-12-20
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 08-12-2010.29A.M Person Contacted: PEACH Vehicle ☒ IN OUT

Date/Time	Action/Instruction (☒) Estimate
	GX 6479D- ☒
	SMH 5897A- ☒
13/1/21	LS \$5000 confirmed by email (Red 9893.28,66%)