



Email : darren@completevms.com.sg ( )  
 lily@completevms.com.sg ( )  
 lihui@completevms.com.sg ( )

RASHSEYD BIN MOHAMAD  
 BLK 216B COMPASSVALE DRIVE #06-546  
 SINGAPORE 542216

Attention : THE OWNER  
 Contact : 84183987

Estimate : ES007103

Date : 07/12/2020  
 Vehicle Num. : SLA6407Z  
 Make/Model : NISSAN X-TRAIL 2.0-2016  
 Chassis/Eng# : JN1JANT3Z0001532/MR20825168B  
 Accident Date : 06/12/2020  
 Claim No. :  
 Reference :  
 Policy No. :

*Not Authorized  
 1/1 Pay @  
 Resurvey After Painting  
 5-6 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	TAIL GATE <i>CM ✓</i>		
2.	1	TAIL GATE W/SCREEN MOULDING TOP <i>na ✓</i>		
3.	1	TAIL GATE W/SCREEN MOULDING BOTTOM <i>na ✓</i>		
4.	2	TAIL GATE W/SCREEN MOULDING SIDE <i>na ✓</i>		
5.	1	REAR BUMPER <i>Build not ad ✓</i>		
6.	1	REAR BUMPER TOP CHROME		
7.	2	REAR BUMPER SIDE RETAINER <i>su x</i>		
8.	2	REAR BUMPER BRACKET <i>na ✓</i>		
9.	8	REAR BUMPER CLIP <i>na ✓</i>		
10.	1	REAR BUMPER BEAM <i>na ✓</i>		
11.	1	REAR BUMPER SPONGE <i>na ✓</i>		
12.	1	REAR END PANEL		
13.	1	REAR END PANEL TOP GARNISH <i>x su</i>		
14.	1	REAR FENDER GARNISH R/H <i>su x</i>		
15.	1	REAR FENDER GARNISH L/H <i>su x</i>		

List Total S\$ :

~~25.00~~ % Discount S\$ :

SPECIAL NETT ITEMS :				
1.	1	TAIL GATE W/SCREEN SEALANT <i>na ✓</i>		
2.	4	REVERSE SENSOR <i>na ✓</i>	280.00	1,120.00 <i>250.00</i>

Special Nett Total S\$ :

LABOUR :  
 SPRAY PAINT DAMAGED AREA AFFECTED *7500*

1,600.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



Email : darren@completevms.com.sg ( )  
 lily@completevms.com.sg ( )  
 lihui@completevms.com.sg ( )

RASHSEYD BIN MOHAMAD  
 BLK 216B COMPASSVALE DRIVE #06-546  
 SINGAPORE 542216

Estimate : ES007103

Attention : THE OWNER  
 Contact : 84183987

Date : 07/12/2020  
 Vehicle Num. : SLA6407Z  
 Make/Model : NISSAN X-TRAIL 2.0-2016  
 Chassis/Eng# : JN1JANT32Z0001532/MR20825168B  
 Accident Date : 06/12/2020  
 Claim No. :  
 Reference :  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		RUST PROOFING TREATMENT		100.00 ?
		TRANSFER TAILGATE COMPONENT TO NEW GATE	60l	150.00
		CHANGE TAIL LAMP AND CHECK WIRING	20l	65.00
		REMOVE & REINSTALL REAR W/SCREEN GLASS	120l	180.00
		TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS		1,200.00 ?
		Labour Total S\$ :		3,295.00

SingDollars : Four Thousand Four Hundred Fifteen Only

Total S\$ : 4,415.00  
 =====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun