

Our Job Ref No : 305437870Date 09/12/20ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : Mr TAUFIKHVehicle Reg No. SHC1196BDate of Accident : 03/12/20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- SLJ5986C

2. The finalized amount shall be:

(a) Spare Parts after List discount \$0.00(b) Labour Charges \$691.00**Total for Part-By-Part Repair Cost** \$691.00

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%**Final Lumpsum Repair cost**3. Estimated normal period for repairs: 2 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : JUMANITel : 62148315Fax : 65468156Signature : taufikhName : TaufikhDate : 22/12/20**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305437870
REGN NO : SHC1196B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.12.2016
DATE/TIME IN : 08.12.2020 10:15
ACCIDENT DATE : 03.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 PB	PANEL BEATING	280.00
0001 SP	SPRAYPAINT CHARGE	400.00
0002 L	MERIMEN FEE	11.00

SUB-TOTAL : 691.00

TOTAL : 691.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :