

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMO20013516/49f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLJ 436G

at Workshop m/s

Team work

of

Insured:

Policy No.

Claims No.

CMTD 7003558/RUC

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$59

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Dep 8800

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLJ 436G

Yr Regn:

28/11/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Toyota Corolla Altis

C.C

1598

Colour

Brown

A/C: Insured / Std / NI / NA

Sp. Reading

206184

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MROS3REH104556708

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55-R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

5/12/20

D.O.I.

8/12/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R/L.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/5/18 11 AM.

LTA \$44940 NOT 14060.

agree 45814k.

28/12/20 4/5 \$14,000 confirmed with Darren. (Red \$18378.83, 57%)

29/12/20 12.56pm revised to Ruth Chua by email.

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

12

1) 28/12/2018

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.P. (\$

7P
14000

TOTAL



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE

SOMPO

Not Authorized
Take photo After Repair
8/12/20
14,000
12275

Vehicle number	SLJ436G
Make / Model	TOYOTA/COROLLA
Chassis number	MR053REH104556708
Accident date	5/12/20
Reference	2012-08

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	BOOTLID Body 733.80	822.50 ✓
1	BOOTLID EMBLEM LOGO nel 61.80	69.00 ✓
1	BOOTLID EMBELM -COROLLA nel 46.00	46.00 ✓
1	BOOTLID EMBLEM - ALTIS nel 42.50	50.60 ✓
1	BOOTLID CHROME GARNISH cre 225.30	265.65 ✓
1	BOOTLID LICENCE PLATE LAMP 11 72.40	72.40 X
2	BOOTLID LAMP B20 281.10 x 2 = 562.20	763.36 ✓
2	BOOTLID LAMP INNER SEAL 11 64.40	64.40 X
1	BOOTLID LOCK Bent/TWI 281.10	437.00 ✓
1	BOOTLID LOCK CATCH 11 23.00	23.00 X
1	BOOTLID HINGE 11 161.10	161.10 X
1	BOOTLID INNER TRIM de/torn 182.30	396.75 ✓
1	BOOTLID WEATHERSTRIP TWI 175.80	281.30 ✓
1	END PANEL Body 600.10	672.75 ✓
1	END PANEL TOP GARNISH TWI 241.50	241.50 ✓
1	REAR BUMPER Dis 557.75	557.75 ✓
2	REAR BUMPER RETAINER 11 130.00	130.00 X
2	REAR BUMPER REFLECTOR n/s B20 65.50	181.20 1PC
2	REAR BUMPER BRACKET 11 149.50	149.50 X
1	REAR BUMPER REINFORCEMENT Dis 399.50	453.20 ✓
4	PDC SENSOR Shoked 153.20 x 2 = 310.40	722.20 2PCS
1	SENSOR WIRE HARNESS 11 381.00	381.00 X
1	REAR WINDSCREEN MOULDING nel 89.70	89.70 ✓
1	REAR FENDER LH Bur 98.10	1124.70 ✓
1	REAR FENDER RH 11 1124.70	1124.70 X
2	REAR FENDER INNER TRIM 11 808.60	808.60 X
1	REAR EXHAUST SILENCER 11 1059.15	1059.15 X
1	REAR EXHAUST HEAT SHIELD 11 46.00	46.00 X
2	REAR EXHAUST MOUNTING 11 40.00	40.00 X

8,155.85

2	TAILLAMP	bro 391.70 x 2 = 783.40	901.06 /
2	TAILLAMP PANEL RH	R	243.80 X
1	FLOOR PANEL	R	898.15 X
1	SPARE TYRE TOP BOARD	Torn 267.00	326.60 /
1	FRONT BONNET	Buc 1146.10	1311.58 /
2	FRONT BONNET HINGES	Bent	235.00 /
1	FRONT BONNET LOCK	Twl 131.10	260.10 /
2	FRONT HEADLAMP	Cne 822.10 x 2 = 1644.20	5633.40 /
2	FRONT HEADLAMP CHROME GARNISH	11	290.50 X
1	FRONT GRILLE	Bro 382.50	564.00 /
1	FRONT GRILLE LOGO	neu 65.00	68.00 /
1	FRONT BUMPER	Torn 522.30	600.60 /
1	FRONT BUMPER SPONGE	11	166.70 X
1	FRONT BUMPER LOWER GRILLE	11	300.80 X
1	FRONT BUMPER REINFORCEMENT	R	400.50 X
2	FRONT BUMPER RETAINER	11	161.80 X
2	FRONT BUMPER FOG LAMP	11	460.80 X
2	FRONT BUMPER FOG LAMP COVER	11	194.20 X
2	FRONT FENDER	nls Bent 01SR 645.10	1801.20 12C
2	FRONT FENDER EMBLEM	11	112.00 X
1	FRONT SUPPORT PANEL	Dis 899.10	1074.50 /
1	FRONT SUPPORT PANEL TOP GARNISH	Dis 162.30	181.50 /
1	FRONT BRACE PANEL	Twl 131.10	225.20 /
2	HORN	Bent 48	116.00 12C
1	AIRCON CONDENSER	Bent/Pan	1287.20 /
1	AIRCON COMPRESSOR ASSY	X	2871.00 X
1	AIRCON LIQUID PIPE	Bent 288.50	837.60 /
1	AIRCON SUCTION PIPE	11	570.00 X
1	AIRCON DISCHARGE PIPE	11	498.00 X
1	RADIATOR	Dis	1510.50 /
1	RADIATOR FAN BLADE	Bro 100.80	155.50 /
1	RADIATOR FAN COWLING	Bro 288.90	433.80 /
1	RADIATOR FAN MOTOR	Im 485.00	699.80 /
1	INTAKE MANIFOLD	su x	
1	Engine...top cover	cne ✓ 285.30 ✓	
1	Air Cleaner Box Assy	bro ✓ 850.00 ✓	
1	THROTTER BODY	Cne	
1	BATTERY	DD	120 x 502 = 605.20
			36626.40
Less 25 %			7962.45
Subtotal			23887.35
Balance C/F			23887.35

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
1 SET	FRONT BUMPER CLIP <i>nee</i>	40.00	✓
1 SET	FRONT NUMBER PLATE <i>Bent</i>	70.00	40
1 SET	FRONT SUPPORT PANEL CLIP <i>11</i>	40.00	X
1 SET	FRONT GRILLE CLIP <i>11</i>	40.00	X
1 SET	REAR BUMPER CLIP <i>nee</i>	40.00	✓
1 SET	REAR FENDER INNER TRIM CLIP <i>11</i>	30.00	X
1 SET	REAR NUMBER PLATE <i>Bent</i>	70.00	40
1 SET	END PANEL GARNISH CLIP <i>11</i>	30.00	X
1 SET	BOOTLID INNER TRIM CLIP <i>11</i>	30.00	X
1 BOT	COOLANT <i>nee</i>	60.00	30
1	JOINT SEALANT <i>11</i>	100.00	X
<i>Ree</i> 1	WINDSCREEN SEALANT <i>nee</i>	100.00	40
Subtotal		650.00	280
Balance C/F		24537.35	
<u>LABOUR AND MISCELLANEOUS CHARGES</u>			
1	CHEECK REAR WIRING AND LIGHTNING SYSTEM	60.00	30
2	REMOVE, REFIT RADIATOR AND TOP UP COOLANT	200.00	100
3	REMOVE, REFIT CONDESER AND TOP UP GAS	200.00	
2	REMOVE, REFIT REAR LINING , TRIM AND GARNISH	200.00	80
3	REMOVE, RENEW REAR REVERSE SENSOR	120.00	50
4	REMOVE AND RENEW REAR EXHAUST <i>11</i>	120.00	X
5	REMOVE AND REFIT FUEL TANK	150.00	60
6	REMOVE AND REFIT REAR WINDSCREEN	150.00	120
7	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00	50
7	PANEL BEATING ON AFFECTED AREAS	2800.00	1800
8	SPRAY PAINTING ON AFFECTED AREAS	2600.00	1800
9	APPLY ANTI RUST ON AFFECTED AREAS	100.00	✓
Subtotal		6900.00	
Grand total		31437.35	4190

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

32378.83

17724.25

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/12/2020 18:00 (SGT)
Date of Accident	05/12/2020 16:30 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ436G
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	ROSET LIMOUSINE SERVICES PTE LTD
Company Reg No	2XXXXX722Z
Email Address	darrenlack@yahoo.com
Mobile Phone No	(Phone) +65-68445225
Alternative Phone No	+65-68445225

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	COROLLA ALTIS CLASSIC 1.6 CVT
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SD20V13100/VPZ/R02
Cover Note Number	-

DRIVER

Name of Driver	LACK CHOON HOU (LU JUNHAO)
NRIC No	SXXXX539E
Date Of Birth	17/12/1975
Occupation	Outdoor

Date Of Driving Pass	28/01/2003
Driving experience	17 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97660368
Alt. Phone Number	-
Email Address	darrenlack@yahoo.com
Address	BLK 293D BUKIT BATOK STREET 21
Address complement	#19-538
Postcode	654293
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT - T/20201205/7087.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF2185G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	HONG JIEMING
NRIC No	SXXXX201D

Contact Number	(Phone) +65-94875815
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBF9692M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	AW CHUAN JOO
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	LACK CHOON HOU (LU JUNHAO)
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	NECK & BACK
Injured person in which vehicle?	SLJ436G
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: S-L 436 G	
B: GBF 2185 G	
C: GBF 9692 M	

Describe Circumstances of the Accident

Refer to police report

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20201205/7087

1 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20201205/7087

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/12/2020 20:01	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: LACK CHOON HOU			Address: 293D BUKIT BATOK STREET 21 #19-538 SINGAPORE 654293	
ID Type / ID No.: NRIC NO / S7537539E			Contact No.:	Mobile: 97660368
Nationality: SINGAPORE CITIZEN			Home/Office:	
			Email: DARRENLACK@YAHOO.COM	
Sex: Male	Age: 44	Date of Birth: 17/12/1975	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Other car and light goods vehicle drivers nec			Driving Licence Information: Class: 2B,3	Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 05/12/2020 16:40	Type of Location: Straight Road
Location: PAN ISLAND EXPRESSWAY				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit: 80 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
GBF2185G	Lorry	NISSAN		White	Seriously Damaged	0
GBF9692M	Lorry	ISUZU		White	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20201205/7087

2 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20201205/7087

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Conditio	No of
SLJ436G	Car	TOYOTA		Brown	Seriously Damaged	0

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	HONG JIEMING	ID No.	S8233201D
Related Vehicle	GBF2185G (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 2B,3 Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
Driver			
Name	AW CHUAN JOO	ID No.	S1139802D
Related Vehicle	GBF9692M (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 2B,3 Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
Driver			
Name	LACK CHOON HOU	ID No.	S7537539E
Related Vehicle	SLJ436G (Car)	Contact No.	97660368
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 2B,3 Date of Expiry: NIL
Date	05/12/2020	Date	05/12/2020
No. of Days granted Medical Leave	03	Degree of	Serious



**SINGAPORE
POLICE FORCE**



T/20201205/7087

3 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20201205/7087

CONTINUATION OF REPORT

Brief Details.

I was travelling on PIE(TUAS). I met a chain accident on Lane 1 before clementi exit involving 3 vehicles. I was involve in the middle vehicle.
It happened while I saw the vehicle in front of me brake and I follow suit. Right after I came to a stop, a vehicle bang onto me from the back which resulted me to collide onto the front vehicle. We exchange particulars and I felt pain on my body and had since consulted a doctor and was given 3days MC.



**SINGAPORE
POLICE FORCE**



T/20201205/7087

4 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20201205/7087

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TP1B /
MOHAMAD ZULFAZDLI BIN ABDULLAH
Contact No.: 65476204

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
05/12/2020 20:01

Classification Of Case: