

Your Ref: S0M02F56

Date: 21st May 2021

Our Ref: CS1/ASM20013524/Gvf3e2

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Oh Vale

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBG 7668S

INSURED VEHICLE: SJQ 71L

ACCIDENT DATE: 03/02/2020

We thank you for your instruction on 08/12/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBG 7668S from M/s PAR Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles GBG 7668S, SJQ 71L and SMH 9217L.
- c) Police Report of Vehicles GBG 7668S.
- d) Final Repair Bill of GBG 7668S from M/s N-51 Automotive Pte Ltd.
- e) Colour damaged vehicle photographs of GBG 7668S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

| | |
|----------------------|---|
| Registration Number | : GBG 7668S |
| Make & Model | : Fiat Doblo Cargo Maxi 1.6 MTJ AMT Glaza |
| Chassis Number | : ZFA26300006H34050 |
| Year of Registration | : 2017 |
| Engine Capacity | : 1598 cc |

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.