

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 08.12.2020

Time: 12:45:47

Page: 1

Aig Asia
CLS)

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305437871
 REGN NO : SHC8101D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 07.08.2014
 DATE/TIME IN : 08.12.2020 10:05
 ACCIDENT DATE : 08.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0578-G	FRT BUMPER	1	1,052.20	20.00	841.76	de
0002 04-01-0103-0638-G	FRT BUMPER UPR BRKT RH	1	44.80	20.00	35.84	X un
0003 04-01-0103-0640-G	FRT BUMPER SIDE BRKT RH	1	24.60	20.00	19.68	per
0004 04-01-0103-0654-G	FRT BUMPER GRILLE RH	1	187.20	20.00	149.76	RP
0005 04-01-0103-0782-A	HEADLAMP RH	1	1,800.00	20.00	1,440.00	X un
0006 04-01-0103-0573-G	FRT FENDER RH	1	663.00	20.00	530.40	bt
0007 04-01-0103-0658-G	FRT WHEEL CAP RH	1	217.20	20.00	173.76	X un

1391.84

SUB-TOTAL : 3,191.20

JOB NATURE

0000 PB	PANEL BEATING	600.00	480
0001 SP	SPRAYPAINT CHARGE	500.00	400
0002 17-01	CHECK ALL LIGHTING	40.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	30

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 08.12.2020

Time: 12:45:47

Page: 2

Arg Asia
(Lys)

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305437871
REGN NO : SHC8101D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 07.08.2014
DATE/TIME IN : 08.12.2020 10:05
ACCIDENT DATE : 08.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 L WHEEL ALIGNMENT

120.00 X un. 940

SUB-TOTAL : 1,300.00

TOTAL : 4,491.20

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

Lungs

Duration.

Turpin 17495749 1391.84
w/ 8/12/2020 940
c/s Resurvey after repair 2331.84
Turpin C/Inauto-wr. 4581850 \$
2 days
(2-3 days)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: