



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI20013532/Uvd3q2 Date: 29/12/2020	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLE 2458G	Veh. Inspected	SCQ 8911T
Policy No.		Coverage (\$)	0.00
Claim No.	C10008263/JM	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	08/12/2020
2. Vehicle Particulars & Condition			
Make & Model	JAGUAR XE (A)	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	SAJAB4AG9GA904338	Colour	GREY
Odometer	51343 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R17	PIRELLI	6 mm
L/H Front Tyre	225/50 R17	PIRELLI	6 mm
R/H Rear Tyre	225/50 R17	PIRELLI	6 mm
L/H Rear Tyre	225/50 R17	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/11/2020	Inspection Date	09/12/2020
Survey held at	JOO HAK KEE AUTO PTE LTD 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	