

Our Job Ref No 305437378
Date : 17.12.20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr TAUFIKH
Vehicle Reg No. SHA1595T CTPL

Fax :
05.12.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FC3340L
2. The finalized amount shall be:
- | | |
|--|--------------------------|
| (a) Spare Parts after List discount | <u>\$1,144.94</u> |
| (b) Labour Charges | <u>\$810.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,954.94</u> |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: <u>20%</u> | |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs: 3 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : taufikh
Name : Taufikh
Date : 28/12/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LKe

NTUC

COMFORTDELGRO ENGINEERING PTE LTD

Date: 07.12.2020

Time: 10:54:30

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305437378
 REGN NO : SHA1595T
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 06.08.2020
 DATE/TIME IN : 05.12.2020 11:15
 ACCIDENT DATE : 05.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52	over
0002 04-01-0104-2531-G	BRACKET ASSY-RR BUMPER SI	1 L	55.80	20.00	44.64	?
0003 04-01-0104-2546-G	COVER-RR BUMPER SIDE UNDE	1 L	108.50	20.00	86.80	X
0004 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	new
0005 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00	X
0006 04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00	2.00-	50.00	not
0007 04-01-0104-2697-G	IONIQV4 LAMP ASSY-REAR CO	1 L	870.40	20.00	696.32	over
* Petrol Only Logo - #15 - new						SUB-TOTAL : 1,623.88

JOB NATURE

0000 L	PANEL BEATING(repair rr fender Lh)	350.00	320
0001 23-502	SPRAYPAINT ON AFFECTED AREA	450.00	400
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30

Remove/Refix Reverse Sensor - #80 30v MLC

Tampine 97415749

WP 7/12/2020 / pm

3 days

P/p Resing before paint
Tampine like auto.com

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305437378
 REGN NO : SHA1595T
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 06.08.2020
 DATE/TIME IN : 05.12.2020 11:15
 ACCIDENT DATE : 05.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0003	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00	2.00-	50.00
0004	04-01-0104-2697-G	LAMP ASSY-REAR COMB OUTSI	1 L	870.40	20.00	696.32
0005	28-01-0302-2017-A	PRIVC FUEL TANK LID (PETR	1 N	15.00	10.00	13.50

SUB-TOTAL : 1,144.94

JOB NATURE

0000 L	PANEL BEATING(repair rr fender Lh)	320.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	400.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	30.00
0004 20-22	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 810.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 17.12.2020

Time: 18:15:46

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305437378
REGN NO : SHA1595T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 06.08.2020
DATE/TIME IN : 05.12.2020 11:1
ACCIDENT DATE : 05.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,954.94

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :