

Our Job Ref No : 305437875Date 10/12/20ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : Mr TAUFIKHVehicle Reg No. SH 6115XDate of Accident : 08/12/20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG --- SLR5308T

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%\$3,400.00**Final Lumpsum Repair cost**3. Estimated normal period for repairs: 3 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and  
finalized amountSignature : Name : JUMANITel : 62148315Fax : 65468156Signature : taufikhName : TAUFIKHDate : 22/12/20**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks: