PRS Filed By: GQ REF: CS3/AIG20009098/Gqf3-1

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s MERLIN MOTOR

of

Insured:

Policy No. 1900168416

Claims No. 6824946365SG

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMJ 8722R Yr Regn: 17 May/2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MERCEDES BENZ C180 c.c 1595

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading 195688 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2040312A833022 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	28-08-2020

Survey held at W/S 3pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
28/08	Yes/No BI Involved — W/S also don't know
	No GIA provided
	Submit DAR
14/12/20	Submit LS $2400, 3 days (Red $5400, 69%)

Date/Time, File Pass to? 1) 14/12 Typist

Date/Time, File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format: TP

Lump Sum Value: 2400

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL