

12/12/2020

REF: CS3/CTI20013593/Kvd3

Special Instruction:

ASS. REC. BY:

Surveyor: KENNETH

ASSIGNMENT (Office)

From (Person): ADELINE CHNG of CTI

Date/Time: 8/12/2020@6.04PM

Estimated Cost:

Bill to:

OD ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBF 5169J

Insured: GBD 730G

at Workshop m/s SPEEDY MOTOR CYCLE

Tel: 9388 6867

of Blk 10 Ang Mo Kio Industrial Park 2A# 05-21

Policy No: DMCVSNW00028632001

Claim No: SNM20D204709/C02

Sum Insured:

Excess:

D.O.A. 28/11/2020

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

MR.LIM

H.O.D. Endorsement:

Date/Time: 10.49AM@9/12/2020

Person Contacted:

Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate	
	FBF 5169J- NA/CTI20013543/r3	DOA : 28/11/2020
	GBD 730G- NA/CTI20013543/r3	DOA ; 28/11/2020
10/12/20	Submit PRS, repair range \$2,000-\$3000	