

ASS. REC. BY:

Jone

REF:

es/CT120013609/Riqd3

4452

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV


To Inspect Vehicle No: SLU 7435Eat Workshop m/s TRANS EUREKASof 27A, TANJONG PERAGUInsured: CTIPolicy No. DMPCSNA00125642002Claims No. SNM20D204715C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 61k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 7435E Yr Regn: 2017 / DECType: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: MAZDA 3 SEDAN 1.5 AT c.c. 1496Colour GREY A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading 46142 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: JM6BN22A8J0192460Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☐ Nil / ☒ R/Rim / ☐ STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 02/12/2020D.O.I. 11/12/2020

Survey held at

TRANS EUREKASDes. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/12/20 @ 2.39pm revised to Irene Tay via Merimen.

16/03/21 @ 11.18am Rasul finalised with Jen Lim final fig \$10721.90, 11 days (Red \$8681.80, 45%)

Date/Time, File Pass to?



: Prelt. Report



: Final Report

19/03 Typist

Date/Time, File Return to?

2)

Days Of Repair: 11Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Rep. Format: MER-TPEmp. Cost / L.B. (\$ 10721.90)



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

ATTN.:

MOTOR CLAIMS

FAX:

NAME: Mdm Ng Phuy Hoon

ADDRESS: 10 Nim Road

Singapore 807544

TEL: 97683337

WIP: 23772

EXCESS:

DATE: 4-Dec-20

VEH NO:

SLU7435E

DATE IN:

CONTACT PERSON:

Catherine

CHASSIS NO:

JM6BN22A8J0192460

MILEAGE:

TYPE OF CLAIM:

THIRD PARTY CLAIM

MODEL:

MAZDA 3

DATE REG.:

13-Dec-17

POLICY NO.:

NATURE OF WORKS

Parts Description

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	REAR BUMPER <i>de-</i>	MBHN1-50-221ABB	1				\$ 1,128.60
2	RETAINER LHS <i>X</i>	MB63B-50-2J1B	1				\$ 33.60
3	RETAINER RHS <i>X</i>	MB63B-50-2H1B	1				\$ 33.60
4	BRACKET CENTER <i>X</i>	MKD53-50-251	1				\$ 5.40
5	GROMMET, FRONT BUMPER <i>re-</i>	MBHN1-50-021A	4				\$ 10.80
6	RIVET, FRONT BUMPER <i>re-</i>	MB8M4-50-355	4				\$ 18.00
7	FASTENER, FRONT BUMPER <i>X</i>	MB45A-56-146A	4				\$ 12.00
8	TOWING COVER LHS <i>Mis-</i>	MBHN1-50-EL1 BB	1				\$ 16.50
9	TOWING COVER RHS <i>X</i>	MBHN1-50-EK1 BB	1				\$ 17.10
10	REFLECTOR RHS, FRONT BUMPER <i>X</i>	MD350-51-5M0E	1				\$ 53.00
11	REAR REINFORMENT <i>bt-</i>	MB45A-50-260	1				\$ 564.20
12	BOOTLID <i>bt-</i>	MBHY2-52-61XB	1				\$ 1,005.30
13	WEATHERSTR, BOOTLID <i>X</i>	MBHN1-56-951A	1				\$ 113.10
14	LOCK, BOOTLID <i>X</i>	MGHK1-56-820A	1				\$ 160.70
15	FASTENER, BOOTLID <i>X</i>	MGJ21-68-885B02	6				\$ 18.00
16	GROMMET, BOOTLID <i>re-</i>	MGA7B-51-146	2				\$ 6.60
17	FASTENER, BOOTLID <i>re-</i>	MEG21-51-146	2				\$ 12.40
18	TAILLAMP LHS <i>X</i>	MB45A-51-160B	1				\$ 534.90
19	TAILLAMP RHS <i>X</i>	MB45A-51-150B	1				\$ 534.90
20	BOOTLID LHS <i>X</i>	MB45A-51-3G0	1				\$ 278.30
21	BOOTLID RHS <i>X</i>	MB45A-51-3F0	1				\$ 278.30
22	GASKET LHS, TAILLAMP <i>re-</i>	MBHN1-51-163	1				\$ 22.00
23	GASKET RHS, TAILLAMP <i>re-</i>	MBHN1-51-153	1				\$ 22.00
24	GASKET LHS, BOOTLID <i>re-</i>	MB45A-51-3J8	1				\$ 22.00
25	GASKET RHS, BOOTLID <i>re-</i>	MB45A-51-3H8	1				\$ 22.00
26	MASCOT, REAR <i>re-</i>	MBHN1-51-730	1				\$ 78.20
27	ORNAMENT, MAZDA 3 <i>re-</i>	MBHN1-51-721	1				\$ 56.10
28	ORNAMENT, SKYACTIV <i>re-</i>	MBHN1-51-771	1				\$ 66.80
29	REAR END PANEL <i>bt-</i>	MB4YA-70-75Z	1				\$ 530.40
30	LOWER PANEL RHS <i>re-</i>	MB4YA-70-40X	1				\$ 373.20

NUMBER <input checked="" type="checkbox"/>	MD350-51-920A	1				\$ 74.90
TRIM, END PANEL <input checked="" type="checkbox"/>	MBHN1-68-89XA	1				\$ 89.40
BEZEL, LOCK <input checked="" type="checkbox"/>	MGHK1-68-894	1				\$ 11.40
TOTAL PARTS						\$ 6,203.70
TOTAL PARTS COST						\$ 6,203.70

SUPPLEMENTARY

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1							
2							
3							
TOTAL PARTS							\$ -
TOTAL PARTS COST							\$ -

Labour Description

1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, LOWER PANEL RH AND BOOT LID. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. <i>Repair rear 2 fenders</i>	2640	\$ 5,280.00
2	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, LOWER PANEL RH AND BOOT LID.	3150	\$ 3,780.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	NETT	\$ 180.00
4	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	330	\$ 660.00
5	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.(WITH REVERSE SENSOR)	330	\$ 660.00
6	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	X	\$ 330.00
7	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	X	\$ 1,260.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOUK)	150	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
11	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	X NETT	\$ 100.00
12	MZ-BR-SUNDRI	SUNDRIES.	30 NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 13,200.00
TOTAL PARTS	\$ -	\$ 6,203.70
TOTAL	\$ -	\$ 19,403.70
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

SUPPLEMENTARY LABOUR DESCRIPTION

1	#N/A		
2	#N/A		

TOTAL LABOUR	\$ -	\$ -
TOTAL PARTS	\$ -	\$ -
TOTAL	\$ -	\$ -
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorized Signature

Rashid
Hp 90010068

11 days

11/12/2020 @ 1000

Resy before part

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 03/12/2020 12:20 (SGT)
Date of Accident 02/12/2020 07:50 (SGT)
Exact Location of Accident Singapore
Additional Location Information CTE BEFORE EXIT TO JALAN BUKIT MERAH
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU7435E

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner NG PHUAY HOON
NRIC No SXXXX445Z
Email Address phuayhoon@yahoo.com
Mobile Phone No (Phone) +65-97683337
Alternative Phone No +65-91773978

VEHICLE PARTICULARS

Manufacturer Mazda
Model 3
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company AIG
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1700092700
Cover Note Number -

DRIVER

Name of Driver TAN HAK KOON
NRIC No SXXXX825J
Date Of Birth 05/11/1963
Occupation Indoor

Of Driving Pass	08/12/1989
ing experience	31 YEARS
ender	Male
obile Number	(Phone) +65-91773978
Alt. Phone Number	-
Email Address	tan.hak.koon@singhealth.com
Address	10 NIM ROAD
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHED SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB2771D
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	NAI YIH SHYONG
NRIC No	SXXXX608H
Contact Number	(Phone) +65-98569182
Address	-
Address complement	-
Postcode	-

Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

China Taiping Insurance

-
-
-


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 2/12/2020
7:30 pm


Driver's Signature
(If driver is not the policyholder)
Date & Time: 2/12/2020
7:30 pm


Reporting Centre Personnel's Signature
Name: Catherine Chua
NRIC/FIN No.:

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At around 7:45am on 2/12/20, I was driving along CTE towards Jurong.
I exited at Jalan Bukit Merah Exit (Exit 1A), and was driving in the
left lane, hoping to turn left into Jalan Bukit Merah towards Karpag Bahru Road.
The weather was sunny, the road was dry and the traffic was smooth.

As ^{we} were approaching the junction at Zebra Crossing, the cars in
front of my car all slowed down, and I slowed down
gradually.

Suddenly I heard a loud 'bang' at the back of my car,
and I realised my car was hit from behind by SKB 2771D.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Ng Phuan Han
Policyholder's Signature
Date & Time: 2/12/2020
7:30pm

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time: 2/12/2020
7:30pm

[Signature]
Reporting Centre Personnel's Signature
Name: Catherine Chua
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	445Z

Vehicle No.:	SLU7435E
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2020
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	P520484616
Chassis No.:	JM6BN22A8J0192460
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$15,348.00
Original Registration Date:	13 Dec 2017
First Registration Date:	13 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$10,348.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2027
PARF Rebate Amount:	\$7,761.00

COE Expiry Date:	12 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,112.00
COE Rebate Amount:	\$32,991.00
Total Rebate Amount:	\$40,752.00

The information contained herein is correct as at 11 Dec 2020

OK

Silver

► Mazda 3 1.5A Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map



興利

HENLY ENTERPRISES COMPANY PRIVATE LIMITED

18 Ubi Road 4, #01-05/07/08 Ubi Car Mall Singapore 408616 Tel: 6336 3133



Price	\$60,500		
Depreciation ⓘ	\$7,990 /yr View models with similar depre	Reg Date	22-Nov-2017 (6yrs 11mths 10days COE left)
Mileage	38,659 km (12.7k /yr)	Manufactured ⓘ	2017
Road Tax ⓘ	\$682 /yr	Transmission	Auto
Dereg Value ⓘ	\$38,858 as of today (change)	OMV ⓘ	\$14,937
COE ⓘ	\$45,201	ARF ⓘ	\$9,937
Engine Cap	1,496 cc	Power	88.0 kW (118 bhp)
Curb Weight ⓘ	1,310 kg	No. of Owners ⓘ	2
Type of Vehicle	Mid-Sized Sedan		

Features

1.5L 4 Cylinders Inline 16 Valve DOHC SKYACTIV-G Engine. 6 Speed Automatic Transmission. SRS Airbags. Keyless Start. View specs of the Mazda 3 Sedan (2014-2019)

