

CSA Form 101

6ul-
PHS

ASSIGNMENT

From _____ Date _____
 Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Garage 13
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$15K 18K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: ST6974J Regn: 20 Jun 2008
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda stream 1.8c 1793
 Colour: Black A/C: Insured / Std / NI / NA
 Sp Reading: 140566 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RN610461 28.
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6</u> mm
D.O.A.		D.O.I.	<u>10-12-20</u>

Survey held at W/S 2:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>CEB 19571</u>
	<u>\$7000 - \$8000</u>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Other (\$

Survey Fee:

Transportation:

☐ : 3 + RS, ☐ : SI

☐ : Photos

☐ : Other

Printed Name

Printed Name / Title

Page 1