

ASS. REC. BY:

REF:

CS/CT120013627/Rivf3

5396

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBK 50106

at Workshop m/s

BORNEO MOTOR

of

2, PANDAN (RESERV)

Insured:

CTI

Policy No.

Claims No.

Sum Insured:

Excess:

350

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

75K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBK 50106

Yr Regn:

2020 / MCH

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA DYNA 150 SMT

c.c 2982

Colour

GREY

A/C: Insured / Std / NI / NA

Sp. Reading

8987

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT 354XOK 215215

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R5 / 75R15

R:

155R12C

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or .

Front

R/Bal.

7

mm

Rear

R/Bal.

5/5

mm

L/Bal.

7

mm

L/Bal.

5/5

mm

D.O.A.

04/12/2020

D.O.I.

11/12/2020

Survey held at

BORNEO MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

Date/Time, File Pass to?

☐

Prelt. Report

☐

Final Report

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.B.A. (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL



Borneo Motors



TOYOTA

hchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

LKK

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No. 0 Document Date 07/12/2020	M/S Uni-Crane Pte Ltd 29 Tuas Avenue 11 #02-03 Singapore 639089

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDY231R	TLMKY S5	20/03/2020	GBK5010G	0	58685	650D/GBK5010G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFAT35YX0K215215	1KDB038786	60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMCVSNW00074792000 ACC DATE:04.12.20 DRIVE IN : 04.12.20 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
4	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP.				180.00
5	S	BP-SUBLET RESET AND REPROGRAMME ECU.				180.00
6	S	BP-SUBLET REMOVE AND REINSTALL FRT DASH BORAD ASSY TO ASSIST REPAIR.				1296.00
7	B	BP-LAB2 REMOVE AND REINSTALL FRT W/SCREEN TO ASSIST REPAIR.				450.00
8	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, FRT PANEL ASSY, L/F MIRROR AND AFFECTED PORTION OF CAR.				2880 3600.00
9	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1770 2360.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	M/S Uni-Crane Pte Ltd 29 Tuas Avenue 11 #02-03 Singapore 639089
	Document No. 0	
	Document Date 07/12/2020	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDY231R	TLMKY S5	20/08/2020	GBK5010G	0	58685	650D/GBK5010G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFAT35YX0K215215	1KDB038786	60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	1	T52101-37985 BUMPER SUB-ASSY, FR <i>bt</i>	1.00	748.90		748.90
11	2	T81110-37660 HEADLAMP ASSY, RH <i>X</i>	1.00	1178.70		1178.70
12	3	T81150-37660 HEADLAMP ASSY, LH <i>cr</i>	1.00	1178.70		1178.70
13	4	T53111-37A01 B1 GRILLE, RADIATOR <i>cr</i>	1.00	595.20		595.20
14	5	T75315-37080 ORNAMENT, RADIATOR <i>cr</i>	1.00	70.50		70.50
15	6	T75311-25100 PLATE, FR NAME, NO.1 <i>bt</i>	1.00	63.40		63.40
16	7	T55700-37350 COWL ASSY <i>bt</i>	1.00	1194.30		1194.30
17	8	T55078-37110 COVER SUB-ASSY, FR <i>bt</i>	1.00	311.80		311.80
18	9	T87905-37122 ARM SUB-ASSY, OUTER <i>bro</i>	1.00	600.10		600.10
19	0	T56121-25040 FRONT W/SCREEN MLDG, <i>new</i>	1.00	369.40		369.40

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Pass
4p 9000008
8 days
11/12/2020
P 0910
Reay before put
EXCESS: 350
Reay

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Acknowledged by Repairer Customer's Signature Date: <i>[Signature]</i>	Charge Summary	Total 14,657.00
	Please acknowledge receipt of vehicle	Parts 6,311.00 Labour 6,790.00 Sublet 1,556.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00% 1,025.99 Less 0.00 Amount Due 15,682.99

Customer Copy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/12/2020 14:30 (SGT)
Date of Accident	04/12/2020 22:30 (SGT)
Exact Location of Accident	1-Blk, 740 Pasir Ris Drive 3, Singapore
Additional Location Information	PASIR RIS DRIVE 1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBK5010G

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	UNI-CRANE PTE LTD
Company Reg No	1XXXXX539G
Email Address	UNIMANDYGOH.UNICRANE@GMAIL.COM
Mobile Phone No	(Phone) +65-68620246
Alternative Phone No	(Office) +65-68620246

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMCVSNW00074792000
Cover Note Number	-

DRIVER

Name of Driver	YONG JUN MENG
NRIC No	SXXXX404I
Date Of Birth	05/05/1980
Occupation	Outdoor

Date Of Driving Pass	25/09/2015
Driving experience	5 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-82011335
Alt. Phone Number	-
Email Address	NORMANLEE20@HOTMAIL.COM
Address	APT BLK 749 PASIR RIS STREET 71 #04-62
Address complement	-
Postcode	510749
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Joo Chiat Neighbourhood Police Post
Police Station Phone No	(Phone) +65-18003459999
Alt. Police Station Phone No	(Fax) +65-64474181
Police Station Address	267 Onan Road Singapore 424773
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT : T/20201205/2088

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SJG974J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

-
-
-
-
-
-
-

SWITCH PLAN

1870-1871: 1871

1. The system is controlled by the feedback which the output error
2. The system is controlled by the feedback which the output error
3. The system is controlled by the feedback which the output error
4. The system is controlled by the feedback which the output error
5. The system is controlled by the feedback which the output error
6. The system is controlled by the feedback which the output error
7. The system is controlled by the feedback which the output error
8. The system is controlled by the feedback which the output error
9. The system is controlled by the feedback which the output error
10. The system is controlled by the feedback which the output error
11. The system is controlled by the feedback which the output error
12. The system is controlled by the feedback which the output error
13. The system is controlled by the feedback which the output error
14. The system is controlled by the feedback which the output error
15. The system is controlled by the feedback which the output error
16. The system is controlled by the feedback which the output error
17. The system is controlled by the feedback which the output error
18. The system is controlled by the feedback which the output error
19. The system is controlled by the feedback which the output error
20. The system is controlled by the feedback which the output error





SINGAPORE POLICE FORCE



T/20201205/2088

Police Station Of Origin:
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No: 1800-3459999

1 of 3

Report No. T/20201205/2088

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/12/2020 16:14	Vide Report No.:	Station Diary No.: 25
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: YONG JUN MENG		Address: APT BLK 749 PASIR RIS STREET 71 #04-62 SINGAPORE 510749	
ID Type / ID No.: NRIC NO / S8087404I		Contact No.: Home/Office: Mobile: 82011335	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 40	Date of Birth: 05/05/1980	Type of Informant: Driver
Race: Chinese		Language: Chinese	Institution / School Name:
Occupation: Civil engineering/Building construction labourer		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 04/12/2020 22:30	Type of Location: Straight Road
Location: PASIR RIS DRIVE 1				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBK5010G	Lorry	TOYOTA		Silver	Slightly Damaged	0
SJG974J	Car	HONDA	STREAM	Black	Slightly Damaged	2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20201205/2088

Police Station Of Origin:
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No: 1800-3459999

2 of 3

Report No. T/20201205/2088

CONTINUATION OF REPORT

Driver				
Name	YONG JUN MENG		ID No.	S8087404I
Related Vehicle	GBK5010G (Lorry)		Contact No.	82011335
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

I was driving along Pasir Ris grove when suddenly, the traffic light turn red. I did not manage to step on the brake in time, resulting my front hitting on the other driver's rear. No injuries was sustained to both drivers and passengers. I did not attain the particulars of the other driver.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No: 1800-3459999



T/20201205/2088

3 of 3

Report No. T/20201205/2088

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

[Handwritten signature]

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 ANDREZ TEO YU WEI

[Handwritten signature]

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Authentication Stamp

NP168

Signature Of Informant:

[Handwritten signature]

Date/Time:

05/12/2020 16:14

Classification Of Case:



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Motor Commercial

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act/Directive 1987
Motor Vehicles (Third-Party Risks and Compensation) Rules 1989
Road Transport Act 1987 Malaysia
Motor Vehicles (Third-Party Risks) Rules 1989 Malaysia

MZ300/C

N SN

AN0650A

Cov. Type:C

CERTIFICATE No.

DMCVSNW00074792000

Engine No.: 1KDB038786

Cha. No.: JTFAT35YX0K215215

1. Make/Model and Registration
Number of Vehicle

GBK5010G

2. Name of Policy Holder

UNI-CRANE PTE LTD

3. Effective date of the Commencement of
Insurance for the purposes of the Regulations,
Ordinance or Enactment

20/08/2020

Excess Sect I. S\$350.00

EX ON WINDSCREEN. S\$100.00

4. Date of Expiry of Insurance

19/08/2021

5. Persons or Classes of Persons entitled to drive

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

(1) Use in connection with the Policyholder's business.

(2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.

(3) Use for social, domestic or pleasure purposes.

The Policy does not cover

(1) Use for hire or reward or racing, pace-making, reliability trial or speed testing.

(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

HIRE PURCHASE CO.: DAIMLER FINANCIAL SVCS AFRICA & ASIA PACIFIC LTD

Conditions referred to operative by Section 3 of the Motor Vehicles (Third-Party Risks and Compensation) Act/Ordinance 1987 and Section 32 of the Road Transport Act 1987 (Malaysia) are not to be included under these headings

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act, Chapter 89 and Part IV of the Road Transport Act, 1987 (Malaysia)

Please see reverse

By CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

BELL AUTO PTE LTD

Authorized Officer

杨西美

Authorized Officer

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	539G
Vehicle No.:	GBK5010G
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2020
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	1KDB038786
Chassis No.:	JTFAT35YX0K215215
Maximum Power Output:	-
Open Market Value:	\$29,349.00
Original Registration Date:	20 Aug 2020
First Registration Date:	20 Aug 2020
Transfer Count:	0
Actual ARF Paid:	\$1,468.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	19 Aug 2030
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$23,888.00
COE Rebate Amount:	\$23,143.00
Total Rebate Amount:	\$23,143.00

The information contained herein is correct as at 11 Dec 2020


OK

Silver

armart.com/used_cars/info.php?ID=920607&DL=1366

► Toyota Dyna 150 3.0M

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)



Price	\$75,800	Lifespan	16-Aug-2040
Depreciation ⓘ	\$7,830 /yr View models with similar depre	Reg Date	17-Aug-2020 (9yrs 8mths 5days COE left)
Mileage	1 km	Manufactured ⓘ	2020
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$21,309 as of today (change)	OMV ⓘ	\$29,349
COE ⓘ	\$22,002	ARF ⓘ	\$1,468
Engine Cap	2,982 cc	No. of Owners ⓘ	1
Curb Weight ⓘ	1,760 kg		
Type of Vehicle	Truck		

Features

Full Loan/Flexible/Fast/Easy Loan Approval Avail. High Trade-In. Your Sincere/Friendly Commercial Advisers To Serve/Help Your Transport Needs Better! View specs of the Toyota Dyna 150 (2014)

