



Your Ref: 20/20/20/VP96/317771

Date: 07<sup>th</sup> Jan 2021

Our Ref: CS1/LPM20013673/Evd3e2

**M/s Lonpac Insurance Bhd**  
21St Flr, Bangunan Public Bank  
No. 6 Jalan Sultan Sulaiman  
50000 Kuala Lumpur, Malaysia

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLA 7419H**  
**INSURED VEHICLE: GG 3222**  
**ACCIDENT DATE: 12/09/2020**

We thank you for your instruction on 09/12/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLA 7419H from M/s JDJ Appraisal.
- b) Police Report of Vehicles SLA 7419H and GG 3222.
- c) Colour damaged vehicle photographs of SLA 7419H.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -
  - Registration Number : SLA 7419H
  - Make & Model : Chevrolet Captiva C140 2.4
  - Year of Registration : 2016
  - Chassis Number : KL1CA26UJGB510687
2. We recommend that the repairs of the entire damage require about 28 (Twenty-Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.