


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MY  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. 1900108961  
 Claims No. 8412571564SG  
 Sum Insured: \_\_\_\_\_ Excess: 0/-  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Cum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMM 4337E Yr Regn: 28/6/19  
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: KIA Cerato c.c. 1591  
 Colour: Silk A/C: ☒ Insured / Std / NI / N  
 Sp. Reading: 35590 T/Radio: ☒ Insured / Std / NI / N  
 Eng/No: \_\_\_\_\_  
 C/No: KNAF 3416 MK 5947758  
 Gen. Cond: ☒ Good / Fair / Poor / Burnt  
 Steering: ☒ In order / Jammed / Leaked / Burnt or  
 Brake: ☒ In order / Jammed / Leaked / Burnt or  
 Modl: NII / S/Rim / STD A/Rim or  
 Tyre Size: F: 225/45 R17  
 R: 225/45 R17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or KUMHO  
 Front Rear  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 10/12/20 D.O.I. 11/12/20  
 Survey held at Cycle & Carriage  
 Des. of Damages: Frt ☒ Rear ☒ O/S / N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MR-75K

11/12/20@5.59pm revert to AIG via Merimen.

13/12/20@5.14pm Kok Chong informed C/A via Merimen.

14/12/20@9.14am Informed Kevin C/A & ex:\$0/-, provide us the sales agreement to prove coating.

19/01/21@5.23pm Confirmed with Ms Loi final fig \$5,558.80, 5 repair days. (Red \$2035.20, 27%)

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1)

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Form: MER-OD

Comp sum / L.P. / \$ 5558.80



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10370/LAM WAIN SION (LAN WENSEN) Reg No/Reg Date SMM4337E / 28/06/201 Date In/Mileage 11/12/2020/ 0 Chassis No KNAF3416MK5047758 Engine No G4FGKH738725 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	10/12/2020/ 17:09	QUK	282 / Kevin Leong	25569		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BOOT & AFFECTED AREA REPAIR ON REAR END PANEL							800 1600.00
E PNT98000 PAINT WORK ON REAR BUMPER, BOOT & END PANEL							700 1050.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMEPARTMENT FOR FACILITATE REPAIR							? 120.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST							? 40.00
M SUNDRY PERFORM RUST PREVENTION							30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							160.00
M SUNDRY TO APPLY ZERTONA COATING ON AFFECTED AREA							20 50.00
M SUNDRY SUNDRIES							
M PANEL ASSY-TRUNK LH				1.00	1297.00	20.00	1037.60
M PANEL ASSY-BACK				1.00	324.00	20.00	259.20
M COVER-RR BUMPER				1.00	651.00	20.00	520.80
M COVER-RR BUMPER LWR				5.00	241.00	20.00	964.00
M EXTN WIRING ASSY-BWS				1.00	207.00	20.00	165.60
M BRACKET-RR BEAM UPR MTG, LH				1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UPR MTG, RH				1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR, CTR				1.00	6.00	20.00	4.80
M BRACKET-RR BEAM LWR MTG				2.00	6.00	20.00	9.60
M BEAM-RR BUMPER				1.00	318.00	20.00	254.40
M ANTENNA ASSY-SMARTKEY				1.00	46.00	20.00	36.80
M STAY-RR BUMPER LH				1.00	65.00	20.00	52.00
M STAY-RR BUMPER RH				1.00	65.00	20.00	52.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10370/LAM WAIN SION (LAN WENSEN) Reg No/Reg Date SMM4337E / 28/06/201 Date In/Mileage 11/12/2020/ 0 Chassis No KNAF3416MK5047758 Engine No G4FGKH738725 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	10/12/2020/ 17:09	QUK	282 / Kevin Leong	25569

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BRACKET ASSY-RR BPR SIDE UPR,L	1.00	25.00	20.00	20.00
M BRACKET-ASSY RR BPR SIDE UPR,R	1.00	31.00	20.00	24.80

Steve (LKK)

00 - NH Authn  
Excess - ?  
11/12/20, 2.00pm

Estimate

By Bel sy

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm &amp; accepted by

	Nett	6,706.00
7% GST on	6706.00	469.42
<b>Total Payable</b>		<b>7,175.42</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission  
Date of Accident  
Exact Location of Accident  
Additional Location Information  
Country/State of Loss

11/12/2020 08:54 (SGT)  
10/12/2020 14:00 (SGT)  
Woodlands Ave 12, Singapore  
WOODLANDS AVENUE 12  
Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMM4337E

#### INSURED/POLICYHOLDER

Is company?  
Name Of Registered Owner  
NRIC No  
Email Address  
Mobile Phone No  
Alternative Phone No

No  
LAM WAIN SION  
SXXXX259D  
IAN.WENSEN@GMAIL.COM  
(Phone) +65-96287410  
+65-96287410

#### VEHICLE PARTICULARS

Manufacturer  
Model  
Variant  
Exact purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle?  
Vehicle Category

Kia  
Cerato  
-  
-  
Yes  
Private car

#### INSURANCE COMPANY

Name of Insurance Company  
Type of Coverage  
Fleet Policy  
Policy Number  
Cover Note Number

AIG  
Comprehensive  
No  
1900108961  
-

#### DRIVER

Name of Driver  
NRIC No  
Date Of Birth  
Occupation

LAM WAIN SION  
SXXXX259D  
08/01/1984  
Indoor

Date Of Driving Pass	10/02/2006
Driving experience	14 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96287410
Alt. Phone Number	+65-96287410
Email Address	IAN.WENSEN@GMAIL.COM
Address	53A EDGEDALE PLAINS #06-06
Address complement	-
Postcode	828693
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	LAM PO LIM
Gender	Male

#### PASSENGER 2

Name	CHEE OI CHIN
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ9G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour .....  
Vehicle Category .....  
Name of Driver .....  
Contact Number .....  
Address .....  
Address complement .....  
Postcode .....  
Insurance Company Name .....  
Nature Of Damage .....  
Details of property damaged in accident .....  
No. Of Passenger (Including Driver) .....

-  
Commercial vehicle  
LEE CHOONG HUI LEONARD  
(Phone) +65-91169113  
-  
-  
-  
-  
-  
-



# SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Was driving on the left most lane along roadlands ave 12 and  
 slowing down at the red traffic light.  
~~Suzuki~~ Suzuki van accelerated and rear ended me.  
 Refer to attached photo and front + rear video attachment for  
 car camera

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 10 Nov 2018  
 4:29

Driver's Signature

(If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: