

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

G/A / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 7/P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: XF 5209Y Yr Regn: 2019 / Sept

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Tipper TruckMake: Mitsubishi Fuso FV70H c.c 10677Colour: White A/C: Insured / Std / NI / NASp. Reading: 44812 T/Radio: Insured / Std / NI / NAEng/No: 470912C0479159C/No: FV70HJA00157Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 295/80 R 22.5R: 11 (double)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Triangle Rear YokohamaR/Bal. 5 mm R/Bal. 5/5 mmL/Bal. 5 mm L/Bal. 5/5 mmD.O.A. 17/03/2020 D.O.I. 15/12/2020Survey held at Ding Auto sin Mly

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

China Teiping ODMV 180.1KLTA 9.71KHL 170.3K

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: _____

Lump Sum / L.B.I. (\$) _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	888E

Vehicle Details

Vehicle No.:	XE5209Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Dec 2020
Vehicle Make:	MITSUBISHI
Vehicle Model:	FUSO FV70HJD2VDEA
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	470912C0479159
Chassis No.:	FV70HJA00157
Maximum Power Output:	-
Open Market Value:	\$106,030.00
Original Registration Date:	16 Sep 2019
First Registration Date:	16 Sep 2019
Transfer Count:	0
Actual ARF Paid:	\$5,302.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	15 Sep 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$12,126.00
COE Rebate Amount:	\$9,700.00
Total Rebate Amount:	\$9,700.00

The information contained herein is correct as at 04 Dec 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2020 15:43
Date Of Accident	17/03/2020 10:35
Exact Location Of Accident	SUNGEI KADUT STREET 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE5209Y
Insured/Policyholder	
Name Of Registered Owner	DOUBLE-TRANS PTE LTD
Co Reg No	1XXXXX888E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-86123163

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	MITSUBISHI FUSO FV70HJD2VDEA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSNA00005742000
Cover Note Number	

Driver

Name of Driver	GNANASEKARAN SATHEESH KUMAR
Passport No/FIN	GXXXX181Q
Date Of Birth	28/10/1982
Occupation	OUTDOOR
Date Of Driving Pass	11/07/2014
Driving Experience	5 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93895502
Fax Number	
Contact Number	

Address	4 SUNGEI KADUT STREET 2
Postcode	729226
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Is any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO. T/20200317/2122.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM123T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN WEE TAT
NRIC/Passport Number	SXXXX512E
Contact Number	93255585
Address	
Postcode	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	TAN WEE TAT (CHEN WEIDA)
Approximate Age	
Injuries Sustain	NECK PAIN
Injured person in which vehicle?	SLM123T
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 


Driver's Signature
(If driver is not the policyholder)
Date & Time: 18/03/2020
14.55 hrs.


Reporting Centre Personnel's Signature
Name: Teo Hong Eng
NRIC/FIN No.: 5110007212

Certificate of Insurance Pg. 1



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Motor Commercial

MZ300/C

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1950
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

N SN

BR0057A

Cov. Type:C

CERTIFICATE No. DMCVSNA00005742000

Engine No.: 470912C0479159

Cha. No.: FV70HJA00157

1. Index Mark and Registration Number of Vehicle XE5209Y

2. Name of Policy Holder DOUBLE-TRANS PTE LTD

3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment 01/01/2020

Excess Sect I. SS1,500.00
EX ON WINDSCREEN. SS100.00

4. Date of Expiry of Insurance 31/12/2020

5. Persons or Classes of Persons entitled to drive*
Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

陳保險經紀私營有限公司
TAN INSURANCE BROKERS PTE LTD
3A/5A Alilwal Street, Chenn Leonn Building
Singapore 199896
www.tib.com.sg
Tel: (65) 6742 6766 Fax: (65) 6742 6669

6. Limitations as to use:

- (1) Use in connection with the Policyholder's business.
- (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
- (3) Use for social, domestic or pleasure purposes.

The Policy does not cover

- (1) Use for hire or reward or racing, pace-making, reliability trial or speed testing.
- (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

HIRE PURCHASE CO. : MAYBANK AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: Lim Lee Choo
Authorised Officer

Authorised Signatory



**SINGAPORE
POLICE FORCE**



T/20200317/2122

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

1 of 3

Report No. T/20200317/2122

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/03/2020 18:05		Vide Report No.: L/20200317/0060		Station Diary No.: 84	
Informant's Particulars					
Name of Informant: GNANASEKARAN SATHEESH KUMAR			Address: APT BLK 246 YISHUN AVENUE 9 #06-263 YISHUN SUNSHINE SINGAPORE 760246		
ID Type / ID No.: FIN NO / G0220181Q			Contact No.: Home/Office: Mobile: 93895502		
Nationality: INDIAN			Email:		
Sex: Male	Age: 37	Date of Birth: 28/10/1982	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: CONSTRUCTION DRIVER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/03/2020 10:35	Type of Location: Straight Road
Location: Along Road 1 SUNGEI KADUT STREET 1				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLM123T	Car				Slightly Damaged	0
XE5209Y	Lorry				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20200317/2122

2 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20200317/2122

CONTINUATION OF REPORT

Driver			
Name	TAN WEE TAT (CHEN WEIDA)		ID No. S7920512E
Related Vehicle	SLM123T (Car)		Contact No. 93255585
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	GNANASEKARAN SATHEESH KUMAR		ID No. G0220181Q
Related Vehicle	XE5209Y (Lorry)		Contact No. 93895502
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17/03/2020 at about 1035hrs, I was driving my lorry (registration plate: XE5209Y) along Sungei Kadut St 1. A car ahead of me (registration plate: SLM123T) made a stop and I had to apply e-brake. However, as it was too sudden, I was not able to stop in time and collided into his rear part of the car.

There was some damage on the rear part of his car as well as damage to my lorry front area. The said driver complained neck pain hence he was conveyed to hospital by ambulance. Traffic police was also at scene (reference L/20200317/0060). I am not injured.

My lorry has an in-car camera but there was no memory card inserted at that point of time.

DING AUTO PTE LTD

Blk 176 #04-06

Sin Ming Drive (Sin Ming Autocare)

Singapore 575721

Tel: 92313123

Fax: 6452 0614

Vehicle: XE5209Y

Model: MITSUBISHI FUSO FV70HJD2VDEA

Chassis: FV70HJA00157

NO	DESCRIPTION	QTY	UNIT COST PRICE	COST PRICE	SURVEYORS MARKING
1	FRONT GRILL BASE <i>ren</i>	1	\$ 510.00	\$ 510.00	X
2	FRONT GRILL LOWER BASE <i>st.</i>	1	\$ 135.00	\$ 135.00	X
3	FRONT BUMPER <i>st.</i>	1	\$ 2,250.00	\$ 2,250.00	X
4	FRONT BUMPER HOOK COVER <i>damaged / missing</i>	1	\$ 115.00	\$ 230.00	X
5	FRONT BUMPER CENTRE GARNISH <i>st.</i>	1	\$ 350.00	\$ 350.00	X
6	HEAD LAMP LHS <i>broken</i>	1	\$ 720.00	\$ 720.00	X
7	HEAD LAMP RHS <i>st.</i>	1	\$ 720.00	\$ 720.00	X
8	HEAD LAMP COVER OUTER LHS <i>crack</i>	1	\$ 260.00	\$ 260.00	X
9	HEAD LAMP COVER OUTER RHS <i>st.</i>	1	\$ 260.00	\$ 260.00	X
10	SIDE STEP RHS <i>st.</i>	1	\$ 240.00	\$ 240.00	X
11	SIDE STEP LHS <i>st.</i>	1	\$ 240.00	\$ 240.00	X
12	RADIATOR <i>st.</i>	1	\$ 4,150.00	\$ 4,150.00	X
TOTAL:				\$ 10,065.00	

	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
1				
2				
3				
	SPECIAL NETT		\$ -	

	LABOUR	PRICE	SURVEYOR MARKING
1	PANEL BEAT- ACCIDENT AREA	\$ 1,500.00	750/-
2	SPRAY PAINT- FRONT BUMPER, FRONT UPPER AND LOWER GRILL, SERVICE DOOR, SIDE STEP X2	\$ 1,500.00	800/-
3	RUST PROOFING	\$ 60.00	40/-
4	REPAIR/CHECK WIRING	\$ 120.00	40/-
5	ALIGN HEADLAMP AND ALL FRONT ACCIDENT AREA	\$ 120.00	30/-
	TOTAL:	\$ 3,300.00	

PARTS	\$ 10,065.00	
LABOUR	\$ 3,300.00	
SPECIAL NETT	\$ -	
TOTAL	\$ 13,365.00	
GST 7%	\$ 935.55	
FINAL TOTAL	\$ 14,300.55	

15/12/22 @ 1400hrs

Not Antimed
Part by Part. 6 days.

Excess \$1500/-

T you

LKK Auto 97237799



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: