

NAME

Naz

REF

AIG

LKE

ASSIGNMENT

File No.

Date:

Refused Case

ACT / TRANSIT RES / QO RES / EVA / INV / MV

Inspected Vehicle No:

Workshop No:

Ref:

Ref:

Ref:

Ref:

Excess:

Ref:

Ref:

Ref:

When the vehicle commenced its
journey at the time of inspection.

☒	☒
N/S	O/S
☒	☒

Ref:

Ref:

Condition? Yes or No

Ref:

Condition? Yes or No

Ref:

3

days

Res: Yes or No

Ref:

1

Val: Yes or No

CA / REV / REP / 24 HRS

Ref: Person Contained

Vehicle IN/OUT

Ref: Action / Instruction

Veh No:

SHC 3153L

Yr Regn 30 OCT 2019

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover /

Truck / Trolley or

Make:

HYUNDAI IONIQ 4.3

cc 1,580

Colour

BLUE

AVC: Insured / Not Insured

Sp Reading

73, 751

TRADP: Insured / Not Insured

Engine

CIN:

KMHC851CVLUI87625

Gen. Cond. Good / Fair / Poor / Burnt

Steering: (border) / Jammed / Locked / Burnt or

Brake: (border) / Jammed / Locked / Burnt or

Wash: W / S / Rim / STD / VRim or

Tyre Size:

195/65 R15

R:

11

US / SUN / EXH / OVA / GY / PS / LZA / M / C / H / S / U / R / S / U / W

WYO / YOKO or

WESTLAKE

Ref:

Ref:

5

mm

Ref:

Ref:

6

Ref:

5

mm

Ref:

Ref:

6

Ref:

11/12/2020

Ref:

11/12/2020

Survey Hold at

CDGE LOYANG

Doc. of Damages: Frl / Rear / O/S / N/S / U/C / Hood/Top or

REAR, N/S REAR

The U/C / Chassis frame / Body Structure affected due to

PLP

Days of Repair:

☐

Prdn. Report

☐

File of Report

Days of Repair:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transporter

Days of Repair:

Add Fee:

☐

Site Insp

15

☐

Interview

15

☐

Tech. Insp

15

☐

Weekend

15

Days of Repair:

Days of Repair: