

Our Ref : 305438407

Date : 11/12/20

Time of Fax : _____

Via Fax : Bman

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshop

Your Insured : SGT4858C

Date of Acc : 10/12/20

* 8 pages

Attn : Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SH7163A

Loyang
59 Loyang Drive
Singapore 508969

1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.

2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

3 Enclosed, please find :

- I) Our initial estimate of repairs of the damaged vehicle.
- II) Accident report made by our client.

4 I would appreciate it if you could call us to arrange for the survey of the vehicle

→ Lim Kwok Eng, Tel no. 62148355 or Hp no. 98240811
Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305
Lim Tien Siong Tel no. 62148398 or Hp no. 96358546
Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006
Fauzy Bin Mokhtar Tel no: 62148319 or Hp no : 81259176
Larry Ng Tel: 6214 8316

5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.

6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

7 Thank you.

Yours faithfully



for Vice President
Crash Repairs & Claims Recovery

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305438407
 REGN NO : SH 7163A
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 30.04.2019
 DATE/TIME IN : 10.12.2020 21:00
 ACCIDENT DATE : 10.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0003 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1 L	451.25	20.00	361.00
0004 04-01-0104-2532-G	IONIQVC BRACKET ASSY-RR B	1 L	55.80	20.00	44.64
0005 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	180.00	2.00-	180.00
0006 04-01-0104-0852-G	IONIQVC REFLECTOR/REFLEX	1 L	41.45	20.00	33.16

SUB-TOTAL : 1,003.92

JOB NATURE

0000 23-01	TOWING FEE	60.00
0001 L	PANEL BEATING	500.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	450.00
0003 20-22	REMOVE/REFIX REVERSE SENSOR	120.00

SUB-TOTAL : 1,130.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 11.12.2020

Time: 17:24:28

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438407
REGN NO : SH 7163A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 30.04.2019
DATE/TIME IN : 10.12.2020 21:0
ACCIDENT DATE : 10.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,133.92

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :