



CYCLE & CARRIAGE

AIG-OD CLAIM
SURVEY: 14/12/20
LKL - STEVE

VEHICLE NO : SMN 5700C

MODEL : MIT/OUTLANDER 2.0

WIP : 60679

Material	:	\$	<u>6,662.18</u>
Labour	:	\$	<u>3,400.00</u>
Sub-Total	:	\$	<u>10,062.18</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>9,762.18</u>
GST 7%	:	\$	<u>683.35</u>
Grand Total	:	\$	<u>10,445.53</u>
Finalise By/Date : <u>Larry on 29/12/20</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 07 WORKING DAYS + 2 days (wk. end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11886/LAM SZE JIA (LAN SIJIA) Reg No/Reg Date SMN5700C / 19/08/2019 Date In/Mileage 12/12/2020/ 16910 Chassis/Package GF7W0601876 /DC17P(F) Engine No 4J11BH4181 Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK
14/12/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	29/12/2020/ 15:40	BLK	884 / Lauro Songcuan	60679

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER, BONNET, FRONT RH FENDER & AFFECTED AREAS				1350.00 ✓
E PNT98000 SPRAY PAINT ON FRONT BUMPER, BONNET, FRONT RH FENDER & FRONT RH DOOR				1400.00 ✓
E PNT88000 REMOVE & INSTALL FRONT PARKING ASSIST				120.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED PORTIONS				40.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY APPLY ZERTONA COATING ON AFFECTED AREAS				320.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
X EXC INSURANCE EXCESS				-300.00
X HEADLAMP ASSY,RH ✓	1.00	1938.00	23.00	1492.26 ✓
X LAMP ASSY,FOG,FR RH ✓	1.00	348.00	23.00	267.96 ✓
X GARNISH,FR BUMPER,RH ✓	1.00	48.00	23.00	36.96 ✓
X BRACKET,FR BUMPER SIDE,RH ✓	1.00	18.00	23.00	13.86 ✓
X EXTENSION,FR BUMPER ?	1.00	515.00	23.00	396.55 ?
X GARNISH,FR BUMPER SIDE ✓	1.00	220.00	23.00	169.40 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	112.00	23.00	86.24 ✓
X HOOD ✓	1.00	975.00	23.00	750.75 ✓
X FENDER,FR RH ✓	1.00	688.00	23.00	529.76 ✓
X MOULDING,FR BUMPER,RH ✓	1.00	116.00	23.00	89.32 ✓
X MOULDING,FR WHEEL ARCH,RH ?	1.00	160.00	23.00	123.20 ?
X BODY KIT, OUTLANDER	1.00	1554.00	00.00	1554.00 X
X FACE,FR BUMPER	1.00	859.00	23.00	661.43 X
X COVER,FR BUMPER	1.00	359.00	23.00	276.43 X

Supp

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE****THIS IS NOT AN OFFICIAL TAX INVOICE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 14/12/2020	Cust No/Name	KCV11886/LAM SZE JIA (LAN SIJIA)
	Reg No/Reg Date	SMN5700C / 19/08/2019
	Date In/Mileage	12/12/2020/ 16910
	Chassis/Package	GF7W0601876 /DC17P(F)
	Engine No	4J11BH4181
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	29/12/2020/ 15:40	BLK	884 / Lauro Songcuan	60679

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X GARNISH,FR BUMPER SIDE	1.00	48.00	23.00	36.96
X RIVET,FR BUMPER	6.00	5.00	23.00	23.10
X TANK,WINDSHIELD WASHER	1.00	86.00	23.00	66.22
X SENSOR,W/SHLD WASHER TANK	1.00	114.00	23.00	87.78

Z TEXT

OD CLAIM - AIG

DOA: 10.12.2020

SURVEY: STEVE (LKK) 14/12/2020

07 DAYS

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	6,662.18	Nett	9,762.18
Labour	3,020.00	7% GST on	683.35
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	10,445.53
Sundry/Others	80.00		
Total(w/o GST)	9,762.18		

This is not an official tax invoice.

This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMN 5700 C

<u>Materials</u>		<u>Cost \$</u>	
1	Face, FR Bumper	859.00	/ BR
2	Cover, FR Bumper	359.00	/ BR
3	Garnish, FR Bumper Side	48.00	/ CUT
4	Rivet, FR Bumper (6 pcs)	30.00	/ nec
5	Tank, Windshield Washer	86.00	/ CRU
6	Sensor, W/Shld Washer Tank	114.00	/ BR
		<u>1,496.00</u>	
23% Discount		<u>344.08</u>	
		<u>1,151.92</u>	
7	Body Kit, Outlander	1,554.00	/ CUT
		<u>2,705.92</u>	
7% GST		<u>189.41</u>	
Total		<u>2,895.33</u>	

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SPIN 5700 CWIP: 60679

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	FR bumper cover	? / SUPP		BR	6400K 147
2	COVER, FR BUMPER	? / SUPP		(Black) BR	6400J 294
3	GRANISH, FR BUMPER SIDE RH	? / SUPP		(brown) BR	6407A 142
4	RIVET, FR BUMPER X(6)	? / SUPP		BR	
5	MOUNTING, FR WHEEL ARCH, RH	? / SUPP		ORC	8260A 2403
6	TANK, WINDSHIELD WASHER	? / SUPP		CRN	Store 18/10/20
7	Body kit	? / SUPP		CHT	
8	EXTENSION, FR BUMPER	(?) SUPP		(Silver) CHT	
9	SENSOR, WINDSHIELD WASHER TANK	? / SUPP		BR	8260A 406
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	18/12/20	Store
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Outlander 2.0SURVEYOR: Store - Wk

SMN 5700 C

All DTCs

Diagnostic Check before erase all DTC

2020.12.21

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GFTW 2019MY

All DTCs

2020.12.21

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MPI/GDI/DIESEL	GAS_0E640000		No DTCs		
Auto Stop & Go (AS&G)	ASG_25080000	P1617	Battery Voltage Low During Idle Stop	Active	
AT/CVT/A-MT/T-C-SST	CVT_14080300		No DTCs		
AUTO CRUISE	GAS_0E640000		Non-target System		
4WS/Electric Power Steering	EPS_45880040		No DTCs		
ABS/ASC/ASTC/MSS	ASC_4208000F		No DTCs		
SRS-AIR BAG	ORC_81047302		No DTCs		
Air Conditioner	AC_80080011	U0184	AUDIO CAN timeout	Active	
ETACS	ETACS_83040801	U0184	AUDIO CAN timeout	Active	
Meter	MTR_84084001	U0184	AUDIO CAN timeout	Active	
Steering Angle Sensor	GS_SAS_47000100		Non-target System		
AND	AND_8C080002		Non-equipped System or Communication Error		
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		
LIN	ETACS_83040801		Non-target System		
Power Gate	ETG_92080000	U0184	AUDIO CAN timeout	Active	

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
KOS/IMMO/Keyless	KOS_8A880020	U0184	AUDIO CAN timeout	Active	
OSS	OSS_9588000B	U0184	AUDIO CAN timeout	Active	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSCFCM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
EPB	EPB_4C080000	C2253	EPB SW malfunction	Stored	
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		

SMN 5700C

All DTCs Diagnostic Check after erase all DTC

2020.12.21

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MPI/GDI/DIESEL	GAS_0E640000		No DTCs		
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs		
AT/CVT/A-MT/C-SST	CVT_14080300		No DTCs		
AUTO CRUISE	GAS_0E640000		Non-target System		
4WS/Electric Power Steering	EPS_45880040		No DTCs		
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs		
SRS-AIR BAG	ORC_81047302		No DTCs		
Air Conditioner	AC_80080011		No DTCs		
ETACS	ETACS_83040801		No DTCs		
Meter	MTR_84084001		No DTCs		
Steering Angle Sensor	GS_SAS_47000100		Non-target System		
AND	AND_8C080002		Non-equipped System or Communication Error		
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		
LIN	ETACS_83040801		Non-target System		
Power Gate	ETG_92080000	U0184	AUDIO CAN timeout	Active	

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSCFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	