

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 30548937
Date : 14/12/2020
Time of Fax: _____

Via Fax : Email
Your Insured: SFY 1315H
Date of Acc : 13/12/2020

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH D 3286 G

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident _

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

♦ Lim Kwok Eng	Tel: 6214 8316 or HP: 9824 0811	} Fax no. 6546 8156
♦ Juman Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	
♦ Larry Ng Nyuk Phin	Tel: 6214 8315 or HP: 9230 2824	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

for Vice President
Crash Repairs & Claims Recovery

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Arg Asia

Date: 14.12.2020

Time: 13:16:05

Page: 1

12 IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438937
REGN NO : SHD3286G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.07.2016
DATE/TIME IN : 14.12.2020 09:45
ACCIDENT DATE : 13.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76
0002 04-01-0103-0637-G	FRT BUMPER UPR BRKT LH	1	22.40	20.00	17.92
0003 04-01-0103-0639-G	FRT BUMPER SIDE BRKT LH	1	24.60	20.00	19.68
0004 04-01-0103-0574-A	FRT FENDER LH	1	663.00	20.00	530.40
0005 04-01-0103-0781-A	HEADLAMP LH	1	1,800.00	20.00	1,440.00

SUB-TOTAL : 2,849.76

JOB NATURE

0000 20-05	FRT FENDER ADV.STICKER LH	100.00
0001 PB	PANEL BEATING	600.00
0002 SP	SPRAYPAINT CHARGE	500.00
0003 17-01	CHECK ALL LIGHTING	40.00
0004 20-00	TUFF COAT ON AFFECTED PARTS.	40.00

SUB-TOTAL : 1,280.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 14.12.2020

REPAIR ESTIMATE

Arg Asia

Time: 13:16:05

Page: 2/2 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438937
REGN NO : SHD3286G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.07.2016
DATE/TIME IN : 14.12.2020 09:45
ACCIDENT DATE : 13.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Cmf

TOTAL : 4,129.76

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :