

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 14.12.2020
Time: 13:16:05
Page: 1

Arg Asia

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438937
REGN NO : SHD3286G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.07.2016
DATE/TIME IN : 14.12.2020 09:45
ACCIDENT DATE : 13.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A FRT BUMPER *de* 1 1,052.20 20.00 841.76
0002 04-01-0103-0637-G FRT BUMPER UPR BRKT LH *? x su* 1 22.40 20.00 17.92
0003 04-01-0103-0639-G FRT BUMPER SIDE BRKT LH *? x su* 1 24.60 20.00 19.68
0004 04-01-0103-0574-A FRT FENDER LH *Repair* 1 663.00 20.00 530.40
0005 04-01-0103-0781-A HEADLAMP LH *? x su* 1 1,800.00 20.00 1,440.00

841.76

SUB-TOTAL : 2,849.76

JOB NATURE

0000 20-05 FRT FENDER ADV.STICKER LH *re* 100.00 ✓
0001 PB PANEL BEATING ~~600.00~~ 280
0002 SP SPRAYPAINT CHARGE ~~500.00~~ 200
0003 17-01 CHECK ALL LIGHTING ~~40.00~~ ? 30 x su
0004 20-00 TUFF COAT ON AFFECTED PARTS. 40.00

580

SUB-TOTAL : 1,280.00

841.76

580.00

1421.76

20%

1137.40

43-1,150

3 days

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 14.12.2020

Time: 13:16:05

Page: 2/2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438937
REGN NO : SHD3286G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.07.2016
DATE/TIME IN : 14.12.2020 09:45
ACCIDENT DATE : 13.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 4,129.76

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068
3 days
4/3
14/12/2020 PM 20
Resue after repair