

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 11.12.2020
 Emailed : 28.12.2020, 2.30pm
 Date Survey : 14.12.2020

VEHICLE NO : SGC 9002 L
 MODEL : KIA CERATO 1.6 A
 WIP : 25728

Material	:	\$	<u>3,631.20</u>
Labour	:	\$	<u>3,140.00</u>
Sub-Total	:	\$	<u>6,771.20</u>
	:		<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>6,471.20</u>
GST 7%	:	\$	<u>452.98</u>
Grand Total	:	\$	<u>6,924.18</u>
Finalise By/Date	:		<u>LOI / 28/12/2020</u>

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12216/Mr LIN Reg No/Reg Date SGC9002L# / 17/03/2020 Date In/Mileage 14/12/2020/ 3284 Chassis/Package KNAF5416ML5063955 Engine No G4FGKH741133 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK
14/12/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	28/12/2020/ 12:00	BLC	260 / AiTing	25728			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE RH FRONT FENDER, RH FRONT DOOR, REPAIR RH SIDE SKIRT, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 800.00
E PNT98000 RESPRAY ON RH FRONT FENDER, RH FRONT DOOR, RH SIDE SILL, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1050.00
E PNT88000 REMOVE & INSTALL RH FRONT DOOR TRIMS AND GLASS TO FACILITATE REPAIR								✓ 180.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment								✓ 120.00
M SUNDRY APPLY SEALANT ON ACCIDENT PORTIONS								✓ 40.00
A 90000001 REPLACE RH FRONT UNDERCARRIAGE PARTS								✓ 400.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								✓ 30.00
E PNT98000 RESPRAY ON RH REAR DOOR → Supp.								350.00
X EXC EXCESS FOR OWN DAMAGE CLAIM								-300.00
X PANEL-FENDER,RH					1.00	✓ 430.00	20.00	344.00
X INSULATOR-FENDER RH					1.00	✓ 27.00	20.00	21.60
X PANEL ASSY-FRONT DOOR,RH					1.00	✓ 1277.00	20.00	1021.60
X MOULDING ASSY-FRT DR FRAME,RH					1.00	✓ 72.00	20.00	57.60
X WHEEL ASSY-ALUMINIUM					1.00	✓ 926.00	20.00	740.80

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 14/12/2020	Cust No/Name LCV12216/Mr LIN Reg No/Reg Date SGC9002L# / 17/03/2020 Date In/Mileage 14/12/2020/ 3284 Chassis/Package KNAF5416ML5063955 Engine No G4FGKH741133 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/12/2020/ 12:00	BLC	260 / AiTing	25728

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BLACK TAPE-FR DR RR,RH	1.00	✓ 13.00	20.00	10.40
X MIRROR ASSY-OUTSIDE RR VIEW,RH	1.00	? 559.00	20.00	447.20
X ARM COMPLETE-FR LWR,RH	1.00	? 286.00	20.00	228.80
X W/STRIP ASSY-FR DR BELT O/S RH	1.00	80.00	20.00	64.00
X W/STRIP ASSY-RR DR BELT O/S RH	1.00	75.00	20.00	60.00
X CLIP-SIDE GARNISH MTG	12.00	2.00	20.00	19.20
X GEAR ASSY-STEERING	1.00	770.00	20.00	616.00

Z TEXT

AIG OD CLAIM

DOA : 11.12.20

SURVEYOR STEVE 14.12.20

POLICY NO : 2070050499

REPAIR 05 DAYS

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,631.20	Nett	6,471.20
Labour	3,050.00	7% GST on	452.98
Standard Menu	0.00		
Specialist Job	30.00	Total Payable	6,924.18
Diagnostics Job	0.00		
Sundry/Others	-240.00		
Total(w/o GST)	6,471.20		

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SGC 9002 L**

<u>Materials</u>		<u>Cost (\$)</u>	
1	W/strip assy-Fr dr belt O/S RH	80.00	✓ BT
2	W/strip assy-RR dr belt O/S RH	75.00	✓ BT
3	Clips (x12)	24.00	✓ nrc
4	Gear Asst-steering	770.00	✓ BT

Total Materials		949.00	
Less 20% discount		189.80	

Total after discount		759.20	


<u>Labour</u>		<u>Cost (\$)</u>	
1	Respray on RH rear door	350.00	✓

Total labour		350.00	
Total amount		1,109.20	
7% GST		77.64	

Grand total		<u>\$ 1,186.84</u>	

Thank You.

Yours faithfully



LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

HOME
 Online

CERATO/FORTE../2020/G 1.6 MPI..

VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

ICU
 CLU
 WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0235	VCI Ver.	02.48
ECU Ver.	M-E-K-01-00-0176	OS Ver.	Android 10

Work Order: R001284
 License: sgc 9002 I
 Technician: kfs 810119
 Mileage: 3519
 Date: 22.12.20 11:32

KIA CERATO 1.6 2019

Front : Left

Actual	Before	Specified Range
-0°26'	-0°11'	-0°53' 0°07'
4°21'	4°16'	4°00' 5°00'
0°01'	-0°05'*	-0°03' 0°09'
8°41'*	8°53'*	13°30' 14°30'
8°15'*	8°42'*	12°37' 14°37'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°23'	-0°38'	-0°53' 0°07'
4°57'	5°00'	4°00' 5°00'
0°02'	-0°02'	-0°03' 0°09'
8°05'*	9°49'*	13°30' 14°30'
7°42'*	9°11'*	12°37' 14°37'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°03'	0°27'	
-0°37'	-0°44'	
0°36'	-0°56'	
0°02'	-0°07'*	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°07'	-0°53'	-1°42' -0°42'
0°05'	0°05'	-0°02' 0°16'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°30'	-1°44'*	-1°42' -0°42'
0°08'	0°08'	-0°02' 0°16'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°23'	0°51'	
0°13'	0°14'	-0°04' 0°32'
-0°02'	-0°02'	

* This value is not within specification. Tire wear, handling and safety problems may result.