





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12216/Mr LIN Reg No/Reg Date SGC9002L# / 17/03/202 Date In/Mileage / 0 Chassis No KNAF5416ML5063955 Engine No G4FGKH741133 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	14/12/2020/ 10:44	BLC	442 / CocoLu	25728		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							800 1200.00
RENEW FRT FENDER RH, FRT DOOR RH, REPAIR SIDE SKIRT RH, REAR FENDER RH							1050 1400.00
E PNT98000							180.00
SPRAY PAINT FOR FRT FENDER RH, FRT DOOR RH, SIDE SILL RH, REAR FENDER RH							120.00
E PNT88000							40.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS							30.00
B WHEELALIGNMENT							400.00
To Conduct Computerize Full Wheel Alignment							30.00
M SUNDRY							400.00
APPLY SEALANT FOR ACCIDENT PORTION							30.00
M SUNDRY							400.00
TRANSFER FRT RIGHT RIM							30.00
A 90000001							120.00
RENEW FRT UNDER CARRIAGE							20.00
A 90000001							400.00
CHECK WIRING & ELECTRICAL SYSTEM							30.00
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							20.00
M SUNDRY							400.00
Sundry							400.00
M PANEL-FENDER,RH				1.00	430.00	20.00	344.00
M INSULATOR-FENDER RH				1.00	27.00	20.00	21.60
M PANEL ASSY-FRONT DOOR,RH				1.00	1277.00	20.00	1021.60
M MOULDING ASSY-FRT DR FRAME,RH				1.00	72.00	20.00	57.60
M WHEEL ASSY-ALUMINIUM				1.00	926.00	20.00	740.80
M BLACK TAPE-FR DR RR,RH				1.00	13.00	20.00	10.40
M MIRROR ASSY-OUTSIDE RR VIEW,RH				1.00	559.00	20.00	447.20
M GUARD ASSY-FRONT WHEEL,RH				1.00	95.00	20.00	76.00
M STRUT ASSY-FR,RH				1.00	280.00	20.00	224.00
M BEARING-STRUT				1.00	86.00	20.00	68.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12216/Mr LIN Reg No/Reg Date SGC9002L# / 17/03/202 Date In/Mileage / 0 Chassis No KNAF5416ML5063955 Engine No G4FGKH741133 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	14/12/2020/ 10:44	BLC	442 / CocoLu	25728

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M HUB ASSY-FR WHEEL	1.00	436.00	20.00	348.80
M ARM COMPLETE-FR LWR,RH	1.00	286.00	20.00	228.80
M STAY RH	1.00	22.00	20.00	17.60

Estimate

14/12/20, 11:00am

Steve CLKK)

OD- NM Auth

Excess - ?

5 dys

P/P

By Bel Jy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm &amp; accepted by

Date:

	Nett	7,147.20
7% GST on	7147.20	500.30
<b>Total Payable</b>		<b>7,647.50</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	14/12/2020 13:02 (SGT)
Date of Accident	11/12/2020 18:20 (SGT)
Exact Location of Accident	Jurong West Street 93, Singapore
Additional Location Information	ALONG JURONG WEST STREET 93 AT CALTEX EXIT JUNCTION BOX
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGC9002L
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	LIN JINGQUAN
NRIC No	SXXXX152F
Email Address	WHATCHUPJQ@GMAIL.COM
Mobile Phone No	(Phone) +65-91544311
Alternative Phone No	+65-91544311

## VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

## INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070050499
Cover Note Number	-

## DRIVER

Name of Driver	LIN JINGQUAN
NRIC No	SXXXX152F
Date Of Birth	22/05/1990



Driving Pass  
experience  
der  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s)  
soliciting/offering accident claims assistance?

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Police Station Name  
Police Station Phone No  
Alt. Police Station Phone No  
Police Station Address  
Was notice of intended Prosecution given?  
If yes, against whom?

#### CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT  
COLLISION-HEAD TO SIDE

#### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?  
Was there any audio recorded?

Indoor  
15/11/2012  
8 YEARS AND 1 MONTH  
Male  
(Phone) +65-91544311  
+65-91544311  
WHATCHUPJQ@GMAIL.COM  
BLK 666B JURONG WEST STREET 65 #11-205  
-  
642666  
Yes  
-  
No  
-  
-

Collision - Head to Rear  
Clear  
Dry

No  
2  
Yes  
Yes  
Yes  
1  
No

Yes  
Jurong Neighbourhood Police Post  
(Phone) +65-18002659999  
(Fax) +65-62664987  
Blk 158 Yung Loh Road #01-58 Singapore 610158  
No  
-

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category

FZ4209G  
-  
-  
-  
-  
Motorcycle

Driver  
 Number  
 Address complement  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 Details of property damaged in accident  
 No. Of Passenger (Including Driver)

## INJURED PERSONS DETAILS

### INJURED 1

Name of injured person  
 Address  
 Address Complement  
 Post Code  
 Approximate Age Years Old  
 Injuries Sustained  
 Injured person in which vehicle?  
 Were seat belts worn?  
 Was this injured conveyed to hospital by ambulance?

FZ4209G  
 No  
 Yes



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 14/12/2020

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

PLAN




**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

I just finish car wash from Coltex along Jurong West Street 93. and was about to exit the petrol station by turning ~~to~~ right. After checking right then left then right, I proceed to move into the yellow junction box after ensuring there was no incoming vehicle from the right.


Once in the yellow junction box, i checked the left side and saw incoming vehicle, hence stopped, while i was still looking left, then i heard a horn & a vehicle impacted my vehicle on the right.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Police Station Of Origin:  
Jurong NPP  
158 Yung Loh Road #01-58 SINGAPORE  
610158  
Tel No: 1800-2659999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made:  
11/12/2020 20 52

Vide Report No.:  
J/20201211/0130

Station Diary No.:  
34

**Informant's Particulars**

Name of Informant:  
LIN JINGQUAN

Address:  
APT BLK 666B JURONG WEST STREET 65 #11-205  
SINGAPORE 642666

ID Type / ID No.:  
NRIC NO / S 152F

Contact No.:  
Home/Office: Mobile: 91544311

Nationality:  
SINGAPORE CITIZEN

Email:

Sex: Age: Date of Birth:  
Male 30 22/05/1990

Type of Informant:  
Passenger

Institution / School Name:

Race:  
Chinese

Language:

Occupation:  
Sales Executive

Driving Licence Information:  
Class: 3 Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 11/12/2020 18:20	Type of Location: Straight Road
Location: JURONG WEST STREET 93				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FZ4209G	Motorcycle				Slightly Damaged	0
SGC9002L	Car				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No  
No. of Pedestrians Injured: NIL  
Use of Pedestrian Crossing: NA



# SINGAPORE POLICE FORCE



T/20201211/2128

2 of 3

Report No. T/20201211/2128

Police Station Of Origin:  
Jurong NPP  
158 Yung Loh Road #01-58 SINGAPORE  
610158  
Tel No: 1800-2659999

## CONTINUATION OF REPORT

Passenger			ID No.	S 152F
Name	LIN JINGQUAN		Contact No.	91544311
Related Vehicle	SGC9002L (Car)		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Hospital/Clinic	NIL		Date Discharge	NIL
Date Treatment	NIL		Degree of Injury	NIL
No. of Days granted Medical Leave	NIL			

### Brief Details.

On the 11/12/2020 at about 1820hrs, I brought my car SGC9002L for carwash at the Caltex located at Jurong West St 93. After the carwash, I proceeded to exit the Caltex. I have checked my right and left side incoming vehicle before inching forward. As there was no oncoming vehicle, I moved forward into the yellow box. As I was in the yellow box, I slowly drive forward while looking at the left side of the road for on coming vehicle. Suddenly I heard a loud horn from the right side and by the time I turn to my right to take a look, motorbike FZ4209C had collided onto my front driver side door. I quickly came out to take a look and a bystander called for ambulance. Traffic police also arrived at scene. The rider was conveyed by ambulance in groggy state. Traffic police took the SD card to my Car camera for investigations. I am unsure of the repair cost for my vehicle. Vide J/20201211/0130 under TP IO Rahim



**SINGAPORE  
POLICE FORCE**



T/20201211/2128

3 of 3

Report No. T/20201211/2128

Police Station Of Origin:  
Jurong NPP  
158 Yung Loh Road #01-58 SINGAPORE  
610158  
Tel No: 1800-2659999

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Staff Sgt TAMILLMAARAN S/O LETCHMANAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

11/12/2020 20:52

Officer In Charge Of Case:

TP / GIT /

Staff Sgt SYED MUHAMMAD ISA BIN OMAR

ALHABSHEE

Contact No.: 65476214

Classification Of Case:

Authentication Stamp

NP168

Singapore Police Force

# PROTECTOR PRIVATE VEHICLE

Policyholder  
No. of Insurance  
No.  
Chassis No.

: LIN JINGQUAN  
: 17 Mar 2020 To 16 Mar 2022  
: G4FGKH741133  
: KNAF5416ML5063955

Vehicle No. : SGC9002L  
Policy No. : 2070050499  
Endorsement No. :  
Issued Date : 24 Mar 2020

## ABOUT THE COVER

Make/Model : KIA Cerato  
Engine Capacity/Tonnage : 1,591.00 CC  
Driver Restriction : NA  
Sum Insured : Market Value  
Off Peak Car : No  
First Year of Registration : 2020  
Insuring with COE/PARF : Yes

### Person or Classes of Persons Entitled to Drive\* :

- a) The Policyholder
- b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.  
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

## EXCESS

Section 1  
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2  
Property Damage - \$0

Windscreen : \$100

### Named Driver and Excess (where applicable)

LIN JINGQUAN - \$600 (Own Damage), \$600 (Flood Cover)

## APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

## IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504671242  
CYCLE & CARRIAGE - ERNEST

239 ALEXANDRA ROAD  
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**

This computer generated document does not require a signature.

SSCNMD

1003133850/AC4/Doc4