

ASS. REC. BY:

Stere 7

REF:

AIG

CS/AIG20013780/Eqf3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 1900160447

Claims No. 0608321067SG


Sum Insured: \_\_\_\_\_ Excess: 0/-

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Cum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMP 1326R

Yr Regn: 12/9/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Cerato

c.c 1591

Colour: Black

A/C: Insured / Std / NI / N

Sp. Reading: 9038

T/Radio: Insured / Std / NI / N

Eng/No: \_\_\_\_\_

C/No: KNAF3416 MK5049 719

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 13/12/20

D.O.A. 14/12/20

Survey held at Cycle &amp; Carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt RH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MK-70K

14/12/20@5.09pm revert to AIG via Merimen.

15/12/20@11.52am Kok Chong informed C/A via Merimen.

15/12/20@11.56am Informed Don C/A &amp; ex:\$0/- by email.

29/12/20@3.02pm confirmed with Ms Loi final fig \$5010.40, 6 days (Red \$3909.60, 44%)

a/Time, File, Pass to?



: Prell. Report



: Final Report

b/Time, File Return to?

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (%)



: Weekend (%)

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

c/Forms:

MER-OD

d/Sum I.E.P. to:

5010.40



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11102/WEE ZHI CONG (HUANG ZHICONG)
	Reg No/Reg Date	SMP1326R / 12/09/201
	Date In/Mileage	/ 9038
	Chassis No	KNAF3416MK5040719
	Engine No	G4FGJH720482
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	14/12/2020/ 14:36	QUD	247 / DonBong	25767		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE, 400 X 2 RH FRONT FENDER, RH FRONT DOOR, RH SIDE MIRROR, REPAIR RH REAR DOOR							800 2000.00
E PNT88000 LABOUR TRANSFER RH FRONT DOOR GLASS, DOOR MECHANISM, DOOR TRIM AND OTHER ATTACHMENT TO NEW DOOR PANEL							120.00
E PNT98000 PAINT WORK SPRAY FRONT BUMPER FACE, RH FRONT FENDER, 350 X 3 RH FRONT DOOR, RH SIDE MIRROR, RH REAR DOOR AND AFFECTED PORTION							1050 1750.00
M SUNDRY APPLY BODY SEALANT							40 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							30.00
M SUNDRY PERFORM RUST PREVENTION							40 80.00
A 20000001 RENEW FRONT UNDERCARRIAGE DAMAGES							? 400.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY SUPPLY RH FRONT SPORT RIM							400.00
M SUNDRY RE-APPLY LTA BREAK SEAL AND RESEAL FOR FRONT NUMBER PLATE							? 80.00
M SUNDRY SUPPLY FRONT NUMBER PLATE WITH FRAME							? 50.00
M SUNDRY LABOUR RENEW RH FRONT RIM INCLUDING BALANCING							20 50.00
M SUNDRY SUNDRIES							
M COVER-FR BUMPER X L				1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER X				1.00	262.00	20.00	209.60

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11102/WFF ZHI CONG (HUANG ZHICONG) Reg No/Reg Date SMP1326R / 12/09/201 Date In/Mileage / 9038 Chassis No KNAF3416MK5040719 Engine No G4FGJH720482 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	14/12/2020/ 14:36	QUD	247 / DonBong	25767			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	RETATNER-BUMPER SIDE MTG				1.00	1.00	20.00	0.80
M	BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	20.00	17.60
M	BRACKET-FR BUMPER UPR SIDE MTG X				1.00	22.00	20.00	17.60
M	ORNAMENT-KIA NO.115				1.00	32.00	20.00	25.60
M	PANEL-FENDER,RH				1.00	430.00	20.00	344.00
M	INSULATOR-FENDER RH				1.00	27.00	20.00	21.60
M	PANEL ASSY-FRONT DOOR,RH				1.00	1277.00	20.00	1021.60
M	BLACK TAPE-FR DR RR,RH				1.00	13.00	20.00	10.40
M	MIRROR ASSY-OUTSIDE RR VIEW,RH				1.00	559.00	20.00	447.20
M	ARM COMPLETE-FR LWR,RH				1.00	286.00	20.00	228.80
M	HUB ASSY-FR WHEEL				1.00	436.00	20.00	348.80
M	HANDLE ASSY-DOOR OUTSIDE,RH				1.00	164.00	20.00	131.20
M	COVER-FR DR O/S HDL RH				1.00	14.00	20.00	11.20
M	PAD-FR DR O/S HDL COVER,RH				1.00	5.00	20.00	4.00
M	PAD-FR DR O/S HDL HINGE,RH				1.00	5.00	20.00	4.00

SURVEYOR NAME: Steve CLKK) 14/12/20, 3.00pmSURVEYOR SIGNATURE: DD - Not AuthDATE: Excess - ?REMARKS: P/P  
Ry Bel sy  
6 daysLKK Auto Consultants hence notify  
the Repairer of the following:

- Confirm & accepted by
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

7% GST on	Nett	8,540.40
	8540.40	597.83
	<b>Total Payable</b>	<b>9,138.23</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission  
Date of Accident  
Exact Location of Accident  
Additional Location Information  
Country/State of Loss

14/12/2020 13:59 (SGT)  
13/12/2020 22:00 (SGT)  
Block 991 Buangkok Link, Singapore 530991  
BLK 991 BUANGKOK SQUARE MALL CARPARK  
Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMP1326R

#### INSURED/POLICYHOLDER

Is company?  
Name Of Registered Owner  
NRIC No  
Email Address  
Mobile Phone No  
Alternative Phone No

No  
WEE ZHI CONG  
SXXXX784H  
WEEZHICONG@GMAIL.COM  
(Phone) +65-96350968  
+65-96350968

#### VEHICLE PARTICULARS

Manufacturer  
Model  
Variant  
Exact purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle?  
Vehicle Category

Kia  
Cerato  
-  
-  
Yes  
Private car

#### INSURANCE COMPANY

Name of Insurance Company  
Type of Coverage  
Fleet Policy  
Policy Number  
Cover Note Number

AIG  
Comprehensive  
No  
1900160447  
-

#### DRIVER

Name of Driver  
NRIC No  
Date Of Birth  
Occupation

WEE ZHI CONG  
SXXXX784H  
20/12/1982  
Indoor



Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

02/12/2005  
15 YEARS  
Male  
(Phone) +65-96350968  
+65-96350968  
WEEZHICONG@GMAIL.COM  
BLK 992A BUANGKOK LINK #07-155  
-  
531992  
Yes  
-  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Side Swipe  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s)  
soliciting/offering accident claims assistance?

No  
2  
No  
-  
Yes  
3  
No

#### PASSENGER 1

Name  
Gender

VIVZAN CHIN  
Female

#### PASSENGER 2

Name  
Gender

WEE SI NING  
Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Police Station Name  
Police Station Phone No  
Alt. Police Station Phone No  
Police Station Address  
Was notice of intended Prosecution given?  
If yes, against whom?

Yes  
Hougang Neighbourhood Police Centre  
(Phone) +65-18004890999  
(Fax) +65-63128989  
60 Hougang Ave 9 Singapore 538775  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

#### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?  
Was there any audio recorded?

Yes  
Yes  
No

#### DETAILS OF OTHER VEHICLE PROPERTY 1



Vehicle Registration Number	SLA9035T
Vehicle Manufacturer	Nissan
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	AIG
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-




## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for Investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature

Date & Time: 14/12/2020  
1116am.


Driver's Signature

(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

second floor of the

On 13 Dec 2020 at around 2200hrs, I was driving my car up the multi-storey carpark of Bugis Junction square mall. On the way up, another car was driving into my lane and subsequently brushed against the right side of my car. I stopped the car but the other car drove off out of the carpark.

Based on my in-car camera, the other party's car plate was captured partially "SLA 9035" with the last alphabet unclear. Car model should be a black Nissan.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 14/12/2020

1116am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**POLICE FORCE**

T/20201213/2105

Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

1 of 3  
Report No. T/20201213/2105

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 13/12/2020 23:14	Vide Report No.:	Station Diary No.: 102
--	------------------	---------------------------

**Informant's Particulars**

Informant's Particulars			Address:	
Name of Informant: WEE ZHI CONG			APT BLK 992A BUANGKOK LINK #07-155 SINGAPORE 531992	
ID Type / ID No.: NRIC NO / S 784H			Contact No.: Home/Office:	Mobile: 96350968
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 37	Date of Birth: 20/12/1982	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Accountant			Driving Licence Information: Class: 3	Date of Expiry:

**General Information of the Accident**

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 13/12/2020 22:00	Type of Location:
Location:  BUANGKOK LINK				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMP1326R	Car	KIA	CERATO 1.6(A) EX	Black	Slightly Damaged	2

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMP1326R	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1900160447	12/09/2019	11/09/2021



**POLICE FORCE**

T/20201213/2105

2 of 3

Report No. T/20201213/2105

Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

**CONTINUATION OF REPORT**

**Brief Details.**

On 13/12/2020 at about 2200hrs, I was driving my car of registration plate number SMP1326R up the multi storey carpark of Buangkok square, with 2 passengers onboard. As I was driving up, another car of unknown registration plate brushed against the right side of my car.

I stopped my car however the other driver did not stop. No one was injured. I have a dashcam installed inside my car. This is the first time such an incident happened. I do not have disputes with anyone prior to this incident. The incident happened in between the third and forth storey of the carpark.



POLICE FORCE

Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

T/20201213/2105

3 of 3

Report No. T/20201213/2105

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
F /  
Staff Sgt MOHAMED FAIZAL AKBAR ALI

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / HRT /  
Insp GOH GEOK LYE  
Contact No.: 65476148

Signature Of Informant:

Date/Time:  
13/12/2020 23:14

Classification Of Case:

Authentication Stamp  
NP168

**KIA AUTO PROTECTOR PRIVATE VEHICLE**  
Name of Policyholder : Wee Zhi Cong (Huang Zhicong)  
Period of Insurance : 12 Sep 2019 To 11 Sep 2021  
Engine No. : G4FGJH720482  
Chassis No. : KNAF3416MK5040719

Vehicle No. : SMP1326R  
Policy No. : 1900160447  
Endorsement No.  
Issued Date : 19 Sep 2019

#### ABOUT THE COVER

Make/Model : KIA Cerato  
Engine Capacity/Tonnage : 1,591.00 CC  
Driver Restriction : NA  
Sum Insured : Market Value  
Off Peak Car : Yes  
First Year of Registration : 2019  
Insuring with COE/PARE : Yes

#### Person or Classes of Persons Entitled to Drive\* :

- a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

#### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

#### EXCESS

Section 1  
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2  
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Wee Zhi Cong (Huang Zhicong) - \$600 (Own Damage)

#### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

#### IMPORTANT NOTES


Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504624050

FULCOKICP2 - CORPORATE  
22 UBI ROAD 4 FULCO BUILDING  
SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

  
AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORISED REPRESENTATIVE

SSC-