ASS. REC. BY: Tay Th

REF: NS/INC20013788/T1tf3e2

ASSI	GINIVIEIVI		
From: Date:	Veh No: SH 67227. Yr Regn: 2017, NOV.		
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi) Prime Mover /		
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or		
To Inspect Vehicle No:	Make: Hyundan 140 c.c 1685		
at Workshop m/s	Colour Street A/C: Insured / Std / NI / NA		
of	Sp.Reading T/Radio: Insured / Std / NI / NA		
Insured:	Eng/No:		
Policy No.	C/No: 1CM 4CB4/4M-94080492		
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt		
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or		
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or		
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or		
Tyre Size: F: nor /lones.			
(Policy Condition)	R: 1 n		
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /		
repair at the time of inspection.	TOYO / YOKO or WEST LAKE		
Bal. or Market Value:	Front Rear		
IDAC Accident Rport: Consistent? : Yes or No	R/Bal mm R/Bal form		
GIA / PR Seen: Consistent?: Yes or No	L/Bal6mm L/Bal6mm		
Est. Repairs:days Res.: Yes or No	D.O.A. D.O.I. 10/12/20		
Lum Sum: % 3 Val.: Yes or No	Survey held at Comfort logery.		
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / Q/S N/S / U/C / Rooftop or		
Date: Person Contacted: Vehicle: IN / OUT			
	The U/C / Chassis frame / Body Structure affected due to collision.		
Date / Time Action / Instruction			
COR I/s \$650 , 1 day.			
red: 176; 21%			
Date/Time, File Pass to? : Preli. Report	Days Of Repair:		
leacestal.	Resurvey No. of Trip: Survey Fee:		
Date/Time, File Return to?	Transportation:		
2) Add Fee	la marca di		
	: Interview (\$) Photos		
RepetiFormal: : Tech. Invs (\$) Others			
Lump Sum / LB.E. () (S)			
	TOTAL		

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 10.12.2020

Time: 16:17:11

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO 305438279 SH 6722T

MILEAGE

: 0000000000 : HYUNDAI

MAKE MODEL

: I-40

DATE OF REGN

: 12.11.2015

DATE/TIME IN

: 10.12.2020 13:55

ACCIDENT DATE : 10.12.2020

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0594-G I40VC MIRROR ASSY-RR VIEW 1 L 670.00 20.00 536.00 CM

SUB-TOTAL: 536.00

JOB NATURE

0000 L

PANEL BEATING

140.00

0001 23-502

SPRAYPAINT ON AFFECTED AREA

100.00

0002 17-01

CHECK ALL LIGHTING

50.00 30

SUB-TOTAL : 290.00

TOTAL: 826.00

AUTHORISED: YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE:

Touther 97495749

Oldey

LIS Rossey Afre uport

tanplin C Mando.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed a is subject to final approval from Insurance Co

Acknowledged by Repairer

Signature:

Date:

OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

24 Seneko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun industrial Park A Singapore 76

Date/Time :20 4000413219202004915:54

Page : 1

JC NO.: 305438279 JOB CARD ARC Repair TP(CLSO)1 Sales Order: leam: REGN NO. 6722T MILEAGE OMER COMFORT TRANSPORTATION PTE LTD MAKE: HYUNDAI FUEL IS 7010045 OMER NO 383 SIN MING DRIVE E.....F MODEL I-40 10.12.2020 13:55 Singapore SINGAPORE 575717 65508755 YR OF MANU: 11.2015 TARGET DATE (R) (P) -CHASSIS CODE KMHLB41UMGU080442 COMPLETION DATE/TIME: DUNT CARD NO. JOB DESCRIPTION

Accident Date: 10.12.2020

VATURE: 3P 10.12.2020

3/NO

LABOR CODE

FRONT DESCRIPTION LEFT SIDE

REAR

KED & PASSED OUT BY:		_		
SERVICE ADVISO	R		CUSTOMER'S SIGNATURE	_
edgement Slip	Taufik	Exit Pass		
lo.: SH 6722T	LKE	Vehicle No.: SH 6722T		
Service Advisor	Signature/Date	Name of Service Advisor	Date	
urned to Service Reception upor	collection	To be kept by Security Guard		

SC1120CA000E / COMFORTDELGRO ENGINEERING PTE LTD [508969] ENTRY DATE & TIME: 10/12/2020 15:05 (SGT) SUBMITTED BY: Janet Lim Siang Gek VERSION: 1 (10/12/2020 15:05 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process

This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss

10/12/2020 15:05 (SGT) 10/12/2020 13:15 (SGT) Near Malaysia TAMPINES STREET 11 BLK 108 OPEN CARPARK Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SH6722T

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address**

Mobile Phone No Alternative Phone No

COMFORT TRANSPORTATION PTE LTD

1XXXXXXXX1R

FLEETSAFETY@CDGETAXI.COM.SG

(Phone) +65-65508768 (Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Hyundai 140

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Private hire

No - Claiming third party

Taxi

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy Policy Number Cover Note Number India International ThirdPartyFireTheft

Yes

MCOM0015

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

SHAFIE BIN HUSSIN SXXXX538F 10/08/1963 Outdoor



Date Of Driving Pass

Driving experience

Gender

Mobile Number

Alt. Phone Number

Email Address

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

521

#11-127 521102 No

18/07/1992

28 YEARS AND 5 MONTHS

shafiehussin63@gmail.com

BLK 102 TAMPINES STREET 11

(Phone) +65-97249427

Other No

-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident

Weather Conditions

Road Surface

Collision - Head to Rear

Clear

Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No -

No

2

Yes

1

No

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

If yes, against whom?

No

No

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHED

* TYPE OF ACCIDENT :- TAXI REVERSED

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

Yes

Yes

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category Name of Driver

Contact Number Address

Address complement

Postcode

GBG8247S

-

-

Commercial vehicle

TOK HOOU LEI

-

-

-

_

Accident report SC1I20CA000E

Page 2 of 15

Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver) NTUC SLIGHT REAR

HVIT CHYLANI NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of me
 facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insura Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copie the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, u disclose and/or process my personal data/personal information setout in this [form] and any other personal informat provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer st Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insure vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, t Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessal investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which my be sited outlisde of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared/disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or ourt orders.

COMPORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature Date & Time:

Driver's Signature (if driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/Fin No.: A LUM LUM A SH 6727 T GBG 8247S ALP)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIBE SHOOMS IN THE SECOND SHOWS IN THE SECOND SHOWS IN THE SECOND SHOWS IN THE SECOND SHO
Street 11 with no passenger onboard, of turn right to B(K 108
Street 11 with no passenger onboard, of turn right to BIK 108
open carned to packing my vehicle. After enter the granding prague.
open carparts to packing my vehicle, After enter the granding prague. no far valide B (5BG 3242S) a truck on the right side
carnade lot raverse and collided onto my right side wing
carparle lot reverse and Collided onto my right side wing minor, where the accident i how exchange particular and take photo with the Third party driver. No one was injuried at that fime of accident
take aboto with the Third party driver. No one was
mounied at that time of accident
Thorres of deader.

DECLARATION

We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature Date & Time: Driver's Signature (if driver is not the policyholder) Date & Time: Reporting Centre/Personnel's Signature Name: NRIC/Fin No.: On Leon Del







