

12/12/2020

REF: CS/MSG20013789/Dqd3

Special Instruction:

ASS. REC. BY:

ASSIGNMENT (Office)

SURVBY
Merimen

From (Person):

KATHERINE WONG of

MSIG

Date/Time: 14/12/2020@2.49PM

Estimated Cost:

Bill to:

OD-TP-WS-TP RES / OD RES / EVA / INV / MV / CS

SLG 5155A

Insured: SJY 2359C

To Inspect Vehicle No:

Tel: 6909 8882

at Workshop m/s

JWG INTERNATIONAL

of

BLK 10 AMK IND. PARK 2A# 03-08

Policy No: 1001347818

Claim No: 250820

Sum Insured:

Excess:

D.O.A. 05/12/2020

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 3.17PM@14/12/2020

Person Contacted:

CYNTHIA

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	Repairer agreed to survey on 15/12/2020
	SLG 5155A-NA/AIG20013621/h4	DOA : 05/12/2020
	SJY 2359C-NA/AIG20013621/h4	DOA : 05/12/2020