JASS. REC. BY: STER J. MET: (S/A)	16200/38/9/EVDS
Jest 100 10 10 10 10 10 10 10 10 10 10 10 10	COT (C/9T 07/3/19)
From: Date:	Veh No: 30 J 330 / 1 Yr Regn: // Will I
Estimated Cost:	Type: (M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
QD/ TP / WS / TP RES / OD RES / EVA / INV / MY	Truck / Trailer or
To Inspect Vehicle No:	Make: MASUMISMI Gutlander c.c 1998  Aug: Insured / Std / NI / N
el Workshop m/s	Colour A/C: Insured / Std / NI / N  OURS T/Radlo: Insured / Std / NI / N
SECTION AND ADDRESS AND ADDRES	Sp.Reading 29962 Tradio: Insured vital
Insured:	Eng/No:
Policy No.	C/No: 01/1/070344
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inprogr / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII (SIRINI / STD AIRIM 91 CP 18
	Tyre Size: F: 225/55R/8
(Policy Condition)	R:
Remark: The veh had commenced its	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or \$ /Mg
Bal, or Market Value:	Front Rear
Consistent 2 : Yes or No	R/Bal. 4 mm R/Bal. mr
On-lotent2 : Veg or No	UBal. 4 mm L/Bal. 4 mm
Peg : Yes of No	D.O.A. 13/12/29 0.0.1. 15/19/29
3 Val : Vas or No	Survey held at CYK & Callace
Lum Sum: % 3 val 163 d. 116	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS  Vehicle: IN / OU	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time   Action / Instruction	
MV- 93K	
: Prell. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
₃/Tune, File Return to?	Transportation:
Add Fee	
•*	: Interview (\$) Fnotes
ornes:	: Tech. Inva (% ) Offices
ip Suin [L.C.]: Cr	: Weel'end (*
	TOTAL



## CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

#### **ESTIMATE**

GST Reg No : MR-8500111-X

o : 197701469G	Owner Name & Vehicle Info		
Involce Name & Address  AIG Asia Pacific Insurance Pte.	Cust No/Name Reg No/Reg Date	KCV10831/YEO TECK YEOW (YANG ZHUYAO) SDJ5569T / 27/03/201	
Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Date In/Mileage		
	Engine No	4J11AC1944	
	riune,	MIT/19MY OUTLANDER 2.0 MODERN(995)	
Contact no	Colour/Trim	PO2 RED METALLIC / BK BLACK	

				Colour/ Irim	OZ KED III				
			CSE	Operator		WIP No			
Account No	Terms	Date/Time Printed	BLC	442 / CocoLu		60708			
FAX00001	Credit	14/12/2020/ 17:01		442 / 000000	Qty	Unit Price	Disc%	An	nount
		Description of Good	s / Services					2600	4050.0
	DIL DEA	ERT FENDER RH, FRT	JIMPER.					7000	
DNITOOOOO		T DOOR FRAME RH, CEI							180.0
REMOVE &		FRT DOOR TRIMS AND (							180.0
RMEOVE &	INSTALL	REAR DOOR TRIMS AND	GLASS						60.0
REMOVE &	INSTALL	PARKING SENSOR		70	<b>[7</b> ]				3150.0
E PNT98000	NT FOR E	RT BUMPER, FRI FENDE	R RHI FRT	DOOR RHOW A	ire	5		245	0
REAR! FEND	ER RH, R	EAR BUMPER	961						120.
To Conduc	MENI t Comput	erize Full Wheel Ali	ignment						60.
SUNDRY		T AND REAR RIGHT RIM						7	450.
54900099 RENEW FRT								1	450.
54900099								•	30.0
RENEW REA 4 54900099									
CHECK WIR		ECTRICAL SYSTEM							120.0
10028901 TO CARRY	OUT DIAG	NOSTIC CHECK USING H	HI-SCAN PRO	TEST 4ºX1					00.0
USING HI-									80.0
	LANT FOR	ACCIDENT PORTION						X	480.0
M SUNDRY SUPPLY FR	T TYRE						- 1	X	480.0
M SUNDRY SUPPLY RE	AR TYRE								
Confirm & a		y Stea	n (LKK)	00- Not A					
		15/12/	120, 1030	on Excess -	•	7			
Authorized	signatory	and company stamp		$\rho/\rho$	M	le Cr	require		

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. Nowever, should this occur, we would advise you. Please he informed that a any additional parts of labour which may be required after repair work has commenced, occasionally work of defined that a after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. Page 1 of 3



# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE** 

GST Reg No : MR-8500111-X

No : 197701469G Invoice Name & Address	THE DISCHALL OF A COMMON STREET	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model	

		N. M. Dalakad	CSE	Operator	STATE STATE OF	WIP No			-
Account No	Terms	Date/Time Printed		442 / CocoLu		60708			
FAX00001	Credit	14/12/2020/ 17:01	BLC	442 / COCOLO	Qty	Unit Price	Disc%	An	nount
57 77 7 7 7 7 7 9 9 9		Description of Good	s / Services	and the last term of th					20.0
M SUNDRY									0000 N
Sundry								160	180.
PNT88000		DEAD QUOTAD CLASS							
	INSTALL	REAR QUOTAR GLASS							60.
SUNDRY		OUOTAT CLASS							225
		QUOTAT GLASS							225.
PNT88000	TNCTALL	REAR COMPARTMENT TR	IMS REAR FE	NDER INNER TRIMS					
	INSTALL	3			202	050 00	22 00		661.
SEATS FACE, FR B	IMDED	< BR 00			1.00	859.00			13.
BRACKET, F	RIMPER		, c , lan =	_	71.00	18.00	23.00		36.
GARNISH, F	RELIMPER	RH / CUT	大公中人	1500	15 7.29	220.00			169.
GARNISH, F	R BUMPER	SIDE /	5111		1.00	7 112.00			86.
GARNISH, F	R BUMPER	SIDE /	<u>ى</u> كا كا		T (A'00)		23.00		36.
GARNISH, F	R BUMPER	SIDE / CUI			1.00		23.00		4.
BRKT.FR B	UMPER SI	DE,LWR RH			1.00	116.00	23.00		89.
MOULDING,	FR BUMPE	R,RH / CUI			1.00	160.00	23.00		123.
MOULDING,	FR WHEEL	ARCH, RH / (UT			1.00	160.00			123.
MOULDING,	RR WHEEL	ARCH, RH			1.00	106.00			81.
MOULDING,	RR BUMPE	1, 1, 1, 1			1.00	688.00			529.
FENDER, FR	RH /	UU - N/C			1.00	470.00			361.
GLASS,QTR	WINDOW,	RH / N/			1.00	348.00			267.
COVER, ENG	ROOM UN	DER, FR			1.00	164.00			126.2
SHIELD, FR	WHEELHO	ם סט			1.00	128.00			98.5
SHIELD, RR SHIELD, RR	WHEEL,F	D DH (			1.00		23.00		16.9
SHIELD,RR PANEL ASS	V FR DOO	R RH / DD			1.00		23.00		752.2
HINGE, FR					1.00	43.00			33.1
HINGE, FR					1.00	43.00			33.1 67.7
MLDG.F/DR	WDO BEL	T LINE, RH X			1.00	88.00			129.3
W/STRIP.F	R DR OPN	G,OTR RH			1.00	168.00			721.4
M PANEL ASS	Y,RR DOO	R,RH / CD			1.00	937.00 43.00			33.1
M HINGE, FR					1.00	43.00	23.00		JJ. 1.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 2 of 3



## **CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED** PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

#### **ESTIMATE** GST Reg No : MR-8500111-X Co Reg No : 197701469G Owner Name & Vehicle Info Invoice Name & Address KCV10831/YEO TECK YEOW (YANG ZHUYAO) Cust No/Name AIG Asia Pacific Insurance Pte. SDJ5569T / 27/03/201 Reg No/Reg Date Itd. Date In/Mileage MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 GF7W0600544 Chassis No AIG BUILDING 4J11AC1944 Engine No SINGAPORE 079120 MIT/19MY OUTLANDER 2.0 MODERN (995) Make/Model Contact No 6419 1000 POZ RED METALLIC / BK BLACK Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
	Credit	14/12/2020/ 17:01	BLC	442 / CocoLu		60708		
FAX00001	credit	Description of Goods			Qty	<b>Unit Price</b>	Disc%	Amount
M HINGE, RR	DOOR HEE	-			1.00	43.00	23.00	33.1
M HINGE, RR M MLDG. R/DF	WOO REL	T LINE, RH X			1.00		23.00	60.8
M MLUG, K/UM	P DOOR C	PNG, FR RH X			1.00	130.00		100.1
M TADE ED F	OOR SASH	I,RH / NC			1.00		23.00	32.3
M TAPE, RR C	OOR SASH	-nec			1.00		23.00	32.3
M TAPE, RR D		1/11			1.00	42.00	23.00	32.3
M GARNISH, F		H / CUL			1.00	190.00		146.3
M GARNISH, R					1.00	164.00	23.00	126.2
M AIR DAM,S		1 (11)			1.00	541.00		416.
M COVER, DOC					1.00	138.00		106.2
M MIRROR AS	CA DOOD	DU X	gang	П	1.00	555.00		427.3
M HEADLAMP		CUT		ima	5 3.00	1938.00		1492.2
		a (4) 15 (	$^{21}$	110012		348.00		267.9
M LAMP ASSY		OH 6. 0H	जा।(क	(0)	2.00	974.00		1499.9
P WHEEL, DIS		DOTALE OF A	DU		1.00	1285.00		989.4
M SHAFT AS,					1.00	432.00		332.6
M HUB ASSY,		314 32 54 54 54 54 54 54 54 54 54 54 54 54 54			1.00	323.00		248.7
M ARM ASSY					1.00	1114.00		857.7
M CROSSMEM		CLE, NO. 1			1.00	406.00		312.6
M STRUT, FR	SUSP, KH	1 1750 1			1.00	137.00		105.4
M LINK, FR	2025 21VI	STRUT 9			1.00		23.00	24.6
M BEARING,					1.00	214.00		164.7
M SHOCK AB		34			1.00	57.00		43.8
M INSUL,RR					1.00	19.00		14.6
M PAD, RR S					1.00	151.00		116.2
M ARM ASSY					1.00	501.00		385.7
		TRAIL, RH -			1.00	86.00		66.2
M LINK,RR					1.00	109.00		83.93
M ARM ASSY					1.00	62.00		47.74
	TIE ROD	STEERING NOT			1.00	1399.00		1077.23
Jenn de L	1331	/ [[			(T.E.S.T)	(T.T.T.) T. T. T.	NOTE TO 2017/07/07	
Confirm &	uto Consu eparer of tr	jants hence notify ie following:						
• To res	survey before/	after spray painting	1			Net	t	24,619.2
To dis	play damaged	part(s) during resurvey	ł		7% GST on	24619.2	3	1723.3
• Parts	prices are sub	eject to confirmation	1					
• Third	party survey is	s on a "Without Prejudice" basis	1		To	tal Payabl	e	26,342.5
No ille	gal modification	on(s) is allowed						
Authorfzed	signatory	(spands) sempany at amp						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubbar scal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.

1A20CE000B / CYCLE & CARRIAGE AUTOMOTIVE PTE LTD ENTRY DATE & TIME: 14/12/2020 16:09 (SGT) SUBMITTED BY: TAN SHIEH YUEN VERSION: 1 (14/12/2020 16:09 (SGT))



## SINGAPORE ACCIDENT STATEMENT

Please report correctly the details of the accident to speed up the claims process.

- 1. Please report <u>correctly</u> the details of the accident to speed up one claims process.
  2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
  5. Any false reporting may be referred to the Police for Investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

14/12/2020 16:09 (SGT) Date of Submission 13/12/2020 04:30 (SGT) Date of Accident PIE, Singapore **Exact Location of Accident** PIE/CHANGI 13KM Additional Location Information Singapore Country/State of Loss

### DETAILS OF OWN VEHICLE

SDJ5569T Vehicle Registration Number

#### INSURED/POLICYHOLDER

Is company? YEO TECK YEOW Name Of Registered Owner SXXXX407D NRIC No TYEO@KAPPS.COM.SG Email Address (Phone) +65-96738593 Mobile Phone No +65-96738593 Alternative Phone No

#### VEHICLE PARTICULARS

Mitsubishi Manufacturer Outlander Model Variant Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to Yes your vehicle? Vehicle Category Private car

#### INSURANCE COMPANY

Name of Insurance Company AIG Type of Coverage Comprehensive Fleet Policy Policy Number 1900022090 Cover Note Number

#### DRIVER

Name of Driver YEO ZONG RONG NRIC No SXXXX394C Date Of Birth 18/07/1997 Indoor

	11/09/2018
of Driving Pass	2 YEARS AND 3 MONTHS
wing experience	Male
cender	(Phone) +65-85229507
Mobile Number Alt. Phone Number	*
Alt Phone Number	RONALDYEO1997@GMAIL.COM
Alt. Phone Number Email Address	BLK 6 PAYA LEBAR ROAD #08-20
Email Address Address	Denve
Address	409055
Address complement Postcode	
Postcode	No
Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured	Child
if No Relationship of the Differ	No
Does Driver Own Other Vehicles?  Vehicle Registration Number of Other Vehicle Owned by Driver	
La Desictration Number of Care	e <b>=</b>
Insurance Company of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by	
Insurance Company of Catal	
GENERAL INFORMATION OF THE ACCIDENT	
GENERAL INFORMATION OF THE ACCIDENT	
	Collided into Property
Type of Accident	Raining
Type of Accident Weather Conditions	
Weather Conditions Road Surface	Wet
Road Surface	and the state of t
OTHER INFORMATION	
the dip the accident?	No
Was any foreign vehicle involved in the accident?	1
Was any foreign vehicle involved in the accident Number of vehicles involved in the accident	No
	MANAS P#€
	No
	4
Descenders (Including Dilver)	4
	No
Has the driver been approached by driktion soliciting/offering accident claims assistance?	110
Soliciting/orienting desired	
PASSENGER 1	
The second secon	NICHOLAS SIM
Name Gender	Male
Gender	
PASSENGER 2	
PASSENGER 2	PHILSON CHAN
Name	Male
Gender	Mole
A CONTRACTOR OF THE PARTY OF TH	
PASSENGER 3	Mark Mark A
Name	VALERIE TAN
	Female
Gender	
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No .
Was notice of intended Prosecution given?	No
If yes, against whom?	m:
II yes, against thiom.	A PART OF A PROPERTY AND A PART OF A
CIRCUMSTANCES OF ACCIDENT	
REFER TO ATTACHMENT	
NEI EN TO AL MONTE	
ATTACHMENT(S)	
五	TV =
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No
	OX
	· ·

#### SKETCH PLAN

## IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
I was driving along PIE towards Changi. Was rainy & road was slipping, was trying to change lane, there was a and the car skidded of rubbed against the trying to change lane, there was a and the while. I EM Called AIL, they bushes at the side. Lost control of the while. I EM Called AIL, they activated EMAS. † MAS came, then police stopped by as well. Police inspected if there was claimle driving and damage to government properties, which they confirmed there were none to both. Police took down my details of left.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

## and which will be a second to the second and the second se CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

; YEO TECK YEOW (YANG ZHUYAO) Name of Policyholder

Period of Insurance

: 27 Mar 2019 To 26 Mar 2021

Engine No. Chassis No.

: 4J11AC1944

: GF7W0600544

Vehicle No.

: SDJ5569T

Policy No.

: 1900022090 : 000000000360648

Endorsement No. Issued Date

: 13 Oct 2020

# ABOUT THE COVER ART OF THE PROPERTY OF THE PRO

Make/Model

: MITSUBISHI Outlander 2.0 Elegance/Sports

Sum Insured : Market Value

First Year of Registration : 2019

the state of the s

Engine Capacity/Tonnage: 1,998.00 CC

: NA

Driver Restriction

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive\*:

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

: All Age Condition

Mileage Condition

: Unlimited Mileage

Age Condition

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

\* Limitations rendered Inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS THE PROPERTY OF THE PRO Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

YEO TECK YEOW (YANG ZHUYAO) - \$600 (Own Damage)

# APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
3 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other. Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

Hire Purchase Company/Employer's Loan: HL Bank

I'We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of State of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks) Rules, 1959 (Mulaysia).

0504620205

C&CMICP2 - DLOOI

239 ALEXANDRA ROAD SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Believe and a second of the se

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

Business Street Bridge When drawning to working a visit of