



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN: CYNDIE YONG

Ref: CS/INC20013811/Atf3e2

Date: 25/01/2021

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFS 9847T	Veh. Inspected	GBH 3734E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1113584-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	14/12/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	VSKYBAM20Z0158458	Colour	WHITE
Odometer	99521 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14C	FALKEN	6 mm
L/H Front Tyre	175/70 R14C	FALKEN	6 mm
R/H Rear Tyre	175/70 R14C	FALKEN	6 mm
L/H Rear Tyre	175/70 R14C	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/12/2020	Inspect Date / Time	15/12/2020 (11:03 AM)
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days