Our Ref

CT 1220 / SHC8138Z /CK(st)

Your Ref:

Date

4-Jan-2021

CDGE Taxi Claims Dept 59 Loyang Drive 4th Flr Singapore 508969

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell 205 Braddell Road Singapore 579701

Loyang 59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

CHINA TAIPING INSURANCE CO LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attn: Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHC8138Z YOUR INSURED YM 8698U 14.12.20 ON AND OTHER

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor SHC8138Z which was involved in the captioned accident with your insured Vehicle No: vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : YM 8698U we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

TAX	I OWNER'S CLAIM	\$	2,247.00
1	Cost of Repair 3 days Loss of Rental @ \$ 110.67 per day	\$	332.01
6	3 days Loss of Roman	\$	1
3	Survey Report Fees (Surveyed by M/s LKK)	\$	2.00
4	LTA Search Fees	\$	-
5	GIA / Police Report Fees	\$	•
6	Towing Fees	Sub Total: \$	2,581.01

HIRER 7	ER'S CLA	IM _ days Loss of Income @	\$	80 00 per days	\$ 240.00
	3			Total Claims :	\$ 2,821.01

We enclose herewith the following documents to support the claims: -

Original repair bill: a)

LTA search slip/s of: b)

YM 8698U

GIA / Police report/s of: c)

SHC8138Z

Letter of authority from owner / hirer / operator d)

() Traffic Compound () Towing/Medical bill/receipts () Certificate of Insurance

() PIR (x) Rental Rate letter

(x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully Catherine Koh

CDGE Claims Department

Tel: 6214 8733 Fax: 6214 1843 Email: catherinekoh@cdge.com.sg

This is a computer generated letter. No signature is required.



LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING i 40 SHC8138Z , YM8698U

ON 14-Dec-20 11:25

ALONG

CTE TUNNEL TWDS SLE

I / We

KOH TECK NGUANG

(Hirer) NRIC No.:

SXXXX534B

and/or

STEPHEN YONG CHOON... (Relief) NRIC No.: SXXXX389I

Taxi Number

SHC8138Z

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of earning (Pending successful recovery), loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

14-Dec-2020

Name of Hirer

KOH TECK NGUANG

Hirer NRIC

SXXXX534B

Signature:

Address

233 BUKIT BATOK EAST AVENUE 5 ...

650233

Contact No.

96381852

Name of Relief

STEPHEN YONG CHOON SENG

Relief NRIC

SXXXX3891

Signature:

Address

230 BUKIT BATOK EAST AVE 3 #07-216

650230

Contact No.

81007390



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 7687

320 Ubi Road 3 Singapore 408649 COMPANY REG. NO.: 199506048W Page: 1

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE 079909

CONTACT NO: 62222366

VEHCLE NO SHC8138Z

NO/DATE 91538014 22.12.2020

MAKE HYUNDAI

JOB NO. 305439041

MODEL I - 40

ODOMETER READING

DATE OF REG 21.04.2016

CHASSIS CODE KMHLB41UMGU087801

JOB TYPE

Description: 3P 14.12.2020

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt Add GST @ 7.000 %

Total Invoice amount

2,247.00

Issued by : CHEWBEELENG 22.12.2020 16:40:33
Repair Type : CLSO/57/57
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd

A member of **COMFORT**DELGRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No. INVOICE No. BANK/CHQ No. **AMOUNT**

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT20120247

Date: 22 December 2020



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

14/12/2020 @ 11:25 hrs

ALONG

CTE TUNNEL TWDS SLE

INVOLVING

YM8698U

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC8138Z (the "Taxi"). The Taxi was hired to KOH TECK NGUANG IC NO SXXXX534B a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$110.67 per day (inclusive of GST).

Please be advised that the Taxi was insured with MS First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Philip Chia Manager, Fleet Safety

This is a computer generated letter. No signature is required.

			Ž	(8)								
HOURS OPERATED (TIME)	OT	1 08 20	1900	272	- BELST	5061	ass	7051-	2550	1300	8000	200 -Pins
HOURS O	FROM	0415	0830	4	okers-	0835	Hrs	120	(us)	05:20	1500	272
MILEAGE	(KM)	103	219	2	(23	463	ta	225	229.8	223	2.92	40)
: READING		8	30	2/2	6 20 6	8 9 3	7	378	809	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	900	186

HOURS OPERATED (TIME)	101		()					
HOURS OP	FROM	280	1736	100 P					
MILEAGE	(KM)		3						
W January	פאוומאפר		_		3				
COLUMNIE DE	MILEAGE		- 4						
NAME OF DRIVER			Acoldon	3					
DATE		14-12-20	10-17-30	R-(1-8)					

Find insurer

YM8698U

Vehicle reg. no.

Date of Accident

14/12/2020

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance China Taiping Insurance

Period of Insurance 04/07/2020 - 03/07/2021

Requested By Por Moy Juan (COMFORTDELG...

Requested Date 14/12/2020 15:28

Payment details

Request Amount: **\$\$1.87** GST Amount: **\$\$0.13**

Total Amount Due (GST Inclusive): **\$\$2**

General Insurance Association

Records Management Centre GST Registration No: **M400017735**

