



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20013816/Aqf3q2 Date: 08/02/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLJ 6913G	Veh. Inspected	SMD 4856X	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10008340/CH	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	15/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MNTBBAB17Z0032520	Colour	BRONZE	
Odometer	65975 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MAXXIS	6 mm	
L/H Front Tyre	205/55 R16	MAXXIS	6 mm	
R/H Rear Tyre	205/55 R16	MAXXIS	6 mm	
L/H Rear Tyre	205/55 R16	MAXXIS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/12/2020	Inspection Date	15/12/2020	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	