

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305438936

Date : 19/12/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RASUL

Vehicle Reg No. : SHA1228D

Date of Accident : 13-Dec-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLP3768Y

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,646.74

(b) Labour Charges \$1,200.00

Total for Part-By-Part Repair Cost \$2,846.74

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 5 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : _____

Name : LIM T S

Name : RASUL

Tel : 62148398

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 17.12.2020

Time: 13:00:34

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438936
REGN NO : SHA1228D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 14.12.2020 09:55
ACCIDENT DATE : 13.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52
0002	04-01-0104-2288-G	REAR BUMPER REINFORCEMENT	1	394.80	20.00	315.84
0003	04-01-0104-3919-G	REAR BUMPER STAY RH	1	138.10	20.00	110.48
0004	04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00
0005	04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00
0006	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60
0007	04-01-0104-2544-G	REAR BUMPER TOW COVER	1	5.40	20.00	4.32
0008	04-01-0104-2270-G	BOOTLID EMBLEM-HYBRID	1	24.30	20.00	19.44
0009	04-01-0104-2271-G	BOOTLID EMBLEM-IONIQ	1	31.30	20.00	25.04
0010	28-01-0103-0005-A	BOOTLID COMFORTDELGRO	1	30.00	10.00	27.00
0011	28-01-0103-0006-A	BOOTLID 65521111	1	30.00	10.00	27.00
0012	28-01-9999-2025-A	BOOTLID APPS	1	40.00	10.00	36.00
0013	09-01-9999-0068-A	REVERSE SENSOR	1	180.00	10.00	162.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438936
REGN NO : SHA1228D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 14.12.2020 09:55
ACCIDENT DATE : 13.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 FNPS NO PLATE(S)W/TRIM COVER 1 N 55.00 10.00 49.50

SUB-TOTAL : 1,646.74

JOB NATURE

0000 PB PANEL BEATING 640.00

0001 SP SPRAYPAINT CHARGE 500.00

0002 L R/I REVERSE SENSOR 60.00

SUB-TOTAL : 1,200.00

TOTAL : 2,846.74


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :