

NTUC (LIS) P/P
LKK - Taufiqh Rasol

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438799
REGN NO : SHD4036E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 18.03.2020
DATE/TIME IN : 14.12.2020 10:00
ACCIDENT DATE : 10.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER <i>cm</i>	1	459.40	20.00	367.52
0002	04-01-0104-2533-G	REAR BUMPER CTR MOULDING <i>cm</i>	1	451.25	20.00	361.00
0003	04-01-0104-2544-G	REAR BUMPER TOW COVER <i>cut</i>	1	98.80	20.00	79.04
0004	04-01-0101-0111-G	REAR BUMPER CLIPS <i>cm</i>	10 L	22.00	20.00	17.60
0005	04-01-0104-2545-G	REAR BUMPER LWR MOULDING <i>cm</i>	1	155.00	20.00	124.00
0006	09-01-9999-0068-A	REVERSE SENSOR <i>? Ysue</i>	1	180.00	10.00	162.00
0007	FNPS	NO PLATE(S)W/TRIM COVER <i>cm</i>	1 N	55.00	10.00	49.50
0008	04-01-0104-2288-G	REAR BUMPER BEAM <i>? cm</i>	1	394.80	20.00	315.84

SUB-TOTAL : 1,476.50

JOB NATURE

0000	PB	PANEL BEATING	350.00	320
0001	SP	SPRAYPAINT CHARGE	250.00	200
0002	L	R/I REVERSE SENSOR	120.00	60

NTUC-48 P/P

12 JS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438799
REGN NO : SHD4036E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 18.03.2020
DATE/TIME IN : 14.12.2020 10:0
ACCIDENT DATE : 10.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 720.00

TOTAL : 2,196.50

Limf

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE

DATE :

Rashu
Hp 90010068

3 days

P/P

14/12/2020 @ 1700

Resurvey before paint

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KE 509x1

Veh No: