

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|---|----------------|---------|------------------------|--|
| | AXA INSURANCE I | PTE LTD | | Ref: | CC4/ASM20013839/Uba3q2 | |
| | 8 SHENTON WAY AXA TOWERSING | | | Date: | 13/05/2021 | |
| | ATTN:RICHARD A | NG | | Code: | ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| | Insured Veh. | SMQ 5116Z | Veh. Inspected | l | GBJ 5088M | |
| | Policy No. | VFX/P2385062 | Coverage (\$) | | 0.00 | |
| | Claim No. | S0M02YWA | Excess (\$) | | 0.00 | |
| | Assign From | | Assign Date | | 15/12/2020 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | NISSAN NV200 (M) | c.c | | 1461 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2019 | |
| | Chassis No. | VSKYBAM20U0177432 | Colour | | GREY | |
| | Odometer | 30837 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | NIL | |
| | General | FAIR | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 175/70 R14 | GOODYEAR | | 6 mm | |
| | L/H Front Tyre | 175/70 R14 | GOODYEAR | | 6 mm | |
| | R/H Rear Tyre | 175/70 R14 | GOODYEAR | | 6 mm | |
| | L/H Rear Tyre | 175/70 R14 | GOODYEAR | | 6 mm | |
| 4. | . Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 13/12/2020 | Inspection Dat | е | 15/12/2020 | |
| | Survey held at | LEE BROTHERS AUTOMOTIVE | PTE LTD | | | |
| | | 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORM | MAL PERIOD FOR REPAIR: | | 9 Worki | ng Days | |
| | <u> </u> | | | | | |