



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

General Details

Involving TPVD UNKNOWN UNKNOWN (FBR9227K)

Date of Loss 12 December 2020

Time of Loss 19.40

Loss Description SJP1282T (INSD) C/W FBR9227K (TP)

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount \$5,782.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion *



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# FBR9227K

Purchase Date



Registration State

Registration Date *



Mileage

Age of Vehicle 0

Driver Details

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<input type="text"/>
Make	TPVD UNKNOWN	<input type="text" value="YAMAHA"/>
Model	UNKNOWN	<input type="text" value="MTN155"/>
Type		<input type="text"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	MOHAMED WASEEM	<input type="text"/>
Date of Birth		<input type="text" value="dd/mm/yyyy"/>
Age	0	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type of Paint		<input type="text"/>
Chassis No		<input type="text" value="MH3RG711000001144"/>
Engine No		<input type="text" value="G3R1E0002343"/>
Engine Capacity		<input type="text" value="155"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="13000"/>

Occupation CATEGORY	Unknown FNOL INFORMATION	<input type="text"/>
		INFORMATION
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text"/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value=""/>

Gender
CATEGORY

Unknown
INFORMATION

Marital status

Unknown

Identification #

S9770934C



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

15/12/2020



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

110-70-17

Rear Tyre Size

140-70-17

Front left side

IRC8mm

Rear left side

IRC8mm

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes No

Part Supplied by AXA

Yes No



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add Approve Deny Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		HANDLE BAR	Bent	0	225	No		10			202.5	Reviewing	
<input type="checkbox"/>		0	1		HANDLE BALANCER LH	Damaged	0	60	No		10			54	Reviewing	
<input type="checkbox"/>		0	2		THROTTLE CABLE	Serviceable	0	0	No		10			0	Deny	
<input type="checkbox"/>		0	1		MIRROR LH	Cut	0	115	No		10			103.5	Reviewing	
<input type="checkbox"/>		0	1		MIRROR RH	Serviceable	0	0	No		10			0	Deny	
<input type="checkbox"/>		0	1		CLUTCH LEVER	Damaged	0	125	No		10			112.5	Reviewing	
<input type="checkbox"/>		0	1		HEAD LAMP	Serviceable	0	0	No		10			0	Deny	
<input type="checkbox"/>		0	1		FORK TUBE LH	Cut	0	685	No		10			616.5	Reviewing	
<input type="checkbox"/>		0	1		FORK OILSEAL N/S	Necessary	0	45	No		10			40.5	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		FORK OILSEAL O/S	Serviceable	0	0	No		10		0	0	Deny	
<input type="checkbox"/>		0	1		RIM SHAFT	Cut	0	125	No		10		112.5	112.5	Reviewing	
<input type="checkbox"/>		0	1		SPORT RIM	Repair	0	0	No		10		0	0	Deny	
<input type="checkbox"/>		0	1		FRONT DISC	Serviceable	0	0	No		10		0	0	Deny	
<input type="checkbox"/>		0	1		STEERING CONE BEARING	Necessary	0	125	No		10		112.5	112.5	Reviewing	
<input type="checkbox"/>		0	1		STEEM STEERING	Serviceable	0	0	No		10		0	0	Deny	
<input type="checkbox"/>		0	1		FRONT SIGNAL LH	Cut	0	120	No		10		108	108	Reviewing	
<input type="checkbox"/>		0	1		FRONT SIGNAL RH	Serviceable	0	0	No		10		0	0	Deny	
<input type="checkbox"/>		0	1		HEAD LAMP COVER LH	Cut	0	160	No		10		144	144	Reviewing	
<input type="checkbox"/>		0	1		HEAD LAMP COVER O/S	Serviceable	0	0	No		10		0	0	Deny	
<input type="checkbox"/>		0	1		METER	Serviceable	0	0	No		10		0	0	Deny	
<input type="checkbox"/>		0	1		FRONT FENDER	Cut	0	185	No		10		166.5	166.5	Reviewing	
<input type="checkbox"/>		0	1		TANK COVER LH	Cut	0	250	No		10		225	225	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		FRONT BODY COVER L/H	Cut	0	450	No		10			405	Reviewing	
<input type="checkbox"/>		0	1		FRONT BODY LOWER COVER L/H	Cut	0	299	No		10			269.1	Reviewing	
<input type="checkbox"/>		0	1		GEAR PEDDAL	Serviceable	0	0	No		10			0	Deny	
<input type="checkbox"/>		0	1		FRONT FOOT REST L/H	Cut	0	75	No		10			67.5	Reviewing	
<input type="checkbox"/>		0	1		REAR FOOT REST L/H	Cut	0	75	No		10			67.5	Reviewing	
<input type="checkbox"/>		0	1		REAR SWING ARM L/H	Serviceable	0	0	No		10			0	Deny	
<input type="checkbox"/>		0	1		SEAT COVER L/H	Cut	0	250	No		10			225	Reviewing	
<input type="checkbox"/>		0	1		L BAR	Serviceable	0	0	No		10			0	Deny	
<input type="checkbox"/>		0	1		REAR SIGNAL LH	Cut	0	120	No		10			108	Reviewing	
<input type="checkbox"/>		0	1		REAR SIGNAL RH	Serviceable	0	0	No		10			0	Deny	
<input type="checkbox"/>		0	1		REAR BOX	Cut	0	450	No		10			405	Reviewing	
<input type="checkbox"/>		0	1		FRONT TYRE	Serviceable	0	0	No		10			0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		FRONT BRAKE PUMP	Serviceable	0	0	No		10		0	0	Deny	
<input type="checkbox"/>		0	1		REAR BOX BAR	Bent	0	150	No		10		0	135	Reviewing	
<input type="checkbox"/>		0	1		IU UNIT	Serviceable	0	0	No		10		0	0	Deny	
<input type="checkbox"/>		0	1		GEAR CHAIN COVER	Damaged	0	95	No		10		0	85.5	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>		0		TRANSPORTATION CHARGES	0	0	0	0	Deny		
<input type="checkbox"/>		0		TO CHECK FRONT AND REAR ELECTRICAL WIRING	0	0	0	0	Deny		
<input type="checkbox"/>		0		TO REMOVE, REFIX AND REALIGN FRONT FORK	0	0	0	0	Deny		
<input type="checkbox"/>		0		TO STRAIGHTEN, REPAIR AND REALIGN CHASSIS FRAME MEMBER	0	0	0	0	Deny		
<input type="checkbox"/>		0		TO RESPRAY PAINTING AND ETC	0	280	0	0	Reviewing		
<input type="checkbox"/>		0		PANEL BEATING, CUT, WELD REMOVE AND REPLACE ABOVE PARTS	0	300	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)[Add](#)[Approve](#)[Deny](#)[Submit All](#)

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
<input type="checkbox"/>		0	GEAR CHAIN	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	YAMAHA EMBLEM	Reviewing		45	NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Estimated Claim Amount \$0.00

Adjusted Claim Amount \$4,390.60

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$3,765.60
Labour	\$0.00	\$580.00
Miscellaneous	\$0.00	\$45.00

[Submit for Review](#)



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

- Add
- Approve
- Deny
- Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	FINAL LUMP SUM	Reviewing		3500		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount \$0.00

Adjusted Claim Amount \$3,500.00

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$3,500.00

Submit for Review