

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 14.12.2020
Time: 16:36:29
Page: 1

NEW - PIP-
JM

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305439040
REGN NO : SHA2405C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 14.05.2019
DATE/TIME IN : 14.12.2020 13:20
ACCIDENT DATE : 14.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-0573-G	IONIQVC PANEL-FENDER RH#	1	588.80	20.00	471.04
0002	04-01-0104-2915-G	IONIQV1-3 LAMP ASSY-HEAD	1	1,993.65	20.00	1,594.92
0003	04-01-0104-3913-G	IONIQVC EMBLEM-BLUE DRIVE	1	26.60	20.00	21.28
0004	04-01-0104-3918-G	IONIQVC BRACKET-FR BUMPER	1	28.00	20.00	22.40
0005	04-01-0104-2534-G	IONIQV2&3 COVER-FR BUMPER	1	430.90	20.00	344.72

SUB-TOTAL : 2,454.36

837.04

837.04

1080.00

1917.04

4 days

JOB NATURE

0000	PB	PANEL BEATING
0001	SP	SPRAYPAINT CHARGE
0002	17-01	CHECK ALL LIGHTING
0003	20-00	TUFF COAT ON AFFECTED PARTS.

700.00 640

500.00 400

500.00 30? XAN

500.00 40

1080

SUB-TOTAL : 1,300.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

4p 900.00 68

4 days

P/P

14/12/2020 @ 1740

Resurvey before paint