



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20013865/T1vd3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 08-01-2021
189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 9889J	Veh. Inspected	SHD 8869S
Policy No.	5109043553-01	Coverage (\$)	0.00
Claim No.	MT/1113274-002	Excess (\$)	0.00
Assign From		Assign Date	14/12/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE	c.c	2493
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	AYH300088686	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R15	WEST LAKE	6 mm
L/H Front Tyre	205/60 R15	WEST LAKE	6 mm
R/H Rear Tyre	205/60 R15	WEST LAKE	6 mm
L/H Rear Tyre	205/60 R15	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/12/2020	Inspection Date	14/12/2020
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------