

ASS. REC. BY: Taught

REF:

CC4/AG20013870

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$90K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SBR 90X Yr Regn: 2015, JuneType: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vellfire C.C. 2493Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 80854 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AGH300014648Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/60 R17R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 27/4/21 05pmSurvey held at AP AutoDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.B. (\$)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

(01)Bent (02)Dented (03)Distorted (04)Cracked (05)Con (06)Scratched (07)Deformed
(08)Stiffed (09)Ductiled (10)Broken (11)Measuring (12)Missing (13)Pore
(14)Unmodified (15)Not Working

MOTOR CAR (Fr)

(1)Replaced (✓) (2)Repair (X) (3)Check (?)
(4)Not Corrosive (NC)

Vehicle No: **SR90X**

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Fr Number Plate			
1002	991887	Fr Number Plate Base			
1003	991889	Fr Number Plate Garnish			
1004	991300	Fr Bumper	Rx		
1005	992341	Fr Bumper Clips	nc	✓	
1006	991325	Fr Bumper Bracket			
1007	991462	Fr Bumper Side Retainer			
1008	991433	Fr Bumper Reinforcement			
1009	991318	Fr Bumper Beam			
1010	991468	Fr Bumper Spouse			
1011	991427	Fr Bumper Protector			
1012	991420	Fr Bumper Pad			
1013	991363	Fr Bumper Grille			
1014	991301	Fr Bumper Moulding			
1015	991407	Fr Bumper Lower Spoiler			
1016	991438	Fr Bumper Sensor			
1017	995100	Fr LH Bumper Fog Lamp Cover			
1018	991355	Fr RH Bumper Fog Lamp Cover			
1019	995079	Fr LH Bumper Fog Lamp			
1020	995080	Fr RH Bumper Fog Lamp			
1021	991793	Fr Grille			
1022	991328	Fr Grille Emblem			
1023	991799	Fr Grille Chrome Moulding			
1024	991222	Fr Apron Panel			
1025	992013	Fr Support Panel			
1026	992025	Fr Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Fr Brace Panel			
1029	995153	Fr LH Headlamp Assy			
1030	991821	Fr RH Headlamp Assy			
1031	995088	Fr LH Side Lamp			
1032	995089	Fr RH Side Lamp			
1033	990248	Bonnet			
1034	991338	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowlng			
1054	992742	Radiator Fan Assy			
1055	992743	Radiator Fan Clutch			
1056	992738	Radiator Hose Top			
1057	992737	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Fr Exhaust Manifold			
1064	991713	Fr Exhaust Manifold Cover			
1065	991054	Fr Exhaust Manifold Sensor (Oxygen)			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Fr LH Chassis Member			
1093	991520	Fr RH Chassis Member			
1094	990728	Fr Vertical Cross Member			
1095	991863	Fr Lower Cross Member			
1096	995070	Fr LH Fender			
1097	995072	Fr LH Fender Inner Panel			
1098	995147	Fr LH Fender Lamp			
1099	995148	Fr LH Fender Protector			
1100	991740	Fr LH Fender Inner Shield			
1101	995179	Fr LH Mudflap			
1102	995170	Fr LH Wheel Rim			
1103	994025	Fr LH Rim Cover			
1104	995065	Fr LH Tyre			
1105	995071	Fr RH Fender			
1106	991739	Fr RH Fender Inner Panel			
1107	991744	Fr RH Fender Lamp			
1108	991752	Fr RH Fender Protector			
1109	991740	Fr RH Fender Inner Shield			
1110	991884	Fr RH Mudflap			
1111	992087	Fr RH Wheel Rim			
1112	994025	Fr RH Rim Cover			
1113	995065	Fr RH Tyre			
1114	992093	Fr Windscreen Glass			
1115	992117	Fr Windscreen Rubber			
1116	992108	Fr Windscreen Moulding			
1117	992098	Fr Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Fr Wiper Arm			
1121	992142	Fr Wiper Blade			
1122	995043	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Fr Driver Seat			
1133	991922	Fr RH Seat Belt Assy			
1134	991899	Fr Passenger Seat			
1135	995182	Fr LH Seat Belt Assy			