# COMFORTDELGRO

Sheet1

SHA1251K

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdae.com.sa

Company Registration No: 199506048W

Workshops

Braddell 205 Braddell Road Singapore 579701

59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Senoko 24 Senoko Loop Singapore 758156

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

Defu 6 Defu Avenue 1

Singapore 539537

Marymount 600 Sin Ming Avenue Singapore 575733

Time of Fax:

Attn: Motor Claims Dept.

**Dear Sirs** 

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO

1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.

- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find:
  - I) Our initial estimate of repairs of the damaged vehicle.
  - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng Jumari Masudin Tel no. 621483\$5 or Hp no. 98240811 Tel no. 62148315 or Hp no. 96355305

Chiang Liat Choon

Tel no. 62148314

Lim Tien Siong

Tel no. 62148398 or Hp no. 96358546

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully

Vice President

Crash Repairs & Claims Recovery







# **CITYCAB PTE LTD REPAIR ESTIMATE**

Vehicle No.: Make

**SHA1251K** 

**TOYOTA PRIUS** 

Model : DOA

Date Insurance:

MVA CHIANG /AIG

| Qty                 | Parts Description / Labour   | Qty     | Unit Price   | Amount     |
|---------------------|------------------------------|---------|--------------|------------|
|                     |                              | STONE   |              | TO END     |
| 1                   | REAR BUMPER                  |         |              | \$458.60   |
| 10                  | BUMPER CLIPS                 |         |              | \$22.00    |
| 2                   | REAR BUMPER SIDE RETAINER LH |         |              | \$112.70   |
| 1                   | TOWING COVER                 |         |              | \$82.70    |
| Vince With State of | SUB TOTAL                    |         |              | \$676.00   |
|                     | LESS 25%                     | 8011    |              | \$169.00   |
|                     |                              |         |              | \$507.00   |
|                     |                              |         |              |            |
| 1                   | REAR BUMPER MAT              |         |              | 50.00      |
| 1                   | PETROL STICKER               |         |              | 15.00      |
| 1                   | REVERSE SENSOR               |         |              | 135.70     |
|                     |                              |         |              | \$200.70   |
|                     | Labour Charge                |         |              | _          |
|                     | PANEL BEATING                |         |              | 500.00     |
|                     | SPRAY PAINTING               |         |              | 500.00     |
|                     | WIRING                       |         |              | 60.00      |
|                     | TUFF KOTE                    |         |              | 60.00      |
|                     | REMOVE/REFIX REVERSE SENSOR  |         |              | 60.00      |
|                     | TOTAL LABOUR                 | A STATE |              | \$1,180.00 |
|                     | ESTIMATE TOTAL               |         | CHICK STREET | \$1,887.70 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

SC1I20CF000M / COMFORTDELGRO ENGINEERING PTE LTD [508969]

ENTRY DATE & TIME: 15/12/2020 14:41 (SGT) SUBMITTED BY: Janet Lim Siang Gek VERSION: 1 (15/12/2020 14:41 (SGT))

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission 15/12/2020 14:41 (SGT) Date of Accident 14/12/2020 15:25 (SGT) Exact Location of Accident Moulmein Rd, Singapore Additional Location Information 143 MOULMEIN RD Country/State of Loss Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SHA1251K

#### INSURED/POLICYHOLDER

Is company? Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD Company Reg No 1XXXXXXXX1R Email Address FLEETSAFETY@CDGETAXI.COM.SG Mobile Phone No (Phone) +65-65508768 Alternative Phone No (Office) +65-65508768

### **VEHICLE PARTICULARS**

Manufacturer

Toyota Model Prius Variant Exact purpose for which vehicle was being used at time of accident Private hire Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category

#### **INSURANCE COMPANY**

Name of Insurance Company India International Type of Coverage ThirdPartyFireTheft Fleet Policy Yes Policy Number MCOM0015 Cover Note Number

#### DRIVER

Name of Driver WONG YONG FATT MICHAEL NRIC No SXXXX215I Date Of Birth 12/07/1951 Occupation Outdoor

Date Of Driving Pass 26/10/1976 Driving experience 44 YEARS AND 2 MONTHS Gender Male Mobile Number (Phone) +65-82271552 Alt. Phone Number Email Address FLEETSAFETY@CDGETAXI.COM.SG Address BLK 123 TOA PAYOH LOR 1 Address complement #07-521 Postcode 310123 Is the driver the policyholder? Nο If No, Relationship of the Driver with the Insured Other Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident ..... Collision - Head to Rear Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER ATTACHED \* TYPE OF ACCIDENT :- 3P REVERSED ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1** 

| Vehicle Registration Number Vehicle Manufacturer | SMQ1067H<br>Mitsubishi |
|--|------------------------|
| Vehicle Model                                    | :\=:                   |
| Vehicle Variant                                  | <b>(a)</b>             |
| Vehicle Colour                                   | ~~<br>**               |
| Vehicle Category                                 | Private car            |
| Name of Driver                                   | UNKNOWN                |
| Contact Number                                   | (Phone) +65-90605140   |
| Address  | •                      |
| Address complement                               |                        |
| Postcode   | Maria<br>Care          |

Insurance Company Name AIG
Nature Of Damage SLIGHT
Details of property damaged in accident REAR RH
No. Of Passenger (Including Driver) 1

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material 3 facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation. 5.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information setout in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which my be sited outlisde of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared/disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or ourt orders.

COMFORT TRANSPORTATION PTE LTD CO, REG. NO. 199303821R

Policyholder's Signature Date & Time:

Driver's Signature (if driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/Fin No.:

Olivia Wendy 15 10 2020

| SKETCH PLAN  |
|--|
| A = SHA 1251K  |
| $\mathcal{C}_{a}$  |
| B= SM@ 1067H 145 TA  |
| (MITEUBISHI)   |
| 200 02: 04: 44   |
| Video Timing Pm 03: Du: 41   |
| DESCRIBE CIRCUMSTANCES OF THE ACCIDENT   |
| 143 Moulmen Rd to drop off my passenger.   |
| Milter my passenger alighted, there's a vehicle of emato67H was reversing aut. So I honked to alert the driver, however the driver did not ctop and the vehicle rear right portion coilided and my taxis left rear portion.  No injury at the point of arcident. |
|  |

# **DECLARATION**

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature Date & Time:

Driver's Signature (if driver is not the policyholder)
Date & Time: Reporting Centre Personnel's Signature Name: Olivia Wendy NRIC/Fin No.:

(5 )FI. 200