CS3/CTI200/0588/QSd3 ASS. REC. BY: Sun Pin ASSIGNMENT Yr Regn: 26/02/2009 SJN 7645 B Veh No: From: Dale: Type: M.Car M.Cycle / Bus / Van / Lorry /. Taxl / Prime Mover / Eslimaled Cost: Truck / Traller or OD/TP/WS/TP RES/OD RES/EVA/INV/MV Touota Wish 1.8 Make: To Inspect Vehicle No: . A/C: Insured / Std / NI / NA ul Workshop m/s T/Radio: Insured / Std / NI / NA Sp.Reading Eng/No: Insured: . JTDER12W603002160 C/No: Policy No. Gen. Cond: Good (Fair Poor / Burnt Claims No. Sleering: Inorder / Jammed / Leaked / Burnt or Sum Insured: Excess: Brake: Inorden/Jammed/Leaked/Burnt or (Client's Record) Modl: NII SIRIM I STD AIRIM or Make of Veh: 145/65 R15 Tyre Size: 145/65 R15 (Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA (MIC) OHTSU / PIR / SUMI / N/S O/S Remark: The veh had commenced Its TOYO / YOKO or \$ repair at the time of inspection. Rear Bal. or Market Value: Fron R/Bal, R/Bal. Consistent?: Yes or No IDAC Accident Rport: mm UEal. UBal. Consistent?: Yes or No mm mm GIA / PR Seen: 0.0.1. 05/10/2020 D.O.A. 25/09/2020 Res.: Yes or No Est. Repairs: M C-Cap 3 Val.: Yes or No Survey held at Lum Sum: Real I OIS I NIS I UIC I Roollop or Des. of Damages (Frt) / CA | REV | REP. | 24 HRS Vehicle: IN/OUT Person Contacted: The UIC / Chassis frame I Body Structure affected due to collision. Dale / Time Action / Instruction *No Damage 1414: 25,000 PV: 10,819 NV: 14,18 INDICATE "THE VEHICLE HAD COMMENCED ITS REPAIR AT THE TIME OF INSPECTION" IN REPORT Dale/Tine, Fle Pass to?... : Prell. Report Days Of Repair: 06/10/2020 Survey Fee: Resurvey No. of Trlp: : Final Report I TYPIST Transportation: Date/Tyne, File Return to? Add Fee: : Site Insp (\$ S + RS__S/ : Interview (\$ Pholos Tech. Inva (\$ CHINACE Popped Formel: : West and is Long Sum / LEU: Ca TOTAL