

ASS. REC. BY:

REF:

AIG/ CS/AIG20013897/Kqd3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

① TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s

Teng Luck

of _____

Insured: _____

Policy No. 0999993880

Claims No. 8849829089SG

Sum Insured: _____ Excess: 1400

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 865K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

GBT 8965L

Yr Regn:

09, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Transporter C.G. 1968

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

34807

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No:

WV1 888 FH BKH 03 2202

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S/Rlm / STD A/Rlm or

Tyre Size:

F: 7

215/60R16

R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal.

6

mm

R/Bal.

9

mm

L/Bal.

6

mm

L/Bal.

9

mm

D.O.A.

4/12/20

D.O.I.

16/12/202

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/12/20@8.32am revert to AIG via Merimen.

17/12/20@9.15am Kok Chong informed C/A via Merimen.

17/12/20@10.03am Informed wksp C/A & ex:\$1400 by email.

23/12/20@9.24am 2nd revert to AIG via Merimen (Supplementary)

28/12/20@3.55pm Kok Chong approve supplementary via Merimen.

28/12/20@4.15pm informed Candy proceed repair supplementary by email.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 04/12/2020

ESTIMATE

NO : QUOT202012-000037(00)

DATE : 09/12/2020

POLICY NO : 999995580

VEH REG NO : GBJ8965L

MAKE/MODEL : VOLKSWAGEN T6 VAN TDI
NWB DSG

CHASSIS NO : WV1ZZZ7HZKH032202

ENGINE NO : CXH179395

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : GBJ8965L

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1	1,180.00	1,180.00 ✓
2 Bonnet hinges - LH/RH	2	95.00	190.00 ✓
3 Bonnet lower lock	1	115.00	115.00 ✓
4 Support Panel	1	780.00	780.00 ✓
5 Brace panel	1	155.00	155.00 ✓
6 Front grille logo	1	75.00	75.00 ✓
7 Front grille logo plate	1	35.00	35.00 ✓
8 Front grille logo base	1	58.00	58.00 ✓
9 Headlamp assy - LH/RH	2	485.00	970.00 ✓
10 Front bumper	1	880.00	880.00 ✓
11 Front bumper reinforcement	1	520.00	520.00 ✓
12 Front bumper reinforcement cover	1	198.00	198.00 ✓
13 Front bumper brackets - RH / LH	2	45.00	90.00 ✓
14 Front bumper side retainer - LH/RH	2	28.00	56.00 ✓
15 Front bumper sponge	1	50.00	50.00 ✓
16 Front bumper moulding - RH / LH	2	65.00	130.00 X
17 Air-con condenser	1	850.00	850.00 ✓
18 Radiator assy (inner)	1	385.00	385.00 ✓
19 Radiator assy (outer)	1	580.00	580.00 ✓
20 Inter-cooler assy	1	680.00	680.00 ✓
			7,977.00
		Add 10%	797.70
			8,774.70
SPECIAL NET			
21 Radiator coolant (tin)	2	60.00	120.00 ✓
22 Front number plate	1	40.00	40.00 ✓
			160.00
LABOUR			
23 To remove and refix air-con condensor, radiator, inter cooler assy and refill air-con gas.	1	150.00	150.00 ✓
24 To panel beat and straighten front chasis frame, front lower cross member, including replacement of parts and align where necessary, to refit and adjust the same.	1	1,000.00	1,000.00 ✓
25 To check and rectify wiring system	1	80.00	80.00 ✓
26 To putty and spray paint on affected areas.	1	1,000.00	1,000.00 ✓



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 04/12/2020

ESTIMATE

NO : QUOT202012-000037(00)

DATE : 09/12/2020

POLICY NO : 999995580

VEH REG NO : GBJ8965L

MAKE/MODEL : VOLKSWAGEN T6 VAN TDI
NWB DSG

CHASSIS NO : WV1ZZZ7HZKH032202

ENGINE NO : CXH179395

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : GBJ8965L

Description	Quantity	Unit Price	Amount
		S\$	S\$
27 To supply artwork and paste sticker on bonnet. <i>(Inland ??)</i>	1	220.00	220.00
			2,450.00
		TOTAL	S\$ 11,384.70
		ADD GST @ 7%	796.93
		GRAND TOTAL	S\$ 12,181.63

SINGAPORE DOLLAR TWELVE THOUSAND ONE HUNDRED EIGHTY-ONE AND CENTS SIXTY-THREE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/12/2020 01:45 (SGT)
Date of Accident	04/12/2020 11:00 (SGT)
Exact Location of Accident	SLE, Singapore
Additional Location Information	SLE TOWARDS WOODLANDS
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBJ8965L

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
Company Reg No	1XXXXX778Z
Email Address	faizal.mohamed@daimler.com
Mobile Phone No	(Phone) +65-68498118
Alternative Phone No	+65-68498118

VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	T6 VAN TDI NWB DSG
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	-

DRIVER

Name of Driver	ZAINI BIN ABDULLAH SANI
NRIC No	SXXXX934E
Date Of Birth	18/12/1978
Occupation	Outdoor

Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

21/04/2008
12 YEARS AND 8 MONTHS
Male
(Phone) +65-87414514
-
faizal.mohamed@daimler.com
NA
-
-
No
Hirer
No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other material or property damaged? Yes
Number of Passengers (Including Driver) 3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name
Gender

PASSENGER 1
Female

PASSENGER 2

Name
Gender

PASSENGER 2
Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD WHEN I ACCIDENTALLY HIT THE REAR OF VEHICLE B. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.


ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer

GBD98Z
Toyota

 Accident report SA0A20C7000D

10.

B:GBD982

SLE TO MEDICATION

K B A

CONFIDENTIAL

←

←

←

REFER TO ATTACHED STATEMENT.

ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD WHEN I ACCIDENTALLY HIT THE REAR OF VEHICLE B. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

7 December 2020 at 12:27 PM

Date/Time:

7 December 2020 at 12:27 PM

