

ASS. REC. BY: Pmm

REF:

CS/CT120013898/Rtd3

083R

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA 1783H

at Workshop m/s TRANSUROKARS

of 27, TANJONG PENJURAN RD

Insured: CTI

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition) arr - 3pm

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 389K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMA 1783H Yr Regn: 2018 / NOV

Type M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: PORSCHE PANAMERA 4SPR C.C 299K

Colour WHITE A/C: Insured / Std / NI / NA

Sp. Reading 28581 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WPO 222972JL181292

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 265/45ZR19

R: \_\_\_\_\_

BS / DUN / EXNOVA / GP / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 01/12/2020 D.O.I. 18/12/2020

Survey held at TRANSUROKARS

Des. of Damages FR Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit 230K</u>
	<u>Finalised amount of \$ 8,253.79 / 3 days of repair is confirmed</u>
	<u>RED:6549.96; 44%</u>

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

2)

Report Format: \_\_\_\_\_

Lump Sum / L.B.A. (\$) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)

☐ Interview (\$ \_\_\_\_\_)

☐ Tech. Invs (\$ \_\_\_\_\_)

☐ Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL



**STUTT GART AUTO PTE LTD**  
**27A TANJONG PENJURU, SINGAPORE 609042**  
**ESTIMATE COST OF REPAIRS**

**EUROKARS GROUP**

**PORSCHE**

<b>CHINA TAIPING INSURANCE (SINGAPORE)</b>		<b>NAME :</b> Mr Virupattur Sridharan Sudarsan		<b>WIP :</b> 11793	
3 Anson Road		<b>ADDRESS :</b> Blk 638 Pasir Ris Drive 1		<b>EXCESS :</b>	
#16-00 Springleaf Tower		#09-554		<b>DATE:</b> 9-Dec-20	
Singapore 079909		Singapore 510638			
<b>ATTN. :</b> MOTOR CLAIMS		<b>TEL :</b>			
<b>FAX :</b>					
<b>VEH NO :</b>	<b>SMA1783H</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	<b>EVA</b> 63310683
<b>CHASSIS NO :</b>	WP0ZZZ97ZJL181292	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	THIRD PARTY
<b>MODEL :</b>	Panamera 4 Sport Turismo	<b>DATE REG.:</b>	15-Nov-18	<b>POLICY NO. :</b>	
<b>NATURE OF WORKS</b>					
<b>S/NO</b>	<b>Parts Description</b>			<b>REVISED</b>	<b>PRICES</b>
		<b>QTY</b>			
1	FRONT BUMPER <i>scd</i>	1	P971-898-010- -		\$ 2,198.80
2	FRONT BUMPER SPOILER <i>de</i>	1	P971-807-541- -OK1		\$ 677.50
3	FRONT GRILLE <i>scd</i>	1	P971-807-683-B -OK1		\$ 288.70
4	FRONT GRILLE LH <i>scd</i>	1	P971-807-681- -OK1		\$ 120.80
5	FRONT GRILLE INSERT TRIM LH ?	1	P971-807-485- -OK1		\$ 97.60
6	FRONT GRILLE SUPPORT DISC ?	1	P971-807-985- -OK1		\$ 92.80
7	DISC BLACK MAT ?	1	P971-807-877- -OK1		\$ 125.50
8	CAMERA HOUSING X	1	P971-807-762- -OK1		\$ 42.20
9	BRACKET FOR CAMERA X	1	P971-807-997- -		\$ 39.50
10	SENSOR ?	6	P5Q0-919-275-B -G2X		\$ 1,485.00
11	SENSOR GASKET <i>scd</i>	6	P5Q0-919-133- -9B9		\$ 18.60
12	NUMBER PLATE BRACKET <i>scd</i>	1	P971-807-999- -OK1		\$ 83.50
13	FOAM PART LH <i>scd</i>	1	P971-807-251- -		\$ 55.50
14	FOAM PART RH <i>scd</i>	1	P971-807-252- -		\$ 55.50
15	FRONT BUMPER REINFORCEMENT ?	1	P971-805-241-E -		\$ 1,080.80
16	FRONT BUMPER SPONGE ?	1	P971-807-550- -		\$ 82.50
17	SUPPORT LOWER REINFORCEMENT ?	1	P971-803-821-B -		\$ 303.20
18	ADDITIONAL HEADLAMP LH <i>scd</i>	1	P971-953-041-H -		\$ 744.10
19		0	0		\$ -
20		0	0		\$ -
<b>TOTAL PARTS</b>					\$ 7,592.10
<b>LESS 10%</b>					\$ 759.21
<b>TOTAL PARTS COST</b>					\$ 6,832.89
<b>Labour Description</b>					
1	TO REMOVE /INSTALL FRONT BUMPER, LOWER SPOILER & ALL DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			<i>1560</i>	\$ <del>3,900.00</del>
2	TO RESPRAY FRONT BUMPER .			<i>1300</i>	\$ <del>1,850.00</del>
3	TO SUPPLY FRONT LICENCE PLATE WITH CASING			NETT	\$ 70.00

	TRANSFER THE FRONT BUMPER SENSORS.	150	\$ 500.00
	TO TRANSFER THE FRONT CAMERA	150	\$ 350.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	180	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 600.00
8	SUNDRIES.	NETT	\$ 20 50.00
		TOTAL LABOUR	\$ - \$ 7,570.00
		TOTAL PARTS	\$ - \$ 6,832.89
		TOTAL	\$ - \$ 14,402.89
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Repair*  
*Hp 90010068*  
*3 days*  
*18/12/2020 @ 1515*  
*Ready before print*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	02/12/2020 17:06 (SGT)
Date of Accident	01/12/2020 12:00 (SGT)
Exact Location of Accident	300 Tampines Ave 5, Singapore 529653
Additional Location Information	NTUC INCOME @ TAMPINES JUNCTION
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA1783H
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	WISH CONTROLS PTE LTD
Company Reg No	2XXXXX083R
Email Address	SALES@WISHCONTROLS.COM
Mobile Phone No	(Phone) +65-91853860
Alternative Phone No	+65-91853860

### VEHICLE PARTICULARS

Manufacturer	Porsche
Model	Panamera
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

### INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1800134765-02
Cover Note Number	-

### DRIVER

Name of Driver	VIRUPATTUR SRIDHARAN SUDARSAN
NRIC No	SXXXX532D
Date Of Birth	07/06/1975
Occupation	Indoor

Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode

11/06/2007  
13 YEARS AND 6 MONTHS  
Male  
(Phone) +65-91853860  
-  
SALES@WISHCONTROLS.COM  
BLK 638 PASIR RIS DRIVE 1 #09-554  
-  
510638  
No  
Employee  
No  
-  
-

Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Hit and run / Vandalism / Damaged whilst parked  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
Number of vehicles involved in the accident 2  
Was anybody injured in the Accident? No  
Was any injured conveyed to hospital by ambulance? -  
Was any other material or property damaged? Yes  
Number of Passengers (Including Driver) 1  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
Was notice of intended Prosecution given? No  
If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO STATEMENT

#### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? No  
Was there any audio recorded? No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number SDN9990L  
Vehicle Manufacturer -  
Vehicle Model -  
Vehicle Variant -  
Vehicle Colour -  
Vehicle Category Private car  
Name of Driver -  
Contact Number -  
Address -  
Address complement -  
Postcode -  
Insurance Company Name -

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





No sketch Plan

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 01/12/2020, I parked my car at NTUC Wilcome at Tampines Junction from 100hrs to 1200hrs. When I returned to collect my car, I saw a note on my front windscreen stating that vehicle had hit on the front position of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



*[Signature]*  
Policyholder's Signature  
Date & Time:

*[Signature]*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	083R
Vehicle No.:	SMA1783H
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2020
Vehicle Make:	PORSCHE
Vehicle Model:	PANAMERA 4 SPORT TURISMO G2 PDK E6 SR
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	032013
Chassis No.:	WP0ZZZ97ZJL181292
Maximum Power Output:	243.0 kW (325 bhp)
Open Market Value:	\$113,185.00
Original Registration Date:	15 Nov 2018
First Registration Date:	15 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$175,733.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Nov 2028
PARF Rebate Amount:	\$131,799.00

COE Expiry Date:	14 Nov 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,900.00
COE Rebate Amount:	\$26,787.00
Total Rebate Amount:	\$158,586.00

The information contained herein is correct as at 20 Dec 2020

OK

White





art.com/used\_cars/info.php?ID=934103&DL=3028

# Porsche Panamera Sport Turismo 4 3.0A PDK

Overview

Financial

Accessories

Similar

Research

Photos

Map



## 360 VR CARS

A subsidiary of 360 HOLDINGS

Price \$386,000

Depreciation ⑦ \$37,300 /yr  
View models with similar depre

Reg Date 11-Oct-2018  
(7yrs 9mths 20days COE left)

Mileage 5,800 km (2.6k /yr)

Manufactured ⑦ 2018

Road Tax ⑦ \$2,380 /yr

Transmission Auto

Dereg Value ⑦ \$166,941 as of today (change)

OMV ⑦ \$120,700

COE ⑦ \$32,001

ARF ⑦ \$189,260

Engine Cap 2,995 cc

Power 243.0 kW (325 bhp)

Curb Weight ⑦ 1,880 kg

No. of Owners ⑦ 1

Type of Vehicle Sports Car

### Features

3.0L V6 Turbocharged Engine With 8 Speed 4 Wheel Drive Transmission Producing 325Bhp And 450Nm Torque. 0 To 100Km/H 5.7 Secs. Fuel Consumption 12Km/L. View specs of the Porsche Panamera (2009-2013)



ASUS