



CYCLE & CARRIAGE

AIG - OD REVERT
SURVEY: 16/12/20
LKK - STEVE

VEHICLE NO : SMP 240 K

MODEL : MIT/ATRAGE 1.2 CVT

WIP : 60765

Material	:	\$	<u>3,174.71</u>
Labour	:	\$	<u>6,645.00</u>
Sub-Total	:	\$	<u>9,819.71</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>9,219.71</u>
GST 7%	:	\$	<u>645.38</u>
Grand Total	:	\$	<u>9,865.09</u>
Finalise By/Date	:	<u>LARRY OW 06/01/21</u>	

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 12 WORKING DAYS + 8 days (3 weekends)
2 P.H



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 16/12/2020	Cust No/Name	KCV12020/F00 MEI LIN ROSELINE MRS.KONG M
	Reg No/Reg Date	SMP240K*DC17P/ 06/09/2019
	Date In/Mileage	16/12/2020/ 11591
	Chassis/Package	MMBSTA13AKH00266E /FTP
	Engine No	3A92UHX8994
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	06/01/2021/ 09:59	BLC	884 / Lauro Songcuan	60765

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, BOOTLID, REAR FENDER LH, REAR LAMP HOUSING LH, REAR END PANEL				2700.00 ✓
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS				240.00 ✓
E PNT88000 REMOVE & INSTALL REAR COMARTMENT TRIMS & REAR FENDER TRIMS				225.00 ✓
E PNT98000 SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR FENDER LH, REAR LAMP HOUSING LH,				1575.00 ✓
M SUNDRY APPLY SEALANT FOR REAR WINDSCREEN				80.00 ✓
M SUNDRY SUPPLY C&C LOGO				40.00 ✓
M SUNDRY APPLY SEALANT FOR AFFECTED PORTIONS				120.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
A 54900099 REMOVE & INSTALL FUEL TANK SYSTEM				225.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00 ✓
E PNT98000 SPRAY PAINT FOR FRONT BUMPER				350.00 ✓
E PNT88000 REPAIR REAR COMPARTMENT → <i>supp.</i>				450.00 ✗
E PNT98000 SPRAY PAINT FOR REAR COMPARTMENT → <i>supp.</i>				350.00 ✗

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 16/12/2020	Cust No/Name	KCV12020/FOO MEI LIN ROSELINE MRS.KONG M
	Reg No/Reg Date	SMP240K*DC17P/ 06/09/2019
	Date In/Mileage	16/12/2020/ 11591
	Chassis/Package	MMBSTA13AKH00266E /FTP
	Engine No	3A92UHX8994
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	06/01/2021/ 09:59	BLC	884 / Lauro Songcuan	60765

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X EXC				-600.00
EXCESS FOR OWN DAMAGE CLAIM				
X FACE,RR BUMPER ✓	1.00	748.00	23.00	575.96 ✓
X BRACKET,RR BUMPER,LH ✓	1.00	28.00	23.00	21.56 ✓
X PANEL,TRUNK LID ✓	1.00	791.00	23.00	609.07 ✓
X WEATHERSTRIP,TRUNK LID ✓	1.00	157.00	23.00	120.89 ✓
X PANEL,QTR,OTR LH ✓	1.00	755.00	23.00	581.35 ✓
X PANEL,RR COMB LAMP HSG,LH ✓	1.00	60.00	23.00	46.20 ✓
X EXTN,QTR PANEL,UPR OTR LH ✓	1.00	118.00	23.00	90.86 ✓
X PANEL,RR END ✓	1.00	425.00	23.00	327.25 ✓
X SPACER,RR WINDOW ✓	3.00	9.00	23.00	20.79 ✓
X STOPPER,WINDSHIELD GLASS ✓	2.00	3.00	23.00	4.62 ✓
X MUD GUARD,RR LH ?	1.00	41.00	23.00	31.57 ?
X MARK,THREE-DIA ✓	1.00	69.00	23.00	53.13 ✓
X MARK,ATTRAGE ✓	1.00	21.00	23.00	16.17 ✓
X BOARD,TRUNK ROOM FLOOR ✓	1.00	195.00	23.00	150.15 ✓
X TRIM,TRUNK ROOM SIDE,LH ✓	1.00	160.00	23.00	123.20 ✓
X LAMP ASSY,COMB,RR LH ✓	1.00	335.00	23.00	257.95 ✓
X BUZZER,KEYLESS OPERATIO,RR ✓	1.00	91.00	23.00	70.07 ✓
X ANT,KEYLESS OPERATION,RR ✓	1.00	96.00	23.00	73.92 ✓
Z TEXT				
OD CLAIM AIG - TP RECOVERY				
DOA: 15/12/2020				
SURVEY: STEVE (LKK) 16/12/2020				
12 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,174.71			
Labour	6,385.00			
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00			
Sundry/Others	-340.00			
Total(w/o GST)	9,219.71			
		7% GST on	9219.71	9,219.71
				645.38
		Total Payable		9,865.09

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMP 240 K

	<u>Labour</u>	<u>Cost \$</u>
1	Repair Rear Compartment	450.00
2	Spray Paint Rear Compartment	350.00
		<u>800.00</u>
	7% GST	56.00
	Total	<u>856.00</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SWP240K

WIP: 60765

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	MUD GUARD, RR LH	2 / SUPP			
2	to 450	2 / SUPP			
3		2 / SUPP			
4	Repair RR Compartment \$ 450	2 / SUPP			
5	Spray : \$ 350	2 / SUPP			
6		2 / SUPP			
7		2 / SUPP			
8		2 / SUPP			
9		2 / SUPP			
10		2 / SUPP			
11		2 / SUPP			
12		2 / SUPP			
13		2 / SUPP			
14		2 / SUPP			
15		2 / SUPP			
16		2 / SUPP			
17		2 / SUPP			
18		2 / SUPP			
19		2 / SUPP			
20		2 / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	23/12/20	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: average

SURVEYOR: Steve

Work Order: R001297
License: SMP240K
Technician: ALVIN (108)
Mileage: 28459
Date: 4.1.21 15:51

Mitsubishi : Mirage/Attrage : 2012- (Including G4)

Front : Left

Actual	Before	Specified Range
-0°39'	-0°39'	-0°40' 0°50'
3°37'	3°38'	3°15' 4°45'
0°00'	-0°15**	-0°07' 0°07'
14°17**	14°14**	10°05' 13°05'
13°38'	13°35'	9°25' 13°55'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°30'	-0°28'	-0°40' 0°50'
4°41'	4°42'	3°15' 4°45'
0°01'	-0°18**	-0°07' 0°07'
12°49'	12°47'	10°05' 13°05'
12°19'	12°19'	9°25' 13°55'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°10'	-0°11'	-0°30' 0°30'
-1°04**	-1°04**	-0°30' 0°30'
1°28'	1°27'	
0°01'	-0°33**	-0°14' 0°14'

Rear : Left

Actual	Before	Specified Range
-1°09'	-1°09'	-1°45' -0°15'
0°05'	0°05'	-0°01' 0°13'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°21'	-1°21'	-1°45' -0°15'
0°09'	0°09'	-0°01' 0°13'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°12'	0°12'	-0°30' 0°30'
0°15'	0°14'	-0°02' 0°26'
-0°02'	-0°02'	

Work Order: R001297
License: SMP240K
Technician: ALVIN (108)
Mileage: 28459
Date: 4.1.21 15:51

Mitsubishi : Mirage/Attrage : 2012- (Including G4)

Front : Left

Actual	Before	Specified Range
-0°39'	-0°39'	-0°40' 0°50'
3°37'	3°38'	3°15' 4°45'
0°00'	-0°15'	-0°07' 0°07'
14°17'	14°14'	10°05' 13°05'
13°38'	13°35'	9°25' 13°55'

Front : Right

Actual	Before	Specified Range
-0°30'	-0°28'	-0°40' 0°50'
4°41'	4°42'	3°15' 4°45'
0°01'	-0°18'	-0°07' 0°07'
12°49'	12°47'	10°05' 13°05'
12°19'	12°19'	9°25' 13°55'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°10'	-0°11'	-0°30' 0°30'
-1°04'	-1°04'	-0°30' 0°30'
1°28'	1°27'	
0°01'	-0°33'	-0°14' 0°14'

Rear : Left

Actual	Before	Specified Range
-1°09'	-1°09'	-1°45' -0°15'
0°05'	0°05'	-0°01' 0°13'

Rear : Right

Actual	Before	Specified Range
-1°21'	-1°21'	-1°45' -0°15'
0°09'	0°09'	-0°01' 0°13'

Camber
Toe

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°12'	0°12'	-0°30' 0°30'
0°15'	0°14'	-0°02' 0°26'
-0°02'	-0°02'	

All DTCS

2020.12.31

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	A13A 2019MY

SMP 240 K -

↳ M.O.T. III Diag. chk -

↳ Read DTC only -

Before

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCs	
AT/CVT/A-MTTC-SST	KOSOSS_99880010		No DTCs	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCs	
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCs	
SRS-AIR BAG	KOSOSS_99880010		No DTCs	
Air Conditioner	KOSOSS_99880010		No DTCs	
ETACS	KOSOSS_99880010	B1707	Flasher open	Active
Meter	KOSOSS_99880010	B1201	Fuel information problem	Stored
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/MMMO/Keyless (with KOS)	KOSOSS_99880010	B1136	Stop lamp switch	Stored

All DTCS

Item	Setting	Information
M.U.T.-3 Version		SEW20091-00
V.C.I. Version		B178
Vehicle Information		A13A 2019MY

SMP240K

After Repair to engine bus-3x not unit to check and

to erase all the found

Job Done.

2021.01.04

All DTCs

2021.01.04

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCs	
AT/CVT/A-MT/C-SST	KOSOSS_99880010		No DTCs	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCs	
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCs	
SRS-AIR BAG	KOSOSS_99880010		No DTCs	
Air Conditioner	KOSOSS_99880010		No DTCs	
ETACS	KOSOSS_99880010		No DTCs	
Meter	KOSOSS_99880010		No DTCs	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCs	