


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. 1900020308  
 Claims No. 8940143662SG  
 Sum Insured: \_\_\_\_\_ Excess: 600  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SMJ 70590 Yr Regn: 18/3/19  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: KIA Cerato c.c. 1591  
 Colour: Blue A/C: Insured / Std / NI / N  
 Sp. Reading: 17790 T/Radio: Insured / Std / NI / N  
 Eng/No: \_\_\_\_\_  
 C/No: KNAT1416 MK5025200  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brakes: Inorder / Jammed / Leaked / Burnt or  
 Mod: NII / S/Rlm / STD A/Rlm or  
 Tyre Size: F: 195/65R15  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Kumho  
 Front Rear  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 13/12/20 D.O.I. 14/12/20  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Frt LH  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>INV-67K</u>
16/12/20	Seek mandate via merimen
17/12/20	Rece approved from Kok Chong via merimen
17/12/20	Informed Coco C/A excess \$600 by email
22/12/20	Final fig \$4276.40 confirmed by email (Red 2569.60, 37%)

Date/Time, File, Pass to? ☐ : Prel. Report  
☐ : Final Report

Date/Time, File Return to?

22/12/20-Typist

Rep. Formed: Merimen

Lump Sum / L.F. / % \$4276.40

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ )  
☐ : Interview (\$ )  
☐ : Tech. Invs (\$ )  
☐ : Weekend (\$ )

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08915/LOH YUE THONG Reg No/Reg Date SMJ7059D / 18/03/201 Date In/Mileage / 0 Chassis No KNAF1416MK5025200 Engine No G4FGJH714153 Make/Model KIA/CERATO 1.6 A L S116 Colour/Trim BBL HORIZON BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	14/12/2020/ 09:54		442 / CocoLu	25707		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							800 1600.00
RENEW FRT BUMPER, FRT FENDER LH, FRT SUPPORT PENEL , 479 X2							
REPAIR FRT DOOR LH, BONNET							?
E PNT88000							100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR							
E PNT98000							700 1400.00
SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, FRT DOOR LH, 750 X2							
BONNET							20.00
M SUNDRY							30.00
Sundry							
A 90000001							120.00
CHECK WIRING & ELECTRICAL SYSTEM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
B WHEELALIGNMENT							120.00
To Conduct Computerize Full Wheel Alignment							
M COVER-FR BUMPER	BR			1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER	CUT			1.00	262.00	20.00	209.60
M LAMP ASSY-DAY RUNNING LIGHT, LH	X			1.00	203.00	20.00	162.40
M MOULDING-FRONT BUMPER, LH	CUT			1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER, LH	CUT			1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER, LH	BR			1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY	X			1.00	84.00	20.00	67.20
M BRACKET-FR BUMPER UPR SIDE MTG	BR			1.00	22.00	20.00	17.60
M PANEL-FENDER, LH	BR			1.00	430.00	20.00	344.00
M CARRIER ASSY-FRONT END MODULE	?			1.00	675.00	20.00	540.00
M LAMP ASSY-HEAD, LH	BR			1.00	1040.00	20.00	832.00
M GUARD ASSY-FRONT WHEEL, LH	CR4			1.00	95.00	20.00	76.00
M DUCT ASSY-EXTENSION (Rear)	BR			1.00	115.00	20.00	92.00

Estimate

Steve CLKK)

14/12/20, 12:00pm

OD - NM AL

Excess - ?

P/P

# Estimate

Steve CLKK)  
14/12/20, 19.00.00  
OD - NM AL  
Excess - ?  
P/P

**Confirm & accepted by**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

\* Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Nett 6,391.60  
7% GST on 6391.60 447.41  
Total Payable 6,839.01

By Bot &  
4 days

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	14/12/2020 10:47 (SGT)
Date of Accident	13/12/2020 15:00 (SGT)
Exact Location of Accident	238 Thomson Rd, Singapore 307683
Additional Location Information	NOVENA SQUARE CARPARK
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMJ7059D

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LOH YUE THONG
NRIC No	SXXXX985B
Email Address	YUETHONGSINGAPORE@ICLOUD.COM
Mobile Phone No	(Phone) +65-91522539
Alternative Phone No	+65-91522539

#### VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

#### INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900020308
Cover Note Number	-

#### DRIVER

Name of Driver	LOH YUE THONG
NRIC No	SXXXX985B
Date Of Birth	10/11/1961
Occupation	Indoor



Date Of Driving Pass .....  
Driving experience .....  
Gender .....  
Mobile Number .....  
Alt. Phone Number .....  
Email Address .....  
Address .....  
Address complement .....  
Postcode .....  
Is the driver the policyholder? .....  
If No, Relationship of the Driver with the Insured .....  
Does Driver Own Other Vehicles? .....  
Vehicle Registration Number of Other Vehicle Owned by Driver .....  
Insurance Company of Other Vehicle Owned by Driver .....

04/05/1988  
32 YEARS AND 7 MONTHS  
Male  
(Phone) +65-91522539  
+65-91522539  
YUETHONGSINGAPORE@ICLOUD.COM  
25 PASIR RIS LINK #09-13  
-  
518150  
Yes  
-  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....  
Weather Conditions .....  
Road Surface .....

Collided into Property  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....  
Number of vehicles involved in the accident .....  
Was anybody injured in the Accident? .....  
Was any injured conveyed to hospital by ambulance? .....  
Was any other material or property damaged? .....  
Number of Passengers (Including Driver) .....  
Has the driver been approached by unknown person(s)  
soliciting/offering accident claims assistance? .....

No  
1  
No  
-  
No  
1  
No  
No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....  
Was notice of intended Prosecution given? .....  
If yes, against whom? .....

No  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

Are accident photos available for attachment? .....  
Was there any video captured by Car Camera? .....  
Was there any audio recorded? .....

Yes  
No  
No

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

14 DEC 2020

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



# NOVENA CAR PARK (TOWARDS EXIT SLOPE DOWN)



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was exiting from Novena Square carpark at about 1500 hours.

The car hit the wall (on the left side of the front of the car) on a downward slope.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

x

Policyholder's Signature

Date & Time:

14 DEC 2020

Doc No: 14 DEC 2020

x

Driver's Signature

(If driver is not the policyholder)

Date & Time:

14 DEC 2020

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

**AIG AUTO PROTECTOR PRIVATE VEHICLE**  
Name of Policyholder : LOH YUE THONG  
Period of Insurance : 18 Mar 2019 To 17 Mar 2021  
Engine No. : G4FGJH714153  
Chassis No. : KNAF1416MK5025200

Vehicle No. : SMJ7059D  
Policy No. : 1900020308  
Endorsement No. :  
Issued Date : 22 Mar 2019

**ABOUT THE COVER**

Make/Model : KIA Cerato  
Engine Capacity/Tonnage : 1,591.00 CC  
Driver Restriction : NA  
Person or Classes of Persons Entitled to Drive\* :

Sum Insured : Market Value  
Off Peak Car : No

First Year of Registration : 2019  
Insuring with COE/PAF : Yes

- a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition  
Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**EXCESS**

Section 1  
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2  
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LOH YUE THONG - \$600 (Own Damage)

**APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)**

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

**IMPORTANT NOTES**

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622224

C&CKICP2 - MELVIN  
239 ALEXANDRA ROAD  
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*Manile*  
AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORISED REPRESENTATIVE

1002054286/ACA/Docal