

Nivitha (LKK Auto)

From: AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>
Sent: Wednesday, 16 December 2020 1:07 PM
To: Admin A; assignments
Cc: Lim, Kok-Chong
Subject: Agency E/5143/2020, SBS6875D - need surveyor ?

Hi LKK,

Kindly assist to survey.

Winnie Fan

Claims Service Associate - Auto
AIG Asia Pacific Insurance Pte. Ltd.

AIG Building
78 Shenton Way, Level 10
Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

From: Seow Yong Hua <seowyh@sbstransit.com.sg>
Sent: Wednesday, December 16, 2020 1:04 PM
To: AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>
Cc: Yao Tianhao <yaoth@sbstransit.com.sg>; Andrew Goh Poh Leong <andrewgoh@sbstransit.com.sg>; Zee Chee Wah <zecw@sbstransit.com.sg>; Erik Toh Ping Khim <erikto@sbstransit.com.sg>; Chong Yong Guang <chongyg@sbstransit.com.sg>; Tham Meng Khuan <thammk@sbstransit.com.sg>
Subject: [EXTERNAL] Re: E/5143/2020, SBS6875D - need surveyor ?

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Mdm,

Please be informed that an accident involving SBS Transit bus **SBS6875D** and vehicle no: **SKK3108R** had taken place at/along **Yio Chu Kang Road before bus stop 56199** at **1019 hrs** on **11/12/2020**.

Kindly let us know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

We have no objection to your panel of surveyor. Please appoint any surveyor from your panel to conduct the pre-repair survey.

If we do not hear from you within the next 2 working days, we shall proceed to repair our vehicle without further notice to you.

To arrange for the inspection:

Please contact directly with the contact person from workshop as provided below for surveying appointment.

TAC report was lodged, the Report number is: **E/5143/2020.**

Kindly advise whether third party Insurer needs to be notified, or we shall proceed to repair our bus.

SBST Workshop:

4. Workshop Address: **3 Yio Chu Kang Crescent road, Singapore 786010**

5. Name of Contact person (s): **Chong Yong Guang.**

6. Office number: **63754263, h/p : 81335877**

7. Email of contact person: chongyg@sbstransit.com.sg

Dear Tham - Thanks for the CCTV footage. Surveyor is required for this accident. Please hold the bus for 3P car surveyor.

Seow Yong Hua
Investigation Officer
Safety (Bus) Department
SBS Transit Ltd

"Be **SAFE**, Be **HEALTHY**"

From: Tham Meng Khuan <thammk@sbstransit.com.sg>
Sent: Wednesday, 16 December 2020 12:19 PM
To: Seow Yong Hua <seowyh@sbstransit.com.sg>
Cc: Yao Tianhao <yaoth@sbstransit.com.sg>; Andrew Goh Poh Leong <andrewgoh@sbstransit.com.sg>; Zee Chee Wah <zeecw@sbstransit.com.sg>; Erik Toh Ping Khim <eriktoh@sbstransit.com.sg>; Chong Yong Guang <chongyg@sbstransit.com.sg>
Subject: E/5143/2020, SBS6875D - need surveyor ?

Hi Raymond,

- 1) See attached file.
- 2) CCTV : <http://odcctvsrvr/cctvportal/East/SEDP/SEDP2020P2959.zip>

Tham Meng Khuan

Contact No : 63754198

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]