

ASS. REC. BY: Tangth

REF:

A14

CS/AIG20014039/T1qd3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_


Insured: \_\_\_\_\_

Policy No. 1900099733Claims No. 2473289534SGSum Insured: \_\_\_\_\_ Excess: 0/-

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 268K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRSDate: \_\_\_\_\_ Person Contacted: Don

Vehicle: IN / OUT

Veh No: SUML5045X Yr Regn: 2019, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Via Canato c.c. 1591Colour: Red A/C: Insured / Std / NI / NASp. Reading: 16469 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAP3416 MK. 5058769

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Michelin

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. \_\_\_\_\_ D.O.I. 17/12/20Survey held at CRC Pandan GdnDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/12/20@10.37am revert to AIG via Merimen.

18/12/20@12.33pm Kok Chong informed C/A via Merimen.

18/12/20@2.13pm Informed Don C/A &amp; ex:\$0/- by email.

18/01/21@12.31pm confirmed with Larry final fig \$3746, 5 days (Red \$3466.80, 48%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format: MER-ODLump Sum / L.B.R. \$ 3746

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV09893/SREEJITH SATHIANATHAN
	Reg No/Reg Date	SML5045X / 24/05/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5038719
	Engine No	G4FGJH720990
	Make/Model	KIA/CERATO 1.6 A SX SR G518
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
LAX00000	Credit	17/12/2020/ 11:40	QUD	247 / DonBong	25929				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID, REAR BUMPER FACE, REPAIR REAR END PANEL					1200	1600.00		
E PNT88000	REMOVE AND INSTALL PARKING ASSIST					✓	60.00		
E PNT98000	PAINT WORK SPRAY REAR END PANEL, REAR BOOT LID, REAR BUMPER FACE AND AFFECTED PORTION					1440	1920.00		
M SUNDRY	PERFORM RUST PREVENTION					40	80.00		
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM					✓	30.00		
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					✓	120.00		
M SUNDRY	SUPPLY C&C LOGO					✓	40.00		
M SUNDRY	SUNDRIES					20	50.00		
M PANEL ASSY-TRUNK LID						1.00	1297.00	20.00	Rx 1037.60
M LOGO ASSY-KIA SUB						1.00	32.00	20.00	25.60
M EMBLEM-CERATO						1.00	28.00	20.00	22.40
M BRACKET ASSY-RR BPR SIDE UPR,L						1.00	25.00	20.00	20.00
M BRACKET-ASSY RR BPR SIDE UPR,R						1.00	31.00	20.00	24.80
M STAY-RR BUMPER LH						1.00	65.00	20.00	52.00
M STAY-RR BUMPER RH						1.00	65.00	20.00	52.00
M ANTENNA ASSY-SMARTKEY						1.00	46.00	20.00	36.80
M BEAM-RR BUMPER						1.00	318.00	20.00	254.40
M BRACKET-RR BEAM LWR MTG						2.00	6.00	20.00	9.60
M BRACKET-RR BEAM LWR,CTR						1.00	6.00	20.00	4.80
M BRACKET-RR BEAM UPR MTG,LH						1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UPR MTG,RH						1.00	9.00	20.00	7.20
M EXTN WIRING ASSY-BWS						1.00	207.00	20.00	165.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09893/SREEJITH SATHIANATHAN Reg No/Reg Date SML5045X / 24/05/201 Date In/Mileage / 0 Chassis No KNAF3416MK5038719 Engine No G4FGJH720990 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	17/12/2020/ 11:40	QUD	247 / DonBong	25929
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
M LAMP ASSY-SIDE T/SIGNAL,LH	1.00	181.00	20.00	X 144.80	
M LAMP ASSY-SIDE T/SIGNAL,RH	1.00	181.00	20.00	X 144.80	
M COVER-RR BUMPER FOG LAMP,LH	1.00	19.00	20.00	X 15.20	
M COVER-RR BUMPER FOG LAMP,RH	1.00	19.00	20.00	X 15.20	
M GROMMET ASSY-SCREW	2.00	2.00	20.00	hel 3.20	
M CLIP	10.00	1.00	20.00	hel 8.00	
M COVER-RR BUMPER	1.00	651.00	20.00	de 520.80	
M COVER-RR BUMPER LWR	1.00	241.00	20.00	de 192.80	
M ULTRASONIC SENSOR ASSY-BWS	1.00	163.00	20.00	X 130.40	
M ULTRASONIC SENSOR ASSY-BWS	1.00	163.00	20.00	X 130.40	
M ULTRASONIC SENSOR ASSY-BWS	1.00	163.00	20.00	X 130.40	
M ULTRASONIC SENSOR ASSY-BWS	1.00	163.00	20.00	? 130.40	

# Estimate

SURVEYOR NAME : Tanphn 47495749SURVEYOR SIGNATURE : TanphnDATE : 17/12/20 @ 1215REMARKS : Not at house Ex: 169Resurvey before paint 05 days  
Tanphn @ 11:40 AM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirm &amp; accepted by

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

7% GST on **7,186.40** **503.05**

**Total Payable 7,689.45**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission 17/12/2020 12:05 (SGT)  
Date of Accident 16/12/2020 17:30 (SGT)  
Exact Location of Accident Keppel Rd Off Street (K 0108), Singapore  
Additional Location Information EXIT KEPPEL ROAD FROM SENTOSA, NEAR VIVO  
Country/State of Loss Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SML5045X  
INSURED/POLICYHOLDER  
Is company? No  
Name Of Registered Owner SREEJITH SATHIANATHAN  
NRIC No SXXXX506C  
Email Address SREEJITH@GMAIL.COM  
Mobile Phone No (Phone) +65-90214509  
Alternative Phone No +65-90214509

### VEHICLE PARTICULARS

Manufacturer  
Model Kia  
Variant Cerato  
Exact purpose for which vehicle was being used at time of accident -  
Are you claiming under your own insurance policy for repair to your vehicle? -  
Vehicle Category Yes  
Private car

### INSURANCE COMPANY

Name of Insurance Company  
Type of Coverage AIG  
Fleet Policy Comprehensive  
Policy Number No  
Cover Note Number 1900099733

### DRIVER

Name of Driver  
NRIC No SREEJITH SATHIANATHAN  
Date Of Birth SXXXX506C  
Occupation 18/05/1977  
Indoor



Date Of Driving Pass	27/05/2017
Driving experience	3 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90214509
Alt. Phone Number	+65-90214509
Email Address	SREEJITH@GMAIL.COM
Address	BLK 192B RIVERVALE DRIVE #09-940
Address complement	-
Postcode	542192
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	PASSENGER
Gender	Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFL6600U
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	CHIONG KOK
Contact Number	(Phone) +65-97306824

Address	-
Address complement	-
Postcode	-
Insurance Company Name	China Taiping Insurance
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature

Date & Time:

17/12/2020  
10.45am

  
Driver's Signature

(If driver is not the policyholder)


Date & Time:

  
Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

We were coming from Seatosia - forgetting Keppel Road exit. The signal near Vivo City turned orange and I had to apply brake. The car behind could not stop as expected. due to rainy conditions and he banged his car behind. He shared his contact and insurance details and agreed to contact insurance for repair and claims.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

17/12/2012 10.45 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



# CERTIFICATE OF INSURANCE

## KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Sreejith Sathianathan  
Period of Insurance : 24 May 2019 To 23 May 2021  
Engine No. : G4FGJH720990  
Chassis No. : KNAF3416MK5038719

Vehicle No. : SML5045X  
Policy No. : 1900099733  
Endorsement No. :  
Issued Date : 04 Jun 2019

### ABOUT THE COVER

Make/Model : KIA Cerato

Engine Capacity/Tonnage : 1,591.00 CC

Driver Restriction : NA

Person or Classes of Persons Entitled to Drive\* :

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2019

Insuring with COE/PAFF : Yes

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

#### Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

#### Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Sreejith Sathianathan - \$600 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504624204

FULCOKICP2 - FN  
22 UBI ROAD 4 FULCO BUILDING  
SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*Manile*

AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORISED REPRESENTATIVE

SSCNMD

1002271094/AC/Docal