



AIG - OD CLAIM
SURVEY: 17/12/20
LKK - TAUFIKH

VEHICLE NO : SML 5045 X

MODEL : KIA/CERATO 1.6 A SX

WIP : 25929

Material	:	\$	<u>796.00</u>
Labour	:	\$	<u>2,950.00</u>
Sub-Total	:	\$	<u>3,746.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>3,746.00</u>
GST 7%	:	\$	<u>262.22</u>
Grand Total	:	\$	<u>4,008.22</u>
Finalise By/Date : <u>LARRY ON 04/01/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (wk end)

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 22/12/2020	<table> <tr><td>Cust No/Name</td><td>LCV09893/SREEJITH SATHIANATHAN</td></tr> <tr><td>Reg No/Reg Date</td><td>SML5045X / 24/05/2019</td></tr> <tr><td>Date In/Mileage</td><td>23/12/2020/ 16685</td></tr> <tr><td>Chassis/Package</td><td>KNAF3416MK5038719 /KC17P</td></tr> <tr><td>Engine No</td><td>G4FGJH720990</td></tr> <tr><td>Make/Model</td><td>KIA/CERATO 1.6 A SX SR G518</td></tr> <tr><td>Colour/Trim</td><td>CR5 RUNWAY RED / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV09893/SREEJITH SATHIANATHAN	Reg No/Reg Date	SML5045X / 24/05/2019	Date In/Mileage	23/12/2020/ 16685	Chassis/Package	KNAF3416MK5038719 /KC17P	Engine No	G4FGJH720990	Make/Model	KIA/CERATO 1.6 A SX SR G518	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK
Cust No/Name	LCV09893/SREEJITH SATHIANATHAN														
Reg No/Reg Date	SML5045X / 24/05/2019														
Date In/Mileage	23/12/2020/ 16685														
Chassis/Package	KNAF3416MK5038719 /KC17P														
Engine No	G4FGJH720990														
Make/Model	KIA/CERATO 1.6 A SX SR G518														
Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	04/01/2021/ 11:55	BLD	884 / Lauro Songcuan	25929

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW DAMAGED PARTS ON REAR BUMPER FACE, REPAIR REAR END PANEL, REPAIR REAR BOOT LID,				1200.00 ✓
E PNT88000 REMOVE AND INSTALL PARKING ASSIST				60.00 ✓
E PNT98000 SPRAY PAINT REAR END PANEL, REAR BOOT LID, REAR BUMPER FACE AND AFFECTED PORTIONS				1440.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED PORTIONS				40.00 ✓
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUPPLY C&C LOGO				40.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
X LOGO ASSY-KIA SUB ✓	1.00	32.00	20.00	25.60 ✓
X EMBLEM-CERATO ✓	1.00	28.00	20.00	22.40 ✓
X CLIP ✓	10.00	1.00	20.00	8.00 ✓
X COVER-RR BUMPER ✓	1.00	651.00	20.00	520.80 ✓
X COVER-RR BUMPER LWR ✓	1.00	241.00	20.00	192.80 ✓
X COVER-RR BUMPER UNDER,LH → <i>supp</i>	1.00	33.00	20.00	de ✓ 26.40 X
Z TEXT OD CLAIM - AIG DOA: 16.12.2020 SURVEY: TAUFIKH (LKK) 17.12.20 05 DAYS				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	796.00	Nett	3,746.00
Labour	2,850.00	7% GST on	3746.00
Standard Menu	0.00		262.22
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	4,008.22
Sundry/Others	100.00		
Total(w/o GST)	3,746.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SML 5045 X

<u>Materials</u>		<u>Cost \$</u>
1	Cover- RR Bumper Under, LH	33.00 de ✓
	20% Discount	6.60
		<u>26.40</u>
	7% GST	1.85
	Total	<u>28.25</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: 5ML 5645X

WIP: _____ (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Cover-RR Bumper under LH	? / SUPP		Steve 29/12/20	
2		? / SUPP			
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	23/12/20	Steve
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Corato 1.6 SXSURVEYOR: Furish e Lkk

HOME Online  CERATO/FORTE../2019/G 1.6 MPI.. VCI  

 **Fault Code Searching**

Rescan Erase All DTC Go to DTC Save

 EPS  AIRCON  AIRBAG

6/6

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0235	VCI Ver.	02.48
ECU Ver.	M-E-K-01-00-0176	OS Ver.	Android 9



HOME

Online



CERATO/FORTE../2019/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



EPS



AIRCON



AIRBAG

6/6

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0235

VCI Ver.

02.48

ECU Ver.

M-E-K-01-00-0176

OS Ver.

Android 9