



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref: CS/TP20014046/Uvf3e2	
BLK 1 KAKI BUKIT AVE 6			Date: 08/01/2021	
#01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883				
ON BEHALF OF GAY CHOON LENG DANNY			Code: TP149	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		SMW 3780L
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		17/12/2020
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4 (A)	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WAUZZZF43KN006521	Colour	GREY	
Odometer	28601 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	PIRELLI	7 mm	
L/H Front Tyre	205/60 R16	PIRELLI	7 mm	
R/H Rear Tyre	205/60 R16	PIRELLI	7 mm	
L/H Rear Tyre	205/60 R16	PIRELLI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/12/2020	Inspection Date	17/12/2020	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	